

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SIM LENG HAN

BLK 782C WOODLANDS CRESCENT #04-333

SINGAPORE 733782

TP China  
Vern

## TAX INVOICE

Repair Code : CLM15384

Date in : 20/12/2021

Vehicle Num. : SJE9020M

Model : VOLKSWAGEN GOLF GT 1.4 TSI

Chassis/Eng# : WVWZZZ1KZ8U023861/BLG051689

Contact : 90188170

### Parts and Labour Assesment

| Description of part                    | Qty | Unit Price | Amount                             |
|----------------------------------------|-----|------------|------------------------------------|
| FRONT LH DOOR <i>Repair</i>            | 1   | 1999.70    | <del>1,999.70</del> <i>X</i>       |
| FRONT LH DOOR PROTECTOR <i>cut</i>     | 1   | 188.96     | <del>188.96</del> <i>✓</i>         |
| FRONT LH DOOR WEATHER STRIP <i>new</i> | 1   | 300.93     | <del>300.93</del> <i>X</i>         |
| REAR BUMPER <i>top</i>                 | 1   | 1800.97    | <del>1,800.97</del> <i>✓</i>       |
| REAR BUMPER LOWER LID <i>cut</i>       | 1   | 300.97     | <del>300.97</del> <i>✓</i>         |
| REAR BUMPER RETAINER L/R <i>LH new</i> | 2   | 99.70      | <del>199.40</del> <i>99.70</i>     |
| REAR LH CONTROL ARM <i>Bent</i>        | 1   | 487.60     | <del>487.60</del> <i>✓</i>         |
| REAR LH DOOR <i>Dented</i>             | 1   | 1988.60    | <del>1,988.60</del> <i>1655</i>    |
| REAR LH DOOR HINGE (LOWER) <i>new</i>  | 1   | 190.77     | <del>190.77</del> <i>X</i>         |
| REAR LH DOOR PROTECTOR <i>new</i>      | 1   | 189.86     | <del>189.86</del> <i>X</i>         |
| REAR LH DOOR WEATHER STRIP <i>new</i>  | 1   | 300.93     | <del>300.93</del> <i>✓</i>         |
| REAR LH FENDER <i>Repair</i>           | 1   | 1699.07    | <del>1,699.07</del> <i>X</i>       |
| REAR LH FENDER INNER SHIELD <i>new</i> | 1   | 200.97     | <del>200.97</del> <i>X</i>         |
| REAR LH KNUCKLE ARM <i>3 days</i>      | 1   | 688.70     | <del>688.70</del> <i>✓</i>         |
| REAR LH KNUCKLE ARM BEARING            | 1   | 688.99     | <del>688.99</del> <i>498</i>       |
| REAR LH LOWER ARM <i>Bent</i>          | 1   | 399.70     | <del>399.70</del> <i>✓</i>         |
| REAR LH SHOCK ABSORBER <i>Bent</i>     | 1   | 189.97     | <del>189.97</del> <i>✓</i>         |
| REAR LH SPORT RIM <i>cut</i>           | 1   | 1300.71    | <del>1,300.71</del> <i>650(SN)</i> |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

SIM LENG HAN  
 BLK 782C WOODLANDS CRESCENT #04-333  
 SINGAPORE 733782

Contact : 90188170

## TAX INVOICE

Repair Code : CLM15384

Date in : 20/12/2021

Vehicle Num. : SJE9020M

Model : VOLKSWAGEN GOLF GT 1.4 TSI

Chassis/Eng# : WVWZZZ1KZ8U023861/BLG051689

|                                         |             |   |        |           |           |
|-----------------------------------------|-------------|---|--------|-----------|-----------|
| REAR LH STABILIZER LINK                 | <i>new</i>  | 1 | 130.77 | <i>x</i>  | 130.77    |
| REAR LH TRAILING ARM                    | <i>Best</i> | 1 | 433.71 | <i>✓</i>  | 433.71    |
| REAR LH UPPER ARM                       | <i>new</i>  | 1 | 499.70 | <i>x</i>  | 499.70    |
| Subtotal before discount                |             |   |        |           | 14,180.98 |
| Percentage discount 0%                  |             |   |        |           | 0.00      |
| Sub-total 1                             |             |   |        |           | 14,180.98 |
| REAR BUMPER CLIPS - SET                 | <i>new</i>  | 1 | 50.00  | <i>30</i> | 50.00     |
| REAR LH 225/40ZR18 TYRE                 | <i>new</i>  | 1 | 550.00 | <i>x</i>  | 550.00    |
| REAR LH FENDER INNER SHIELD CLIPS - SET | <i>new</i>  | 1 | 50.00  | <i>x</i>  | 50.00     |
| Subtotal before discount                |             |   |        |           | 650.00    |
| Percentage discount 0%                  |             |   |        |           | 0.00      |
| Sub-total 2                             |             |   |        |           | 650.00    |
| Parts-total                             |             |   |        |           | 14,830.98 |

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

*50* 80.00  
*220* 280.00  
*80* 100.00  
*50* 100.00  
*80* 160.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

SIM LENG HAN  
BLK 782C WOODLANDS CRESCENT #04-333  
SINGAPORE 733782

Contact : 90188170

## TAX INVOICE

Repair Code : CLM15384

Date in : 20/12/2021

Vehicle Num. : SJE9020M

Model : VOLKSWAGEN GOLF GT 1.4 TSI

Chassis/Eng# : WVWZZZ1KZ8U023861/BLG051689

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,940.00

Parts & Labour Total

17,770.98

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lg  
H/S 22/14/21

06 Days.

total: 9158.78

H/S 7.3K ✓