

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veh# : GBK3782A

Model: NISSAN NV200

Accident Date : 20/12/2021

26/6/2020

Location : SOON LEE STREET BESIDE PIONEER JUNCTION BUILDING

3P:

YP269L (EQ)

| S/Nos         | Qty    | Description                                           | List \$    | S/Nett \$ | Nett \$  |
|---------------|--------|-------------------------------------------------------|------------|-----------|----------|
| 1             | 1 pc   | Rear bumper <i>lt</i>                                 |            |           | 695.90   |
| 2             | 1 pc   | Rear bumper n/s retainer <i>neu</i>                   |            |           | 86.60    |
| 3             | 10 pcs | Rear bumper clips <i>neu</i>                          |            | 30.00     |          |
| 4             | 1 pc   | Rear n/s tail lamp panel <i>12g</i>                   |            |           |          |
| 5             | 1 pc   | Rear n/s tail lamp <i>lt</i>                          |            |           | 364.60   |
| 6             | 1 pc   | Rear n/s tail lamp inner seal <i>neu</i>              |            |           | 20.00    |
| 7             | 1 pc   | Rear n/s windscreen moulding <i>3m</i>                | 3296.80    |           | 100.00   |
| 8             | 1 pc   | Rear n/s windscreen sealant                           | 2967.12    |           | 80.00    |
| 9             | 1 pc   | Rear n/s body panel <i>Dented</i>                     | SN: 130    |           | 2,126.80 |
| 10            | 1 pc   | Rear n/s sliding door guide <i>Dented</i>             |            |           | 318.40   |
| 11            | 1 pc   | Rear n/s sliding door guide garnish <i>gyl d</i>      |            |           | 76.50    |
|               |        | Rear n/s body panel glass <i>lt</i> \$28.5 ✓ 285      | Sub Total: | 0.00      | 3,868.80 |
|               |        |                                                       |            | 30%       | 10%      |
|               |        | After Less %:                                         | 0.00       | 30.00     | 3,481.92 |
| <b>Labour</b> |        |                                                       |            |           |          |
| 1             |        | To dismantle damaged parts, straighten & welding.     | 800.00     | 600       |          |
| 2             |        | To spray painting.                                    | 400.00     | 250       |          |
| 3             |        | To remove and replace rear n/s fender glass           | 140.00     | 60        |          |
| 4             |        | To remove and refit n/s door                          | 100.00     | x         |          |
| 5             |        | To remove and replace upholstery to facilitate repair | 150.00     | 60        |          |
| 6             |        | To remove and refit rear reverse sensor               | 40.00      | ✓         |          |
| 7             |        | To check wiring                                       | 60.00      | 30        |          |
| 8             |        | To re seal anti rust.                                 | 40.00      | ✓         |          |
|               |        | Sub Total:                                            | 1,730.00   |           |          |
|               |        | Total:                                                | 5,241.92   |           |          |
|               |        | After less 20%                                        | 4,193.54   |           |          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to confirmation from Insurance Company

Chan San Choon

Director

Acknowledged by: AAE MIMI, MSAE (Aust)

Signature:

Date:



8778 1999  
24 hr accident call

Mobil 1



PAYNOW