

14/12/2021

REF: *1*

ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : GBB4086SMake & Model : RENUALT KANGOOYear of Manufacture : 2009 /EXP 2023 NOVChassis No. : VF1FC1EAF38795251

Engine No. : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

Ins Company : GE VS china

Excess : \_\_\_\_\_

Date of Accident : 10/12/2021

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**Case Owner : BRENDA NG

Signature : \_\_\_\_\_

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

[PatrickTia@sparkcarcare.com](mailto:PatrickTia@sparkcarcare.com)

63837730 - Brenda Ng

[BrendaNg@sparkcarcare.com](mailto:BrendaNg@sparkcarcare.com)

63837466 - Rohani

[RohaniM@sparkcarcare.com](mailto:RohaniM@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

[Ngotw@sparkcarcare.com](mailto:Ngotw@sparkcarcare.com)

63838115 -

63837362 -

Parts (a) Cost / List Price Items	\$ -
Plus/Less	\$ -
Total of Cost / List	\$ -
(b) Nett Price Items	\$ -
Less	
Total of Nett Item	
(c) Special Nett Items	\$ 250.00
<b>Total Parts Cost (Appendix A)</b>	<b>\$ 250.00</b>
<b>Labour (Appendix B)</b>	<b>\$ 1,950.00</b>
<b>Total Repair Cost</b>	<b>\$ 2,200.00</b>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Henrich  
 Company : CCC  
 Survey conducted on : 16/12/21 at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 16/12/21



# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62815767

Page 1

## Car Parts

Vehicle No : GBB4086S

Case Owner : BRENDA NG

Make & Model : RENUALT KANGOO

Year Manufacture : \_\_\_\_\_

Chassis No : VF1FC1EAF38795251

Engine No : 0

Sales Order : \_\_\_\_\_

Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER <i>683.60 Bn</i>	1			<i>745</i>		<i>✓</i>
2	REAR BUMPER LH COVER	1		<i>Bn</i>	<i>340</i>		<i>X</i>
3	REVERSE SENSOR	1		<i>Bn</i>		\$ 250.00	<i>X</i>
4	LH BACK DOOR <i>Ry</i>	1			<i>1149.50</i>		<i>✓</i>
5	LH BACK DOOR GLASS <i>Shatter</i>	1			<i>340</i>		<i>✓</i>
6	LH BACK DOOR GLASS WEATHER STRIP <i>Nrc</i>	1			<i>220</i>		<i>✓</i>
7	LH BACK DOOR LOWER GARNISH <i>170 Ry</i>	1			<i>300</i>		<i>✓</i>
8	LH BACK DOOR RENAULT EMBLEM <i>90 na</i>	1			<i>170</i>		<i>✓</i>
9	REAR NO. PLATE W/CASING(SILVER/EMBOSS) <i>Bn</i>	1				<i>45</i>	<i>X</i>
10	0	1					
11	0	1					
12	0	1					
13	0	1		<i>108</i>			
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	2					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ComfortDelGro Engineering Pte Ltd**  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : **GBB4086S**  
Make & Model : **RENUALT KANGOO**

Case Owner : BRENDA NG  
Year of Manufacture : 2009 /EXP 2023 NOV

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*