

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Keny Ong Thiam Beng

Date: 30 Dec 2021

Preliminary Advice

Insured Vehicle No	: WC2513K	Accident Date	: 17/12/2021
TP Vehicle No	: GBE6011D	Assignment Date	: 21/12/2021
Make	: TOYOTA HIACE	Est. Duration of Repair	:
Date of Inspection	: 21/12/2021		
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,087.80
Revised Amount	:S\$	4,591.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,591.60
Lump Sum Repair	:S\$	3,650.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	1,849.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,151.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.