

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J Tel: 6741-1730 / 731 Email: liusbros@gmail.com

Invoice/Ref No GBE6011D211217

Estimate

Customer

Name: **MSIG Insurance (Singapore) Pte Ltd**Address: **Motor Claims Department****4 Shenton Way #21-01****SGX Centre 2****Singapore 068807**Date: **20-12-21**Vehicle No: **GBE6011D**Model/Make: **Toyota Hiace****DX 3.0 Manual**

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>D/S</i>	\$ 496.40	
2	Bumper Clips 1 set <i>new</i>	\$ 48.00	
3	Bumper Bracket <i>1 set. new old car</i>	\$ 202.00	
4	Rear Rh Tail Lamp <i>C/R</i>	\$ 366.30	
5	Body Panel (Fender) <i>Body to D/S</i>	\$ 2,110.10	
6	Inner Panel <i>Body to</i>	\$ 674.00	
7	Window Panel <i>11</i>	\$ 771.00	X
8	Sliding Door Panel <i>11</i>	\$ 810.00	X
	Remove Inner Stainless Steel Panel	\$ 400.00	- 280
	To check all wiring & electrical component for proper function	\$ 40.00	- 20
	Remove and refix rear bumper reverse sensor	\$ 120.00	- 40
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc.	\$ 1,200.00	- 150
	To putty & spray painting & including touch up paint on accident affected areas	\$ 800.00	- 700
	To apply Rust Proofing, reseat tuff-coating treatment on accident area	\$ 50.00	- 40

Total Parts & Labour of estimate for damaged vehicle

\$ 8,087.80

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Bro Auto Engrg Wks

not Awarded
new
21/12/21
1/5 @ 3,650
9 days

LKZ Auto Consultants hence notify the Repairer of the following:

- To resurvey below water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2. 3148-80
257
2361.60
2230
4591.60
222
3673