

SERVICE ESTIMATE

0 - C00001

SL: SERVICE SALES - PC

SNA5216R

-Chen Mingyou

-

-

-

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks :

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 03/12/2021

WIP No. . : 57619

Veh.In/Out:

*Tel.No. . :

Reg.No. . : SNA5216R

Reg.date . :

Mileage .. : 0

Chassis No: WDC2539092F292147

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BONNET, FRT RH FENDER, FRT RH DOOR, REAR RH DOOR, RH WING MIRROR, SIDE STEP, ETC	0	6000.00	0		6,000.00	S
800	TO SPRAYPAINT ON BONNET, FRT RH FENDER, FRT RH DOOR, REAR RH DOOR, WING MIRROR COVER, REAR RH FENDER, ETC	0	6300.00	0		6,300.00	S
802	TO REMOVE, REFIT & TRANSFER FRT RH DOOR COMPONENTS	0	500.00	0		500.00	S
0031	TO REPLACE FRT RH RIM	0	50.00	0		50.00	S
419	WHEEL ALIGNMENT	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	SIDE MIRROR RH	1.0 EA	3645.20			3,645.20	S

SERVICE ESTIMATE

0 - C00001

SL: SERVICE SALES - PC

SNA5216R

-Chen Mingyou

-

-

-

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks :

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 03/12/2021

WIP No. . : 57619

Veh.In/Out:

*Tel.No. . :

Reg.No. . : SNA5216R

Reg.date .:

Mileage .. : 0

Chassis No: WDC2539092F292147

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	DOOR PANEL FRT RH	1.0 EA	3581.40			3,581.40	S
	DOOR SEAL FRT RH	1.0 EA	425.10			425.10	S
	SIDE STEP RH	1.0 EA	573.30			573.30	S
	FENDER FRT RH	1.0 EA	1271.40			1,271.40	S
	RIM	1.0 EA	2285.40			2,285.40	S
	BONNET	1.0 EA	2798.90			2,798.90	S

Gross Total. 28,331.70

Labour Total 13,751.00
 Parts Total 14,580.70
 Package Total 0.00

Net..... 28,331.70
 GST @ 7.0% 1,983.22
 Total..... 30,314.90
 Paid..... 0.00
 Please Pay.. 30,314.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated