



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
WEARNES AUTOMOTIVE PTE LTD **			Ref: CS/TP21012933/Rqf3e2	
249 ALEXANDRA ROAD SINGAPORE 159935			Date: 22/07/2022	
ON BEHALF OF CHEN MINGYOU			Code: TP275	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SNA 5216R
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		22/12/2021
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC250D 4M	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDC2539092F292147	Colour	BLACK	
Odometer	91593 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	285/55 R19	PIRELLI	6 mm	
L/H Front Tyre	285/55 R19	PIRELLI	6 mm	
R/H Rear Tyre	285/55 R19	PIRELLI	6 mm	
L/H Rear Tyre	285/55 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2021	Inspection Date	22/12/2021	
Survey held at	2 JALAN PESAWAT			
Repairer	WEARNES AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	