

TEC AUTO SERVICES PTE LTD

48 TOH GUAN ROAD EAST #05-107 ENTERPRISE HUB SINGAPORE 608586

Estimate

PAGE : 1/3

YEAR : 2013 VEHICLE NO : SKP6613C
MODEL : : B.M.W. 520I AT D/AB 2WD 4DR LED NAV CHASSIS NO : WBA5A32060D789326

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	REAR BOOTLID <i>4/</i>	1	\$1,750.00
2	REAR BOOTLID CENTRE LOGO <i>new</i>	1	\$39.00
3	BOOTLID HINGE <i>X</i>	2	\$115.00
4	BOOTLID HINGE GARNISH <i>X</i>	2	\$130.00
5	BOOTLID WEATHERSTRIP <i>X</i>	1	\$215.00
6	BOOTLID LOCK ASSY <i>X</i>	1	\$310.00
7	BOOTLID LOCK CATCH <i>X</i>	1	\$145.00
8	BOOTLID CONTROL UNIT <i>X</i>	1	\$1,050.00
9	BOOTLID DAMPER LH <i>X</i>	1	\$570.00
10	BOOTLID DAMPER RH <i>X</i>	1	\$570.00
11	BOOTLID LAMP LH <i>?</i>	1	\$365.00
12	BOOTLID LAMP RH <i>see</i>	1	\$365.00
13	END PANEL <i>repair photo</i>	1	\$610.00
14	END PANEL TOP GARNISH <i>?</i>	1	\$149.00
15	END PANEL LOCK SENSOR <i>X</i>	1	\$75.00
16	FLOOR PANEL COMPARTMET <i>X</i>	1	\$850.00
17	REAR LUGGAGE COMPARTMENT TRIM <i>X</i>	1	\$110.00
18	REAR FENDER INNER TRIM LH <i>X</i>	1	\$250.00
19	REAR FENDER INNER TRIM RH <i>X</i>	1	\$250.00
20	REAR BUMPER RETAINER <i>X</i>	2	\$95.00
21	REAR BUMPER BRACKET CENTRE <i>?</i>	1	\$150.00
22	REAR BUMPER CENTRE UPPER HOLDER <i>?</i>	1	\$30.00
23	REAR BUMPER CENTRE LOWER HOLDER <i>?</i>	1	\$30.00
24	REAR BUMPER REINFORCEMENT <i>?</i>	1	\$640.00
25	REAR BUMPER REINFORCEMENT BEAM <i>2</i>	1	\$145.00
26	REAR BUMPER REFLECTOR LH <i>X</i>	1	\$45.00
27	REAR BUMPER REFLECTOR RH <i>X</i>	1	\$45.00
28	REAR PARKING SENSOR <i>? 2 pcs</i>	2	\$1,480.00
29	REAR SENSOR HOLDER <i>new</i>	4	\$80.00
30	REAR EXHAUST ASSY <i>? photo</i>	1	\$2,310.00

TEC AUTO SERVICES PTE LTD

48 TOH GUAN ROAD EAST #05-107 ENTERPRISE HUB SINGAPORE 608586

Estimate

PAGE : 2/3

YEAR : 2014 VEHICLE NO : SMR5201E
MODEL : VOLKSWAGEN GOLF A7 1.4 TSI AT 5 CHASSIS NO : WVWZZZAUZEW407831

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
31	REAR EXHAUST MOUNTING ?	2	\$30.00
32	REAR EXHAUST HEAT SHIELD X	1	\$114.00
			\$13,112.00
		Discount 10%	\$1,311.20
		TOTAL :	\$11,800.80
S/NO	SPECIAL ITEMS	Qty	Price
1	REAR NUMBER PLATE X	1	\$90.00
2	REAR BUMPER (AFTER MARKET) de N-5	1	\$1,700.00
3	REAR TAILLAMP (AFTER MARKET) X	1 SET	\$1,800.00
4	BOOTLID INNER TRIM CLIP re X	1 SET	\$30.00
5	FENDER INNER TRIM CLIP X	1 SET	\$30.00
6	BOOTLID SPOILER re	1	\$500.00
7	JOINT SEALNT X	1	\$120.00
8	M5 DIFFUSER (m)	1	500
			\$4,270.00 4770
		Parts Total :	\$11,800.80
		S/P Item :	\$4,270.00 4770
		TOTAL :	\$16,070.80 16570.80

TEC AUTO SERVICES PTE LTD
48 TOH GUAN ROAD EAST #05-107 ENTERPRISE HUB SINGAPORE 608586

Estimate

PAGE : 3/3

YEAR : 2013 VEHICLE NO : SKP6613C
MODEL : : B.M.W. 520I AT D/AB 2WD 4DR LED NAV CHASSIS NO : WBA5A32060D789326

S/NO	LABOURS	AMOUNT
1	CHECK ALL WIRING AND LIGHTNING SYSTEM	\$ 30 120.00
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	\$ 200 500.00
3	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	\$ 60 200.00
4	REMOVE AND RENEW REAR SENSOR	\$ 60 120.00
5	REMOVE AND RENEW REAR EXHAUST ASSY <i>photo</i>	\$ 100 150.00
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	\$ 60 250.00
7	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	\$ 600 1,400.00
8	REMOVE AND RENEW WRAPPING ON AFFECTED AREAS	\$ 200 1,200.00
9	APPLY ANTI RUST ON AFFECTED AREAS	\$ 50 200.00

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL : \$ 4,140.00
PARTS TOTAL : \$ ~~4,070.80~~ 16,570.80
GRAND TOTAL : \$ ~~8,210.80~~ 20,710.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid
Hp 90010068
5 days
L/S
22/12/21 @ 1520
Ready after repair