



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21012942/Rqf3e2	
			Date: 14/02/2022	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJG 5845R	Veh. Inspected	SLX 3827T	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D17282201	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	21/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA LEXUS ES250 EX S/R	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTHBJ1GG002106496	Colour	WHITE	
Odometer	79717 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/12/2021	Inspection Date	23/12/2021	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	