

ASS. REC. BY: TaudikhREF: CS/11/21012943/71v53

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / CP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SDH 5188UPolicy No. D18MPC0000960_03Claims No. MPC2021D0005511

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 457K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV 6879X Yr Regn: 2015, SepType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mini One 5RR C.C. 1498Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 03702 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMWXS/20502680367Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/55R16R: 195/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/12/2021 D.O.I. 22/12/21Survey held at TSLDes. of Damages: FR / CR / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/7/22	Taudikh informed LS \$17,000 (Red 36,607, 68%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 15/7/22-typist

Rep. Format: MerimenLump Sum / LS: \$17,000Days Of Repair: 12Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

No	Qty	Parts Description		Estimated Parts Price
1	1	Front bumper assy	820	\$ 1,274.30 <i>de</i>
2	2	Front bumper bracket		\$ 175.60 <i>x nn</i>
3	2	Front bumper side retainer		\$ 252.80 <i>x nn</i>
4	1	Front bumper reinforcement	470	\$ 596.70 <i>bt</i>
5	1	Front bumper sponge		\$ 176.60 <i>de</i>
6	1	Front bumper tow cover		\$ 68.80 <i>x nn</i>
7	1	Front bumper lower grille	160	\$ 181.90 <i>de</i>
8	1	Front bumper lower grille outer moulding		\$ 202.80 <i>x nn</i>
9	1	Front grille assy	125	\$ 342.20 <i>car</i>
10	1	Front grille outer moulding complete assy	148	\$ 212.30 <i>car</i>
11	1	Front left fog lamp		\$ 258.90 <i>car</i>
12	1	Front right fog lamp		\$ 258.90 <i>x nn</i>
13	1	Front bonnet assy	1250	\$ 1,587.20 <i>bt</i>
14	2	Front bonnet hinges		\$ 152.20 <i>x</i>
15	2	Front bonnet side damper		\$ 305.80 <i>x</i>
16	1	Front bonnet left lock		\$ 67.80 <i>x</i>
17	1	Front bonnet right lock		\$ 67.80 <i>x</i>
18	1	Front bonnet left lock catch		\$ 45.20 <i>x</i>
19	1	Front bonnet right lock catch		\$ 45.20 <i>x</i>
20	1	Front bonnet centre emblem	70	\$ 158.80 <i>car</i>
21	1	Front left headlamp assy	1450	\$ 1,868.90 <i>car</i>
22	1	Front right headlamp assy	1450	\$ 1,868.90 <i>x nn</i>
23	1	Front left headlamp outer chrome moulding		\$ 276.80 <i>x nn</i>
24	1	Front right headlamp outer chrome moulding	220	\$ 276.80 <i>ms</i>
25	1	Front support panel		\$ 820.10 <i>x</i>
26	1	Front support panel top garnish		\$ 233.80 <i>x</i>
27	2	Front support panel rubber stopper		\$ 88.80 <i>x</i>
28	1	Front inner rubber		\$ 188.10 <i>x</i>
29	1	Front wiper tank		\$ 109.60 <i>x</i>
30	1	Front air duct		\$ 281.30 <i>x</i>
31	1	Front radiator assy		\$ 1,490.80 <i>x</i>
32	1	Front radiator fan with motor assy		\$ 772.80 <i>x</i>
33	1	Front radiator fan cowling		\$ 253.80 <i>x</i>
34	1	Front air con condenser assy	895	\$ 1,289.20 <i>bt</i>
35	1	Front air con discharge pipe		\$ 380.80 <i>x nn</i>
36	1	Front air con suction pipe		\$ 380.50 <i>x nn</i>
37	1	Front turbo intercooler	650	\$ 849.50 <i>bt</i>
38	1 set	Front turbo intercooler hose		\$ 221.50 <i>x nn</i>
39	1	Front left aluminium side chassis member	498	\$ 698.30 <i>bt</i>
40	1	Front right aluminium side chassis member	498	\$ 698.30 <i>bt</i>
less 10%			9139.50	\$ 19,480.40
			10% 8225.55	\$ 1,948.04
				\$ 17,532.36

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Front bumper clips	\$	60.00 30 u ✓
2	1 set	Front grille clips	\$	40.00 20 u ✓
3	1 set	Front bumper lower grille clips	\$	40.00 20 u ✓
4	1	Front no plate with garnish	\$	100.00 45 u ✓
5	6	Front support panel top garnish clips	\$	30.00 X u ✓
6	1	Front bumper lower spoiler assy	\$	880.00 400
7	1	Front bumper lower spoiler sealant	\$	100.00 40
8	8	Front bumper lower spoiler clips	\$	40.00 20
9	1 set	Front bonnet sticker <i>black</i>	\$	250.00 u / 150.
10	2	Front radiator coolant	\$	100.00 X u
11	1	Front air con gas	\$	100.00 u X u
			\$	1,740.00
Total parts			\$	19,272.36 825

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

No	Qty	Parts Description		Estimated Parts Price
1	1	Rear bumper assy	850	\$ 1,251.80 <i>del</i> ✓
2	2	Rear bumper retainer		\$ 184.20 <i>x un</i>
3	2	Rear bumper bracket		\$ 126.80 <i>x un</i>
4	2	Rear bumper tow cover	70	\$ 108.60 <i>ant</i> ✓
5	1	Rear left bumper inner side trim		\$ 91.60 <i>me</i> ✓
6	1	Rear right bumper inner side trim		\$ 91.60 <i>me</i> ✓
7	1	Rear bumper reinforcement		\$ 520.80 <i>bt</i> ✓
8	1	Rear bumper center sponge		\$ 178.50 <i>x un</i>
9	1	Rear bumper centre lamp	182	\$ 282.80 <i>ant</i> ✓
10	1	Rear bumper centre lamp chrome garnish	151	\$ 251.60 <i>ant</i> ✓
11	1	Rear tailgate assy	960	\$ 1,617.40 <i>bt</i> ✓
12	1	Rear tailgate centre logo	65	\$ 158.80 <i>nee</i>
13	1	Rear tailgate 'one' emblem	70	\$ 151.10 <i>del</i> ✓
14	1	Rear tailgate outer garnish		\$ 277.80 <i>x</i>
15	2	Rear tailgate number plate lamps		\$ 128.80 <i>x</i>
16	1	Rear tailgate inner trim board		\$ 379.30 <i>x</i>
17	1	Rear tailgate lock		\$ 182.50 <i>x</i>
18	1	Rear tailgate lock catch		\$ 68.20 <i>x</i>
19	2	Rear tailgate hinges		\$ 185.80 <i>x</i>
20	1	Rear tailgate weatherstrip	180	\$ 205.40 <i>ant</i> ✓
21	1 set	Rear tailgate rubber stopper		\$ 68.80 <i>x un</i>
22	2	Rear tailgate dampers		\$ 585.80 <i>x un</i>
23	1	Rear left taillamp	340	\$ 999.70 <i>me</i> ✓
24	1	Rear right taillamp	340	\$ 999.70 <i>me</i> ✓
25	1	Rear left taillamp outer chrome garnish	105	\$ 167.10 <i>me</i> ✓
26	1	Rear right taillamp outer chrome garnish	105	\$ 167.10 <i>me</i> ✓
27	1	Rear left fender		\$ 1,022.50 <i>x</i>
28	1	Rear right fender		\$ 1,022.50 <i>x</i>
29	1	Rear left fender protector		\$ 187.50 <i>x</i>
30	1	Rear right fender protector		\$ 187.50 <i>x</i>
31	1	Rear left fender inner shield	169	\$ 269.90 <i>me</i> ✓
32	1	Rear right fender inner shield		\$ 269.90 <i>x</i>
33	1	Rear left fender inner garnish		\$ 296.30 <i>x</i>
34	1	Rear right fender inner garnish		\$ 296.30 <i>x</i>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

No	Qty	Parts Description	Estimated Parts Price
35	1	Rear wiper blade	\$ 88.80 x ✓
36	1	Rear wiper motor	\$ 293.40 x ✓
37	2	Rear air duct ventilator	\$ 180.10 x ✓
38	1	Rear end lower panel	500 \$ 1,256.30 bl ✓
39	1	Rear end lower panel top garnish	\$ 288.90 de ✓
40	1	Rear exhaust muffler assy	890 \$ 1,400.50 bt ✓
41	2	Rear exhaust muffler rubber mountings	\$ 68.80 m ✓
42	1	Rear exhaust muffler heat shield	\$ 209.90 x ✓
43	1	Rear windscreen glass moulding	168 \$ 288.80 ne ✓
44	1	Rear left quarter glass moulding	\$ 188.80 x ✓
45	1	Rear right quarter glass moulding	\$ 188.80 x ✓
46	1	Rear tool tray	\$ 131.50 tra ✓
47	1	Rear spare tyre top board	\$ 299.80 x ✓
			6338.20 \$ 17,868.40
		less 10%	5704.38 \$ 1,786.84
			<u>\$ 16,081.56</u>

Special Nett Items

1	10	Rear bumper clips	\$ 60.00 300 ✓
2	8	Rear tailgate inner trim board clips	\$ 40.00 200 ✓
3	4	Rear tailgate outer garnish clips	\$ 30.00 x ✓
4	1	Rear left fender sealant	\$ 100.00 x ✓
5	1	Rear right fender sealant	\$ 100.00 x ✓
6	6	Rear left fender protector clips	\$ 35.00 10 ✓
7	6	Rear right fender protector clips	\$ 35.00 10 ✓
8	6	Rear left fender inner shield clips	\$ 40.00 10 ✓
9	6	Rear right fender inner shield clips	\$ 40.00 10 ✓
10	8	Rear left fender inner garnish clips	\$ 50.00 x ✓
11	8	Rear right fender inner garnish clips	\$ 50.00 x ✓
12	1	Rear end lower panel sealant	\$ 140.00 40 ✓
13	6	Rear end lower panel top garnish clips	\$ 40.00 x ✓
14	1	Rear no plate with garnish	\$ 100.00 45 ✓
15	1	Rear windscreen glass sealant	\$ 100.00 60 ✓
16	1	Rear left quarter glass sealant	\$ 80.00 x ✓
17	1	Rear right quarter glass sealant	\$ 80.00 x ✓
18	1	Rear bumper lower spoiler	\$ 980.00 400 ✓
19	1	Rear bumper lower spoiler sealant	\$ 100.00 x ✓
20	10	Rear bumper lower spoiler clips	\$ 50.00 20 ✓
			<u>\$ 2,250.00</u> 655

Total parts

\$ 18,331.56

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,200.00 600
2	To putty and spray painting front portion.	\$ 1,200.00 600
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 X
5	To remove and install air con system to facilitate the repair and refill gas.	\$ 180.00 100? ✓
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 180.00 100 X nn
7	To apply anti rust proofing to front affected area.	\$ 140.00 30
8	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00 700
9	To putty and spray painting rear portion.	\$ 1,400.00 700 -
10	To check rear lighting and wiring.	\$ 50.00 30
11	To remove and install rear tailgate lock mechanism.	\$ 80.00 60
12	To remove and install rear exhaust muffler assy.	\$ 120.00 80
13	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 X nn
14	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 60
15	To apply anti rust proofing to rear affected area.	\$ 140.00 30
16	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120
17	To apply blue sticker to entire front portion.	\$ 2,500.00 500 ne ✓
18	To apply blue sticker to entire rear portion.	\$ 2,000.00 500 ne ✓
19	To conduct chassis alignment.	\$ 350.00 200 X nn
20	Towing service.	\$ 100.00 X nn.
Total labour :		\$ 11,630.00 4140

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total parts : \$ 37,603.92

Total labour : \$ 11,630.00

Total repair cost : \$ 49,233.92

Tanpin 97495744
 WP' 22/12/21

L/S Resurvey after repair
 Tanpin C. Lim
 12 days

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	--------------------------

Supplementary Items

1	1	Front left seat assy	\$ 1,660.10 X R SN 350
2	1	Front right seat assy	\$ 1,660.10 X R SN 350
3	1	Front left seat railing assy	\$ 380.50 ht ✓
4	1	Front right seat railing assy	\$ 380.50 ht ✓
			\$ 4,081.20
			\$ 408.12
			\$ 3,673.08

Total parts

\$ 3,673.08

761
10% 684.90
SN 700

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKV6879X Mini One

No	Description	Labour Charges
1	To remove and install front left seat assy.	\$ 350.00 120
2	To remove and install front right seat assy.	\$ 350.00 120
Total labour :		\$ 700.00

240

Total parts : \$ 3,673.08
Total labour : \$ 700.00
Total repair cost : \$ 4,373.08

8225.55
825
5704.38
655
4140
684.90
700
240

21,174.83
15\$16,900
12days *