



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012951/Ktf3n2 Date: 07/01/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 6462R	Veh. Inspected	PC 4421L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103782/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	21/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	HIGER KLQ6109Q	c.c	6691
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	LKLR1FSJ0FA692881	Colour	WHITE / GREY
	Odometer	219607 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	11 R22.5	GOLDEN CROWN	6 mm
	L/H Front Tyre	11 R22.5	GOLDEN CROWN	6 mm
	R/H Rear Tyre	11 R22.5 (D)	ANNAITE	10/10 mm
	L/H Rear Tyre	11 R22.5 (D)	ANNAITE	10/10 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/12/2021	Inspection Date	23/12/2021
	Survey held at	CONNECT3 7 OLD TOH TUCK ROAD SINGAPORE 597648		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	