

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref: CS/SMO21012951/Ktf3	
50 RAFFLES PLACE #03-03			Date: 21/12/2021	
SINGAPORE LAND TOWERS SINGAPORE 048623			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 6462R		Veh. Inspected	PC 4421L
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2103782/AGC		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	21/12/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/12/2021		Inspection Date	23/12/2021
Survey held at	CONNECT3 7 OLD TOH TUCK ROAD SINGAPORE 597648			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				