

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 23 Dec 2021

**Preliminary Advice**

Vehicle No	: SNB829A	Accident Date	: 18/12/2021
Make	: BMW 330CI	Policy No.	:
			DMPCSNA00207822103
Assignment Date	: 21/12/2021	Excess	: S\$1,250.00
Date of Inspection	: 22/12/2021	Est. Duration of Repair	: 20
Inspection At	: PERFORMANCE MOTORS LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,892.20
Revised Amount	:S\$	36,073.15
Check Items (Estimated)	:S\$	14,533.00
Total	:S\$	50,606.15
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	117,000.00
COE / PARF Rebate	:S\$	61,391.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,609.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .