

ASS. REC. BY: Steve

REF:

CS/CTI21012956/R113

CS/CTI21012956/Ety3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD 7623 G Yr Regn: 30/10/15Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf c.c. 1395Colour: White A/C: Insured / Std / NI / NASp. Reading: 92281 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 22ZAU 2FW 099145Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / SI / Rim / STD A/Rim orTyre Size: F: 225/40ZR19R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 5 mmL/Bal. 5 mmD.O.A. 19/12/21Survey held at Nineteen Autowerks

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-49K

LUMP SUM 6300.5DAYS

RED: 10392.69;62%

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Stere (LKK) WML PL
L/S
8322 8813 My AL 9, 5 dys

NINETEEN AUTOWERKS PTE LTD
436 TAMPINESS STREET 43 #07-97
SINGAPORE 520436
HP: 96741991(Vessle Foo)

Estimate for SMD7623G(VW GOLF)

*COVER FOR BUMPER PRIMED	\$1,158.63
*1SET SENSOR BRACKETS (LH) ?	\$221.89
*RETAINER FOR SPOILER X	\$188.11
*GUIDE PIECE - BUMPER SIDE BRACKET LH ?	\$120.91
*GUIDE PIECE - BUMPER SIDE BRACKET RH X	\$120.91
*LOWER CONTROL ARM LH X	\$351.87
*WHEEL BEARING WITH MOUNTI - SOPEX 2019-VGS & NORA ?	\$562.42
*RADLAGERGEHAUSE - WHEEL BEARING HOUSING X	\$592.14
*DRIVE SHAFT FRT LH X	\$2,512.37
*GAS-FILLED SHOCK ABSORBER LH ?	\$531.29
*BALL BEARING - TOP BEARING LH ?	\$345.71
*SUSPENSION STRUT MOUNTING - TOP MTG ?	\$293.61
*TIE ROD LH X	\$302.45
*TIE ROD END LH X	\$340.95
*FRT LH FENDER / 00	\$869.10
*WHEELHOUSE LINER - FENDER LINER LOWER LH ?	\$284.97
*LH HEADLAMP ?	\$3,818.52
*ALLOY WHEEL GALVANO GREY / CUT	1,337.14
	<u>\$13,952.99</u>
Less 10%	\$1,395.30
	<u>\$12,557.69</u>

S/nett

Front Bumper Clip / 112	\$50.00
Front LH Splash Shield Clip ?	\$50.00
Headlamp Clip LH X	\$40.00
	<u>\$140.00</u>

DIAGNOSTIC AND PROGRAMMING
R&R RIM & BALANCE
R&R RHS FRT U/CARRIAGE
WHEEL ALIGNMENT
LABOUR
SPRAY PAINT

\$350.00	100
\$80.00	30
\$300.00	?
\$200.00	60
\$1,200.00	400
\$800.00	600
<u>\$2,930.00</u>	

Total

\$15,627.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: