



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6119K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	459.40	459.40
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	55.80	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
2	REAR BUMPER REINFORCEMENT STAY LH/RH @\$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER CENTRE MOULDING	DENTED	451.25	451.25
1	REAR BUMPER TOW COVER	SERVICEABLE	94.60	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	41.45	-
1	REAR NUMBER PLATE LAMP	SERVICEABLE	85.30	-
1	ANTENNA SMART KEY SENSOR	SERVICEABLE	40.50	-
1	REAR FOG LAMP	SERVICEABLE	201.50	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM IONIQ	NECESSARY	31.30	31.30
	LESS 20% DISCOUNT		-435.68	-197.65
			1,742.72	790.60
<u>NETT ITEMS</u>				
1	REAR REVERSE SENSOR (N)	SERVICEABLE	180.00	-
1	REAR NUMBER PLATE W/HOLDER (N)	MISSING	55.00	55.00
1	REAR BOOTLID CTPL STICKER (N)	NECESSARY	30.00	30.00
1	REAR BOOTLID TEL/NO STICKER (N)	NECESSARY	30.00	30.00
1	REAR BOOTLID CTPL APP STICKER (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-33.50	-15.50
			301.50	139.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.		600.00	350.00



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK LIGHTING AND WIRING.		60.00	20.00
	TUFF KOTE.		90.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			1,410.00	920.00
GRAND TOTAL			3,504.22	1,900.10
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,900.10

Report Ref No. NS/INC21012958/Vvcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.