

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1037/2021/JT
DATE : 21-Dec-21
WIP : 59785

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 22/12/21
YOUR INSURED VEH NO : SME 7722 Z

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LOH WENG LOONG VERNON
ADDRESS : 66 TAMAN PERMATA
SINGAPORE 575189
TELEPHONE : HP +65 98639609
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210060717
VEHICLE NO : **SMR 8268 T**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 15/6/2021
ENGINE NO : DFY 265322
CHASSIS NO : WAUZZZGY7MA092170
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Dec-21
PLACE OF ACCIDENT : CTE (AFTER MOULMEIN EXIT BESIDE KIM
KEAT TOWARDS ANG MO KIO)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8268 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00	X
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500
3	TO RESPRAY REAR BUMPER	\$ 900.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
5	TO RE-APPLY PAINT COATING TO DAMAGE AREA	S/N TBC	✓
TOTAL LABOUR CHARGES		: \$ 2,502.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8268 T

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>dehd</i>	1	\$ 1,798.00	✓	
2	REAR BUMPER LOCKING MECHANISM - LH / RH <i>neu</i>	2	\$ 28.00	✗	
3	REAR BUMPER TRIM - LH / RH <i>neu</i>	2	\$ 128.00	✗	
4	REAR BUMPER SUPPORT - LH / RH <i>neu</i>	2	\$ 50.00	✗	
5	REAR BUMPER SPOILER <i>dehd</i>	1	\$ 203.00	✓	
6	RETAINER FOR CONTROL UNIT <i>neu</i>	1	\$ 25.00	✗	
7	BOOT LID CONTROL UNIT <i>neu</i>	1	\$ 411.00	✗	
8	TAILGATE SENSOR LINE <i>?</i>	1	\$ 206.00	?	
9	REAR LIGHT REFLECTOR - LH / RH <i>neu</i>	2	\$ 66.00	✗	
10	REAR PARKING AID SENSOR <i>neu</i>	2	TBC	✗	
11	REAR PARKING AID SENSOR RING <i>neu</i>	4	\$ 28.00	✗	
12	REAR BUMPER CARRIER <i>?</i>	1	\$ 561.00	?	
13	REAR BUMPER BRACKET - LH / RH <i>neu</i>	2	\$ 56.00	✗	
14	SUNDRIES <i>?</i>		\$ 200.00	?	
TOTAL SPARE PARTS		:	\$ 3,760.00		
TOTAL LABOUR CHARGES		:	\$ 2,502.00		
GRAND TOTAL		:	\$ 6,262.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Adrian Ling*
: *22/12/21.*
:
:
:
:
: *Not Authorised, 03 Days.*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT