

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Asher.

Quotation

DATE : 28.12.2021
 VEH NO : SJU3772G
 MODEL : Toyota Altis
 D O A : 19.12.2021
 YR REF : SKJ9210T

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJU3772G (TOYOTA ALTIS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Deformed</i>	1	482.30 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.80 ✓
3	Rear Bumper Sponge <i>new</i>	1	126.20 ✓
4	Rear Bumper Reinforcement Rod <i>new</i>	1	123.60 x
5	Rear Bumper Impact Bracket - LH & RH <i>Dented</i>	2	123.60 ✓
6	Rear Bumper Reflector - LH & RH <i>new</i>	2	71.40 x
7	Rear End Panel <i>Dented</i>	1	588.10 ✓
8	Rear End Panel Top Garnish <i>Deformed</i>	1	241.20 ✓
9	Tail Lamp - LH & RH <i>ut</i>	2	724.00 ✓
10	Bootlid <i>Buckled</i>	1	794.10 ✓
11	Bootlid Lock <i>Damaged</i>	1	189.80 ✓
12	Bootlid Weatherstripe <i>ut</i>	1	195.40 ✓
13	Bootlid Reflector - LH & RH <i>new</i>	2	451.60 x
14	Toyota Logo	1	45.10 ✓
15	1.6 Emblem	1	42.40 ✓
16	Corolla Emblem	1	50.40 ✓
17	Altis Emblem	1	49.20 ✓
18	LX emblem	1	39.40 ✓
19	Spare Tyre Panel Top Board <i>new</i>	1	285.40 x.

Less 25%

4,694.00
 (1,173.50)
 \$ 3,520.50

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1	\$ 30.00 ✓
2	Reverse Sensor <i>Damaged</i>	1	\$ 280.00 <i>280</i>
3	Rear End Panel Top Garnish Clips <i>new</i>	1	\$ 20.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SJU3772G (TOYOTA ALTIS)

4	Rear End Panel Sealant <i>Mr</i>	1	\$	60.00 ✓
			\$	390.00
			\$	3,910.50

310
Total Parts

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 <i>80</i>
2	To putty & spray up paint works	\$	1,000.00 <i>80</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To spray tuff coat	\$	150.00 <i>60</i>
5	To remove reverse sensor	\$	100.00 <i>50</i>
6	To remove upholstery	\$	150.00 <i>80</i>
7	To transfer boot fittings	\$	150.00 <i>60</i>

1880
Total Labour \$ 2,800.00

Grand Total \$ 6,710.50

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5011.50
4/s : 4K.
06 days