

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO/GST Reg. No. 201019626G
SHD374E

Not Authored
L/Rg 8225d AAD2112-095

Vehicle No.:
 Chassis No.:
 Vehicle Make: **20 DEC 2021**
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD374E
VF1ABL15AUC282655
RENAULT
LATITUDE
18/12/2021
AIG
10/06/2016

PART		LIST	
1	BUMPER COVER FRT	\$ <i>Brz/mg cm</i>	747.20 ✓
1	BUMPER RETAINER FRT LH	\$ <i>Dr</i>	101.40 ✓
1	HEADLAMP LH	\$ <i>mg cm</i>	743.60 ✓
1	HEADLAMP PANEL FRT LH	\$ <i>h</i>	128.30 X
1	BUMPER FOG LAMP GRILLE LH	\$ <i>h</i>	207.21 X
1	FENDER PANEL FRT LH	\$ <i>Br</i>	437.10 ✓
1	WHEELARCH FRT LH	\$ <i>h</i>	191.40 X
1	AIR CLEANER LOWER	\$ <i>h</i>	271.26 X
1	AIR CLEANER HOSE	\$ <i>h</i>	175.85 X
1	AIR CLEANER BOX	\$ <i>h</i>	464.20 X
		\$	3,467.52
		10% \$	346.75
		\$	<u>3,120.77</u>

Special Nett			
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$ <i>nn</i>	10.00 X
1SET	BUMPER RETAINER CLIP LH RR	\$ <i>nn</i>	20.00 X
1	BUMPER CLIP FRT	\$ <i>nn</i>	85.00 <i>6611</i> ✓
1	FENDER LINER CLIP	\$ <i>nn</i>	65.00 X
		TOTAL \$	180.00
		TOTAL PARTS \$	<u>3,300.77</u>

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *4401*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD374E

AAD2112-095

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 3,000.00 ^{400/}

To Rust-Proofing Of The Affected Areas.

\$ 170.00 ^{30/}

To reinstall rear bumper parking sensor.

\$ 170.00 ^{100/} X

To transfer of bootlid fittings, attachments and
perform water seepage test.

\$ 170.00 X

To repair and realign rear exhaust pipe.

\$ 170.00 X

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$ 170.00 X

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ 170.00 X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel
alignment

\$ 220.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 ^{20/}**TOTAL \$ 7,580.00****Over All Total \$ 14,001.54****LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

**(LUMP SUM)
Repair Days****20 DAYS****2 days**

Acknowledged by Repairer

Signature:

Date: