

12/6/14

RESPRAY AUTOMOTIVE PTE LTD

8, KAKI BUKIT AVE 4 , #04-06 PREMIER @KB
S(415875)

TEL:82632225 EMAIL: tfyong1966@gmail.com
CO REG NO: 202106720W

SLW7037K

Vehicle Model : LEXUS GS300
Accident Date : 20.12.2021
Original Reg Date : 09.01.2009

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *Chion*

Date: *12/6/14*

Chassis : JTHBG96S105063480

TP Ins. CTP

ESTIMATE

1	1 pc	Boot Lid <i>Regis</i>		1,458.70	x.
2	1 pc	Boot Lid Outer Garnish <i>Regis</i>		1,125.90	856.
3	1 set	Boot Lid Outer Garnish Clips <i>Regis</i>		40.00	30.
4	2 pcs	Boot Lid Number Plate Lamps <i>Regis</i>	129.70	259.40	x
5	1 pc	Boot Lid Opener Switch <i>Regis</i>		158.10	x
6	1 pc	Boot Lid Key Lock <i>Regis</i>		341.80	x
7	2 pcs	Boot Lid Lamps <i>Regis</i>	423.70	847.40	303.
8	2 pcs	Boot Lid Lamps Inner Sealer <i>Regis</i>	40.00	80.00	x
9	2 set	Boot Lid Lamps Clips <i>Regis</i>	25.00	50.00	x
10	2 pcs	Boot Lid Stopper <i>Regis</i>	18.00	36.00	x
11	1 pc	Boot Lid Insulator <i>Regis</i>		578.80	x
12	1 set	Boot Lid Insulator Clips <i>Regis</i>		40.00	x
13	1 pc	Boot Lid Pocket Handle <i>Regis</i>		173.00	x
14	1 pc	Boot Lid Inner Lock <i>Regis</i>		458.90	x
15	1 pc	Boot Lid Lock Cover <i>Regis</i>		96.40	x
16	1 pc	Boot Lid Auto Lock Actuator <i>Regis</i>		481.70	x
17	1 pc	Boot Lid Lock Catch <i>Regis</i>		66.20	x
18	1 pc	Boot Lid Weatherstrip <i>Regis</i>		258.90	x
19	2 pcs	Boot Lid Hinges <i>Regis</i>	119.30	238.60	x
20	2 pcs	Boot Lid Absorber <i>Regis</i>	286.10	572.20	x
21	1 pc	Rear Bumper <i>Regis</i>		1,186.90	975.
22	2 pcs	Rear Bumper Side Retainers <i>Regis</i>	108.80	217.60	148.80
23	2 pcs	Rear Bumper Attachment Retainers <i>Regis</i>	75.60	151.20	x
24	1 set	Rear Bumper Clips <i>Regis</i>		50.00	30.
25	2 pcs	Rear Bumper Side Screw Cover <i>Regis</i>	27.70	55.40	x
26	1 pc	Rear Bumper Reinforcement <i>Regis</i>		525.	x
27	2 pcs	Rear Bumper Reinforcement Bracket <i>Regis</i>	161.30	322.60	x
28	1 pc	Rear Bumper Sponge <i>Regis</i>		198.70	x
29	2 pcs	Rear Bumper Towing Cover <i>Regis</i>	36.00	72.00	36.
30	1 pc	Rear Bumper Bottom Cover <i>Regis</i>		156.20	x
31	1 set	Rear Bumper Bottom Cover Clips <i>Regis</i>		30.00	x
32	1 pc	End Panel <i>Regis</i>		789.60	x
33	1 pc	End Panel Top Trim <i>Regis</i>		345.20	x
34	1 set	End Panel Top Trim Clips <i>Regis</i>		30.00	x

35	1 pc	Spare Tyre Panel		938.40	+
36	1 pc	Spare Tyre Panel Top Board		359.50	+
37	2 pcs	Spare Tyre Panel Top Side Board	148.00	296.00	+
38	1 pc	Spare Tyre Panel Top Tray		459.60	+
39	1 pc	Spare Tyre Panel Top Inner Insulator		541.80	+
40	1 pc	Spare Tyre Wheel Nut		65.20	+
41	1 pc	Rear Key Antenna Sensor		216.00	+
42	1 pc	Rear Chassis Frame Member LH		756.20	+
43	2 pcs	Taillamps LH & RH	945.60	1,891.20	+
44	2 pcs	Taillamps Inner Sealer	36.00	72.00	+
45	2 set	Taillamps Clips	25.00	50.00	+
46	2 pcs	Taillamps Side Cover Garnish	75.00	150.00	+
47	1 pc	Taillamps Panel LH		227.80	+
52	2 pcs	Rear Fender Inner Trim	536.00	1,072.00	+
53	2 set	Rear Fender Inner Trim Clips	30.00	60.00	+
54	2 pcs	Rear Fender Inner Shield	169.00	338.00	+
55	2 set	Rear Fender Inner Shield Clips	25.00	50.00	+
56	2 pcs	Rear Air Vents	85.00	170.00	+
57	1 pc	Fuel Lid Cover		110.00	+
58	1 pc	Rear Exhaust Silencer		1,853.60	+
59	6 pcs	Rear Exhaust Mountings	38.00	228.00	+
60	2 pcs	Rear Exhaust Mountings Bracket	112.00	224.00	+
61	1 pc	Rear Exhaust Gasket		65.00	+
62	2 pcs	Rear Exhaust Heat Plate	135.00	270.00	+

21,708.60

3479.70

Less 10%

2,170.86

3131.73

19,537.74

Special Nett

1	1 pc	Rear Number Plate with Cover (Special)		150.00	+
2	1 set	Reverse Sensor		250.00	+
3	1 set	Body Panel Joint Sealant		120.00	+
4	1 set	Rear Floor Panel Insulator Pad		150.00	+
5	2 pcs	Rear Exhaust Chrome Pipe	140.00	280.00	+

Labour charge

Panel Beating		2,000.00	+
Spray painting		2,000.00	+
Check Wiring on tailamp		120.00	+
Anti rust		180.00	+
Remove and install interior upholstery		180.00	+
Remove and install reverse sensor		120.00	+
Remove and install rear exhaust silencer.		150.00	+

\$ 25,237.74

Adrian L
1/5 21/12/21

total: 4271.73

L/S: 34K

03 Days