MFORT TRANSPORTATION PTE LTD

PAIR ESTIMATE

ehicle No. : SHA7761R

Make

: HYUNDAI

Model

: IONIQ(G2)

Date: 20/12/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			ne \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT		W.	\$394.80
	SUB TOTAL LESS 20% DISCOUNTED TOTAL	,	473.25 378.60	\$1,327.45 \$265.49 \$1,061.96
1	REAR BUMPER RUBBER MAT REAR NUMBER PLATE WITH TRIM COVER	-10.00%	55	ny \$50.00 dis \$55.00
1	REAR BUMPER REVERSE SENSOR	-10.00%	49.50 hu	\$55.00 \$180.00 \$235.00
L	abour Charge			
P	PANEL BEATING			350
s	PRAY PAINTING CHARGE		८३०	\$400.00
R	REMOVE/REFIX REVERSE SENSOR			2 1 4000.00
	TOTAL LABOUR		\$1058.10	\$\sqrt{\$60.00}\$
	ESTIMATE TOTAL		\$1058.10 \$ 2deys	\$2,056.96
This is an initial				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanflin 97498749

WP 20/12/21 & 5pm

2 days

lemy new paids

tanflin 2/blanfowers

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: