

Our Job Ref No : 305498410
Date : 23/12/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Taufikh
Vehicle Reg No. : SHA7761R CTPL

Fax :


17/12/2021


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** --- **SKA 224K**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$378.60
 - (b) Labour Charges ~~\$685.00~~ 679.50
 - Total for Part-By-Part Repair Cost** ~~\$1,063.60~~ 1058.10
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Taufikh
Date : 27/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: Towing fee incurred

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305498410
REGN NO : SHA7761R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 23.01.2020
DATE/TIME IN : 20.12.2021 09:10
ACCIDENT DATE : 17.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C 1 451.25 20.00 361.00

0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

SUB-TOTAL : 378.60

JOB NATURE

0000 PB PANEL BEATING SHA7761R 350.00

0001 SP SPRAYPAINT CHARGE 250.00

0002 20-204 REMOVE/REFIX REVERSE SENSOR 30.00

0003 L REAR BUMBER PLATE WITH TRIM COVER 55.00 less 10%- 49.50

SUB-TOTAL : ~~685.00~~ 679.50TOTAL : ~~1063.00~~ 1058.10

MVA NAME & SIGNATURE

DATE : 23/12/21

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO