



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1620T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER COVER	CRACKED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DISTORTED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	138.10	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER REFLECTOR LAMP RH	NOT NECESSARY	41.45	-
1	ANTENNA ASSY SMARYKEY	CRACKED	40.50	40.50
1	REAR BUMPER FOG LAMP	CRACKED	201.50	201.50
1	LICENCE LAMP	NOT NECESSARY	85.30	-
1	REAR PANEL	NOT NECESSARY	532.00	-
1	REAR PANEL GARNISH	NOT NECESSARY	346.80	-
1	BOOTLID LAMP RH	NOT NECESSARY	794.40	-
1	BOOTLID	BENT	2,480.40	2,480.40
1	BOOTLID HYUNDAI PLATE	NOT NECESSARY	24.30	-
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	BOOTLID LAMP LH	NOT NECESSARY	794.40	-
1	REAR BUMPER LOWER MOULDING	DEFORMED	155.00	155.00
	LESS 20% DISCOUNT		-1,423.20	-773.13
			5,692.80	3,092.52
<b><u>NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (N)	CRACKED	55.00	55.00
1	BOOTLID COMFORT TEL NO STICKER (N)	NECESSARY	40.00	30.00
1	BOOTLID COMFORT LOGO STICKER (N)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	30.00	40.00
1	REAR BUMPER REVERSE SENSOR (N)	CRACKED	180.00	180.00
	LESS 10% DISCOUNT		-	-33.50
			335.00	301.50



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		1,100.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHK ALL LIGHTING.		60.00	30.00
	TUFF KOTE.		60.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			1,900.00	1,115.00
<b>GRAND TOTAL</b>			<b>7,977.80</b>	<b>4,559.02</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>4,559.02</b>

Report Ref No. NS/INC21012977/T1vce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.