

ASS. REC. BY: Tau Jkh

REF: INC NS/INC21012977/T1vc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBJ 1772Y

Policy No. _____

Claims No. MT/1154974-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WR

Date: _____ Person Contacted: Ms Loh Vehicle: IN / OUT

Veh No: SHC 1620T Yr Regn: 2020 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai cc 1500

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 154534 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHG 851 CL64188767

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or as stated

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/12/21 D.O.I. 20/12/21

Survey held at Compass Logic

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/12/21	Final fig \$4559.02 confirmed by email (Red 3423.28, 75%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? 2) 27/12/21-typist

Rep. Format: TP

Lump Sum / L&R (\$) \$4559.02

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
_____ \$ + RS. _____ \$	_____
Photos	_____
Others	_____
TOTAL	_____

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1620C

Make : HYUNDAI

Model : IONIQ(G3)

Date: 20/12/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			over \$459.40
10	REAR BUMPER CLIPS			over \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			diag \$451.25
1	REAR BUMPER REINFORCEMENT			? \$394.80
1	REAR BUMPER REINFORCEMENT BRACKET RH			? \$138.10
1	REAR BUMPER TOWING COVER			X \$98.80
1	REAR BUMPER REFLECTOR LAMP RH			X \$41.45
1	ANTENNA ASSY SMARTKEY			? \$40.50
1	REAR BUMPER FOG LAMP			? \$201.50
1	LICENCE LAMP			\$85.30
1	REAR PANEL			X \$532.00
1	REAR PANEL GARNISH			X \$346.80
1	BOOTLID LAMP RH			\$794.40
1	BOOTLID			bt \$2,480.40
1	BOOTLID HYUNDAI PLATE			over \$24.30
1	EMBLEM HYBRID			over \$24.30
1	EMBLEM - IONIQ			over \$31.30
1	BOOTLID LAMP LH			X \$794.40
	SUB TOTAL			\$6,961.00
	LESS 20%			\$1,392.20
	DISCOUNTED TOTAL			\$5,568.80
1	REAR BUMPER RUBBER MAT			over \$50.00
1	BOOTLID COMFORT TEL NO STICKER			over \$40.00
1	BOOTLID COMFORT LOGO STICKER			over \$30.00
1	BOOTLID COMFORT APP STICKER			over \$30.00
1	REAR BUMPER REVERSE SENSOR			over \$180.00
				\$330.00
	Labour Charge			
	PANEL BEATING			\$25 \$1,100.00
	SPRAY PAINTING CHARGE			500 \$600.00
	CHK ALL LIGHTING			30 \$60.00
	TUFF KOTE			30 \$60.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	TOTAL LABOUR			\$1,900.00
	ESTIMATE TOTAL			\$7,798.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 97495749
wpr 20/12/21 @ 5:05pm
3 days
Pls survey before paint

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tan Jiah @ lkkauto.com

Workshops

Date/Time: 20.12.2021 08:24 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4153513

JC NO305498354


JSTOMER
R/MS COMFORT TRANSPORTATION PTE LTD
JSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)
(P)
SCOUNT CARD NO.

REGN NO: SHC1620T	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 17.12.2021 16:05
YR OF MANU. 16.01.2020	TARGET DATE
CHASSIS CODE KMHC851CVLU188762	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 17.12.2021
NATURE: 3P 17.12.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHC1620T** YY

Vehicle No.: **SHC1620T**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard