

NS/INC21012978/T1tc

ASS. REC. BY: Tang JH

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **MT/1155452-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chuan Vehicle: IN / OUT

Veh No: SHC 2331X Yr Regn: 209 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 42440 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDUB3F4503077914

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/12/11

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / A/Rooftop or

Frnt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

lump sum 1850 2days

red: 6344.01;77%

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L&A ()

Days Of Repair: **2**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ \$ + RS. \$ _____

Photos _____

Others _____

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 20.12.21MODEL: Toyota PriusVEHICLE NO.: SHC2331XINSURANCE: NTUC - 45MVA: CHIANG

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$499.90
	Front Bumper Side Bracket LH	1		\$82.30
	Front Bumper Clips	10	\$2.20	\$22.00
	Front Fender LH	1		\$945.30
	Front Fender (Hybrid) LH	1		\$86.50
	Front Fender Shield LH	1		\$198.50
	Front Door LH	1		\$1,264.00
	Rear Door LH	1		\$1,258.30
	Front Wheel Rim LH	1		\$1,570.55
	Wing Mirror LH	1		\$1,390.10
	Wing Mirror Outer Cover LH	1		\$141.90
	SUB TOTAL			\$7,459.35
	LESS 25%			\$1,864.84
	DISCOUNTED TOTAL			\$5,594.51
	Rear Door APPS LH	1		\$80.00
	Front Door ComfortDelGro LH	1		\$75.00
	S/NETT SUB			\$155.00
	LESS 10%			\$15.50
	S/NETT TOTAL			\$139.50
	SPARE PARTS TOTAL			\$5,734.01
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$1,200.00
	Tuff Kote			\$100.00
	Transfer Of Doors			\$240.00
	Wheel Alignment			\$120.00
	TOTAL LABOUR			\$2,460.00
	ESTIMATE TOTAL			\$8,194.01

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495745
 'WP' 20/12/21 @ 510 pm
 L/S Resurvey after repair
 2-4 days
 Tanpin C. M. M. M. M.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 20.12.2021 10:00

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305498357

OMER

IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

DUNT CARD NO.

REGN NO:

SHC2331X

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)18.12.2021 08:45

DATE/TIME IN

YR OF MANU.

07.01.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU503077914

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 17.12.2021
ATURE: 3P 17.12.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Jo: SHC2331X

CHIANG

Vehicle No.:

SHC2331X

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard