

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK

DATE: 20-Dec-21INSURANCE: NTUC CP/PMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC8332D

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Smart Key Antenna	1		\$40.50 <i>an</i>
	Rear Bumper	1		\$459.40 <i>an</i>
	Rear Bumper Reinforcement	1		\$394.80 <i>an</i>
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20 <i>an</i>
	Rear Bumper Centre Moulding Assy	1		\$451.25 <i>an</i>
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 <i>an</i>
	Rear Bumper Cover Clips	10	\$2.20	\$22.00 <i>an</i>
	Rear Bumper Fog Lamp	1		\$201.50 <i>an</i>
	Rear Bumper Towing Cover	1		\$98.80 <i>an</i>
	SUB TOTAL		<i>473.25</i>	\$2,099.45
	LESS 20%		<i>378.60</i>	\$419.89
	DISCOUNTED TOTAL			\$1,679.56
	Rear Bumper Reverse Sensor	1	<i>55</i>	\$180.00 <i>an</i>
	Rear No. Plate W/Trim Cover	1		\$55.00 <i>an</i>
	SUB S/NETT		<i>49.50</i>	\$235.00
	LESS 10%			\$23.50
	SUB S/NETT TOTAL			\$211.50
	Rear Bumper Mat	1		\$50.00 <i>an</i>
	NETT TOTAL			\$50.00
	SPARE PARTS TOTAL			\$1,941.06
	Labour Charge			
	Panel Beating		<i>630</i>	\$400.00 <i>350</i>
	Spray Painting Charge			\$300.00 <i>250</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>40</i>
	TOTAL LABOUR		<i>1058.10</i>	\$820.00
	ESTIMATE TOTAL		<i>2 days</i>	\$2,761.06

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

faulst 97495749
upr 20/12/21 @ 535
2 days
pld using New parts
faulst @ chhandban

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company