

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 20-Dec-21MODEL: Hyundai IoniqVEHICLE NO.: SHC8332DINSURANCE: NTUC *CP/P*MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Smart Key Antenna	1		\$40.50 ?
	Rear Bumper	1		\$459.40 <i>25</i>
	Rear Bumper Reinforcement	1		\$394.80 ?
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20 ?
	Rear Bumper Centre Moulding Assy	1		\$451.25 <i>del</i>
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 <i>X</i>
	Rear Bumper Cover Clips	10	\$2.20	\$22.00 <i>del</i>
	Rear Bumper Fog Lamp	1		\$201.50 ?
	Rear Bumper Towing Cover	1		\$98.80 <i>X</i>
	SUB TOTAL			\$2,099.45
	LESS 20%			\$419.89
	DISCOUNTED TOTAL			\$1,679.56
	Rear Bumper Reverse Sensor	1		\$180.00 ?
	Rear No. Plate W/Trim Cover	1		\$55.00 <i>del</i>
	SUB S/NETT			\$235.00
	LESS 10%			\$23.50
	SUB S/NETT TOTAL			\$211.50
	Rear Bumper Mat	1		\$50.00 <i>X</i>
	NETT TOTAL			\$50.00
	SPARE PARTS TOTAL			\$1,941.06
	Labour Charge			
	Panel Beating			\$400.00 <i>25</i>
	Spray Painting Charge			\$300.00 <i>25</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>25</i>
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,761.06

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Handwritten notes:
 97495749
 20/12/21 @ 535
 2 days
 1/1 Body New parts
 1/1 @ (headroom)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 20.12.2021 11:08

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4153560

JC NO305498411

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.


REGN NO: SHC8332D	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 20.12.2021 09:40
YR OF MANU. 08.01.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU191855	COMPLETION DATE/TIME:

cident Date: 17.12.2021
TURE: 3P 17.12.2021

JOB DESCRIPTION

NO LABOR CODE
0010 PB

DESCRIPTION
PANEL BEATING-SHC8332D



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.: SHC8332D

LIMITS

SHC8332D

Service Advisor

Signature/Date

Name of Service Advisor

Date

med to Service Reception upon collection

To be kept by Security Guard