NS/INC21012984/T1vc INC ASSIGNMENT SHD 34784. Yr Regn: 29.6, try From: Veh No: Estimated Cost OD I(TP) WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: Hyurday" 140. at Workshop m/s Colour Insured / Std / NI / NA Sp.Reading T/Radio: Insured / Std / NI / NA **SMM 4743R** Insured: Eng/No: Policy No. C/No: MT/1155317-002 Claims No. Gen. Cond: Good | Fair / Poor / Burnt Sum Insured: Steering: Inorder / Jammed / Leaked / Burnt or Excess: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Make of Veh: Modi: NII BRIM / STD AIRIM OF Tyre Size: (Policy Condition) Remark: The veh had commenced Its NIS OIS BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. Worthalu TOYO / YOKO or Rear Front Bal. or Market Value: R/Bal, R/Bal. Consistent? : Yes or No IDAC Accident Rport: UBal. L/Bal. Consistent?: Yes or No GIA / PR Seen: mm 20/ D.O.I. D.O.A. 19/12/21 Res.: Yes or No days Est. Repairs: Survey held at 3 Val.: Yes or No Lum Sum: Des. of Damages : Frt / Regr / O/S / N/S / U/C / Rooftop or CA / REY / REP. / 24 HRS Vehicle: IN / OUT The U/O / Chassis frame / Body Structure affected due to collision. Person Contacted: Date / Time Action / Instruction LS \$900 confirmed by email (Red 1162.90, 56%) 25/12/21 Date/Time, File Pass to? : Prell. Report Days Of Repair: Resurvey No. of Trip: 1 Survey Fee: : Final Report Date/Time, File Return to? Transportation: Add Fee: : Site Insp (\$ \_S + RS.\_\_SI 2) 27/12/21-typist : Interview (\$ Pholos : Tech. Invs (\$ Represent: TP Others Lump Sum / HEA (\* \$900 Weelend (\$ TOTAL

Sheet2

## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD3478U

Make

: HYUNDAI

Model

: 1-40

Date: 20/12/2021

Insurance: NTUC

MVA: MS. YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount	1.
1 F	REAR BUMPER COVER			\$1,106.00	
1 F	REAR BUMPER CLIPS			\$22.00	ne
1 F	REAR BUMPER UNDER COVER			\$228.00	EY.
				<b>*</b> 504.00	
	SUB TOTAL			\$1,584.00	
	LESS 20%			\$316.80 <b>\$1,267.20</b>	
	DISCOUNTED TOTAL				
	THE RUNANTED DEVEROES SENSOR		-10%	\$135.70	Ne
1	REAR BUMPER REVERSE SENSOR		-1070	\$135.70	1
	Laborate Observe				
	Labour Charge PANEL BEATING			\$300.00	2
- 1	SPRAY PAINTING CHARGE			\$300.00	5
	REMOVE/REFIX REVERSE SENSOR			\$60.00	1
	TOTAL LABOUR			\$660.00	1
	ESTIMATE TOTAL			\$2,062.90	1
	hamadana and amazan his bir				
					1

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

taufhi 2749)749

al' 20/12/21 ( 53)

2 dezs

2/5 Resnon after epoir

fenfish (Mharoforam

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:



## ComfortDelGro Engineering Pte Ltd

Date/Time: 20.12.2021 14:10

Workshops 205 Braddell Road Singapore 5 79701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Page : 1

JOB CARD Sales Order: 4153615 JC NO305498418 ARC Repair TP(CLSO)1 Team: REGN NO.: SHD3478U MII FAGE CUSTOMER COMFORT TRANSPORTATION PTE LTD FUEL MR/MS HYUNDAI 7010045 E.....1/2.. CUSTOMER NO MODEL I-40 383 SIN MING DRIVE 20.12.2021 10:45 ADDRESS Singapore SINGAPORE 575717 65508755 TARGET DATE YR OF MANU. 25.08.2016 TEL. (R) (P) CHASSIS CODE KMHLB41UMGU093410 COMPLETION DATE/TIME DISCOUNT CARD NO. JOB DESCRIPTION Accident Date: 19.12.2021 NATURE: 3P 19.12.2021 FRONT DESCRIPTION LABOR CODE S/NO CHECKED & PASSED OUT BY: **CUSTOMER'S SIGNATURE** SERVICE ADVISOR Exit Pass knowledgement Slip Vehicle No.: YY ' SHD3478U SHD3478U nicle No.:

me of Service Advisor

Signature/Date

Name of Service Advisor

Date

be returned to Service Reception upon collection

To be kept by Security Guard