

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHD3478U

Date: 20/12/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$1,106.00	de
1	REAR BUMPER CLIPS			\$22.00	ney
1	REAR BUMPER UNDER COVER			\$228.00	ben
			1128		
	SUB TOTAL		902.40	\$1,584.00	
	LESS 20%			\$316.80	
	DISCOUNTED TOTAL			\$1,267.20	
1	REAR BUMPER REVERSE SENSOR		Xan -10%	\$135.70	Nett
			135.70	\$135.70	Nett
			122.13		
	Labour Charge				
	PANEL BEATING		560	\$300.00	280
	SPRAY PAINTING CHARGE			\$300.00	250
	REMOVE/REFIX REVERSE SENSOR			\$60.00	30
	TOTAL LABOUR		1462.40	\$660.00	
	ESTIMATE TOTAL		4/5/900	\$2,062.90	
			0.2 days		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

tauphin 27495719  
 'wp' 20/12/21 @ 535  
 • 2 days  
 4/5 resurvey after repair  
 tauphin@hklawfirm.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company