

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
GOH KOON KEE		Cust No/Name	/GOH KOON KEE
42 LAKESIDE DRIVE		Reg No/Reg Date	SMV8986H / 27/10/202
#12-08		Date In/Mileage	/ 0
SINGAPORE 648322		Chassis No	KNAF5416ML5086943
		Engine No	G4FGKH754871
		Make/Model	KIA/CERATO 1.6 A GT LINE H171
Contact No	Mobile: 98228594	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	23/11/2021/ 17:49	TLK	282 / Kevin Leong	42884		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2560.00
REPLACE FRT BUMPER, FRT LH DOOR, FRT LH FENDER & AFFECTED AREA							
E PNT98000							2200.00
PAINT WORK FRT BUMPER, FRT LH FENDER & FRT LH DOOR							
E PNT88000							180.00
TO TRANSFER FRT LH DOOR ATTACHMENT TO NEW PANEL							
M SUNDRY							100.00
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							100.00
PERFORM RUST PREVENTION							
A 54900099							120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
B WHEELALIGNMENT							192.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							50.00
TO TRANSFER FRT LH RIM INCLUDING BALANCING							
M SUNDRY							50.00
SUNDRIES							
M LAMP ASSY-HEAD,LH					1.00	2210.00 00.00	2210.00
M PANEL-FENDER,LH					1.00	430.00 00.00	430.00
M PANEL ASSY-FRONT DOOR,LH					1.00	1277.00 00.00	1277.00
M COVER-FR BUMPER					1.00	633.00 00.00	633.00
M AIR DUCT-FR BUMPER,LH					1.00	14.00 00.00	14.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00 00.00	22.00
M ORNAMENT-KIA NO.115					1.00	32.00 00.00	32.00
M MOULDING ASSY-FRT DR FRAME,LH					1.00	72.00 00.00	72.00
M W/STRIP ASSY-FR DR BELT O/S LH					1.00	80.00 00.00	80.00
M W/STRIP ASSY-FR DR SIDE LH					1.00	102.00 00.00	102.00

Confirm & accepted by

	Nett	10,704.00
7% GST on	10704.00	749.28
	Total Payable	11,453.28

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.