

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/1033/2021/NK  
DATE : 20-Dec-21  
WIP : 59460

*Xiao Chun .  
24 Days. H.S.  
\$45 K.*

VEHICLE IN BENOI WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/12/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

OWNER'S NAME : MR CHUA SWEE BOON(CAI RUIWEN)  
ADDRESS : BLK 609 ANG MO KIO AVE 4  
#10-1169  
SINGAPORE 560609  
TELEPHONE : HP +65 94306852  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1700063199-04  
VEHICLE NO : **SGH 7637 S**  
MODEL CODE : AUDI A4 1.4 TFSI  
MODEL YEAR : 11/10/2017  
ENGINE NO : CVN041412  
CHASSIS NO : WAUZZZF4XHA182059  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 18-Dec-21  
PLACE OF ACCIDENT : NEAR GUILLEMARD ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGH 7637 S**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ <del>700.00</del>	500. ✓
3	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ <del>500.00</del>	250. ✓
4	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	S/N \$ 800.00	✓
5	TO RENEW FRONT WINDSCREEN	S/N \$ 480.00	✓
6	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	S/N \$ 400.00	✓
7	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	S/N \$ <del>200.00</del>	150. ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,440.00</b>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGH 7637 S**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING. BOTH CURTAIN AIR BAGS.	S/N \$ 3,600.00	✓✓
9	TO REMOVE AND RENEW AIRCON CONDENSERS, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 1,400.00	✓✓
10	TO RENEW COOLANT HOSE, THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$ 780.00	?X
11	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGERMENTS COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,000.00	2500 ✓
12	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDER, BOTH FRONT DOOR AND BOTH UPPER A-PILLAR.	\$ 6,900.00	3300 ✓
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	192 ✓✓ 192
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 23,784.00</b>	192



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 7637 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,111.00	✓ 1688.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	TBC	x
3	FRONT BUMPER SECURING STRIPS <i>Best</i>	2	\$ 71.00	✓ 56.32
4	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 196.00	✓ 156.40
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE <i>crushed</i>	1	\$ 210.00	✓ 167.60
6	FRONT BUMPER AIR GUIDE LH <i>new</i>	1	\$ 63.00	? 50.08 ✓
7	FRONT BUMPER AIR GUIDE RH <i>new</i>	1	\$ 63.00	X
8	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,819.00	✓ 1455.20
9	AIR GUIDE GRILLE LH / RH <i>new</i>	2	\$ 730.00	✓ 584
10	FRONT BUMPER FOAM FILLER <i>crushed</i>	1	\$ 124.00	✓ 99.20
11	FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>	1	\$ 845.00	✓ 675.60
12	FRONT BUMPER GUIDE SECTION LH / RH <i>LH Damaged</i>	2	\$ 74.00	3758.56
13	FRONT BUMPER BRACKET LH / RH <i>Damaged</i>	2	\$ 456.00	? 364 ✓
14	FRONT BUMPER TOP COVER <i>del</i>	1	\$ 127.00	✓ 101.60
15	SIGN CAUTION <i>new</i>	1	\$ 14.00	✓ 10.88
16	STICKER FOR AIR CONDITIONER <i>new</i>	1	\$ 8.00	✓ 5.68
17	LOCK CARRIER BRACKET <i>crushed</i>	1	\$ 137.00	✓ 109.60
18	LOCK CARRIER SUPPORT LH/ RH <i>new</i>	2	\$ 58.00	✓ 44.96
19	HORN HIGH TONE LH <i>new</i>	1	\$ 126.00	? X
20	HORN LOW TONE RH <i>new</i>	1	\$ 126.00	? X
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 7,358.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 7637 S**

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	SPRING SHACKLE LH / RH <i>Abol rec</i>	2	S	58.00	?X	
22	FRONT FENDER LH / RH <i>Regis</i>	2	S	1,534.00	+	
23	FRONT FENDER ATTACHMENTS PARTS	1	S	202.00	+	
24	FRONT FENDER CLOSING ELEMENTS LH/ RH <i>Rec on</i>	2	S	144.00	+	
25	FRONT FENDER BRACKET LH / RH	2	S	70.00	+	
26	FRONT FENDER BRACKET DEFORMATION ELEMENT LH/RH <i>Rec</i>	2	S	98.00	+	
27	FRONT FENDER BRACE FRONT LH / RH <i>Rec</i>	2	S	236.00	+	
28	WHEEL HOUSING LINER LH <i>Rec</i>	1	S	240.00	+	
29	WHEEL HOUSING LINER RH	1	S	241.00	+	
30	WHEEL HOUSING LINER ATTACHMENTS PARTS	1	TBC		+	
31	WHEEL SPOILER LH/ RH <i>Rec</i>	2	S	146.00	58.40 ✓	damaged
32	WHEEL SPOILER TRIM LH / RH	2	S	71.00	+	
33	BONNET <i>Dented</i>	1	S	3,246.00	2596.80	
34	BONNET ATTACHMENTS PARTS <i>Rec</i>	1	S	412.00	+	
35	BONNET LID HINGE LH / RH <i>Rec</i>	1	S	610.00	+	
36	BONNET IMPACT PROTECTION CENTRE/ LH/RH <i>Rec</i>	3	S	84.00	65.68 ✓	
37	BONNET STRIKER LH / RH <i>Rec</i>	2	S	100.00	79.84 ✓	
38	BONNET LID LOCK <i>Rec</i>	2	S	427.00	341.60 ✓	
39	BOWDEN CABLE CENTRE LH / RH <i>Rec</i>	2	S	116.00	92 ✓	
40	BOWDEN CABLE COVER <i>NOT</i>	1	S	10.00	+	
<b>SUB TOTAL SPARE PARTS</b>		:	\$	<b>8,045.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 7637 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RELEASE LEVER	1 S	14.00	X
42	LID LOCK CABLE	1 S	74.00	X
43	COVER FOR PLENUM CHAMBER	1 S	97.00	X
44	FLAT CONNECTOR HOUSING	2 S	26.00	X
45	FRONT FENDER FLEDGE COVER LONG LH / RH	2 S	62.00	X
46	FRONT FENDER FLEDGE COVER SHORT LH / RH	2 S	46.00	X 38.08 ✓
47	LED HEADLIGHT LH / RH	2 S	15,386.00	12308.80
48	HEADLIGHT POWER MODULE	2 S	1,521.00	X
49	HEADLIGHT CONTROL UNIT	2 S	1,501.00	? 600.40 ✓
50	HEADLIGHT HOSE LH / RH	2 S	72.00	X
51	HEADLIGHT COMPENSATING 10MM PC	2 S	160.00	? X
52	HEADLIGHT COMPENSATING 0.8MM PC	2 S	83.00	? X
53	HEADLIGHT LIFT CYLINDER LH/ RH	2 S	420.00	? X
54	HEADLIGHT BRACKET	2 S	12.00	? X
55	HEADLIGHT CORRUGATED PIPE	1 S	93.00	? 74 ✓
56	LOCK CARRIER	1 S	1,016.00	812.80
57	LOCK CARRIER SUPPORT	2 S	76.00	? 60.64 ✓
58	A/C CONDENSER	1 S	622.00	✓ 497.60
59	A/C PRESSURE SENSOR	1 S	191.00	X
60	A/C VALVE PRESSURE SWITCH	1 S	51.00	X
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 21,523.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 7637 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REFRIGERANT LINE	1 S	167.00 +	
62	REFRIGERANT LINE	1 S	340.00 +	
63	REFRIGERANT LINE	1 S	248.00 +	
64	REFRIGERANT LINE BRACKET	1 S	19.00 +	
65	ADDITIONAL COOLER FOR COOLANT LOWER CENTRE	1 S	511.00	408.40 ✓
66	COOLER FOR COOLANT	1 S	655.00	523.60 ✓
67	RUBBER BUSH LOWER	2 S	25.00	X
68	COOLANT	6 S	266.00	212.64
69	COOLANT HOSE UPPER	1 S	53.00 +	
70	COOLANT HOSE	1 S	117.00 +	
71	FAN RING 600W	1 S	267.00	213.20 ✓
72	RADIATOR FAN	1 S	2,318.00	1854.40 ✓
73	RADIATOR FAN AIR GUIDE LH / RH BIG	2 S	56.00	44.64 ✓
74	RADIATOR FAN AIR GUIDE LH / RH SMALL	2 S	24.00	18.88 ✓
75	AIR GUIDE UPPER / LOWER	2 S	38.00	X
76	INTAKE AIR DUCT RH	1 S	22.00	X
77	AIR GUIDE	1 S	53.00	X
78	INTAKE HOSE	1 S	95.00	X
79	AIR FILTER	1 S	386.00	X
80	INTAKE CONNECTION	1 S	603.00	X
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 6,263.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 7637 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	CHARGE AIR COOLER <i>Not m</i>	1 S	775.00	X
82	THROTTLE VALVE ADAPTER <i>Not m</i>	1 S	825.00	X
83	NOISE INSULATION <i>Not m</i>	1 S	572.00	X
84	FRONT WINDSCREEN <i>Cracked</i>	1 S	1,125.00	900
85	GEL FOIL FOR RAIN SENSOR <i>Not m</i>	1 S	137.00	109.20
86	RETAINING SPRING <i>m</i>	1 S	21.00	16.56
87	WINDSCREEN PRIMER <i>m</i>	1 S	20.00	15.76
88	WATER DEFLECTOR LH / RH <i>Not m</i>	2 S	134.00	X
89	WINDOW SLOT SEAL LH / RH <i>Not m</i>	2 S	614.00	307 245.20
90	TRIM STRIP FOR WINDOW GUIDE <i>Not m</i>	2 S	514.00	X
91	AIRBAG UNIT FOR STEERING WHEEL	1 S	3,421.00	2736.80
92	AIRBAG UNIT FOR PASSENGER SIDE	1 S	4,374.00	3499.20
93	HEAD AIRBAG UNIT LH/RH	2 S	3,726.00	2980.80
94	CONTROL UNIT FOR AIRBAG	1 S	2,112.00	1689.60
95	CRASH SENSOR FOR AIRBAG FRONT	3	TBC	X NN
96	CENTRAL PROTECTION <i>Activated</i>	1 S	533.00	426
97	STEERING WHEEL LEATHER <i>Not m</i>	1 S	2,241.00	X
98	DASHBOARD AIR DUCT <i>torn</i>	1 S	5,289.00	4231.20
99	DEFROSTER NOZZLE FOR WINDSCREEN <i>Not m</i>	1 S	167.00	133.60 ✓
100	GRILLE <i>Not m</i>	1 S	123.00	X
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 26,723.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 7637 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	MOULDED HEADLINING <i>reformed</i>	1 S	1,918.00	✓ 1534.40
102	THREE POINT AUTOMATIC SEAT BELT TENSIONER <i>Activated</i>	1 S	2,206.00	✓ 1764.80
103	SEAT BELT HEIGHT ADJUSTER <i>DAM</i>	2 S	342.00	✓ 273.60 ✓
104	GRAB HANDLING FOLDING FRONT <i>3rd</i>	2 S	283.00	? 226.40 ✓
105	GRAB HANDLING FOLDING LEFT REAR <i>2nd</i>	1 S	142.00	? 113.20 ✓
106	GRAB HANDLING FOLDING RIGHT REAR <i>2nd</i>	1 S	142.00	? 113.20 ✓
107	A-PILLAR TRIM LH/ RH UPPER <i>Del</i>	2 S	408.00	? 326.40 ✓
108	C-PILLAR TRIM LH <i>Del</i>	1 S	217.00	? 173.20 ✓
109	C-PILLAR RH <i>Del</i>	1 S	217.00	? 173.20 ✓
110	FRONT NO PLATE <i>Bent</i>	S/N S	60.00	✓
111	FRONT WINDSCREEN SEALANT <i>new</i>	1 S	200.00	✓
112	SUNDRIES <i>new</i>	1 S	500.00	? 213.44 ✓
<b>TOTAL SPARE PARTS</b>		:	\$ 76,547.00	
<b>TOTAL LABOUR CHARGES</b>		:	\$ 23,784.00	
<b>GRAND TOTAL</b>		:	\$ 100,331.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lj

SURVEYED DATE

: 21/12/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

17 Days Not Authorised.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT