|--|--|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	iale Des Experts En	Automob	ile		
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS/SMR21012991/R1qf3		
	60 WOODLANDS E4SINGAPORE 75	INDUSTRIAL PARK 57705		Date:	22/12/2021		
				Code:	SMR		
1.	Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SHF 319E	Veh. Inspected	i	YP 9945J		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	TAX/11/21/2067	Excess (\$)		0.00		
	Assign From	HUA YEN	Assign Date		22/12/2021		
2.	2. Vehicle Particulars & Condition						
	Make & Model		c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	-	Steering				
	Brakes		Modification				
	General						
3.		Condition	ons of Tyres				
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
4.		Descriptio	n of Damages				
5.	1		Information				
	Accident Date	23/11/2021	Inspection Dat	te	23/12/2021		
	Survey held at	V-TECH AUTO SERVICE					
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605					
5a.	Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						