

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1025/2021/JT
DATE : 18-Dec-21
WIP : 59421

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

15-Mar-22

OWNER'S NAME : MR TEO KEE HUAT
ADDRESS : 18 BEDOK RISE
#10-54
SINGAPORE 465410
TELEPHONE : HP +65 96155981
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210086538
VEHICLE NO : **SKF 2836 E**
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 5/8/2021
ENGINE NO : CZD C41885
CHASSIS NO : WAUZZZF34M1131576
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Dec-21
PLACE OF ACCIDENT : SPC PETROL (BEDOK NORTH)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 2836 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUR SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	3,000.00	\$	1,300.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,272.00	\$	2,472.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2836 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,335.00	\$	1,068.00
2	FRONT BUMPER CONNECTING PIECE	1	\$ 145.00		
3	FRONT BUMPER FIXING PARTS	1	\$ 414.00		
4	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 59.00		
5	FRONT BUMPER TRIM - CENTER MANHATTAN GREY	1	\$ 356.00	\$	284.40
6	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	\$	173.20
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 50.00		
8	FRONT BUMPER GRILLE COVER	1	\$ 51.00		
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00		
10	FRONT BUMPER SPOILER	1	\$ 763.00	\$	610.00
11	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 153.00		
12	FRONT BUMPER TRIM - LH MANHATTAN GREY	1	\$ 164.00	\$	130.80
13	FRONT PARKING AID SENSOR SUPPORT OUTER - LH	1	\$ 25.00		
14	RADIATOR GRILLE	1	\$ 1,928.00	\$	1,542.40
15	FRONT STRIKER PLATE	1	\$ 244.00	\$	194.80
16	RADIATOR GRILLE COVER	1	\$ 244.00	\$	194.80
17	RADIATOR BRACKET	1	\$ 41.00		
18	RADIATOR BRACKET COVER	1	\$ 56.00		
19	FRONT BUMPER FOAM FILLER PIECE	1	\$ 102.00		
20	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 916.00		
SUB TOTAL SPARE PARTS		:	\$ 7,453.00	\$	4,198.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2836 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 4,198.40</i>
21	FRONT BUMPER TOP COVER	1	\$ 123.00	
22	"CAUTION" STICKER	1	\$ 14.00	
23	AIR COND STICKER	1	\$ 8.00	
24	HORN - LH	1	\$ 137.00	
25	HORN BRACKET - LH	1	\$ 22.00	
26	FRONT PARKING AID SENSOR	2	TBC	
27	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	
28	HEADLIGHT MOUNTING - LH	1	\$ 118.00	<i>\$ 94.40</i>
29	HEADLIGHT - LH	1	\$ 5,589.00	
30	LIFT CYLINDER - LH	1	\$ 210.00	
31	LIFT CYLINDER HOSE	1	\$ 80.00	
32	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 7.00	
33	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	
34	FRONT WHEEL HOUSING TRIM - LH	1	\$ 16.00	
35	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,072.00	<i>\$ 857.60</i>
36	RADIATOR AIR GUIDE - LH	1	\$ 38.00	
37	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 84.00	
38	FRONT NOISE INSULATION	1	\$ 397.00	
39	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
40	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 15,977.00	\$ 5,210.40
TOTAL LABOUR CHARGES			\$ 5,272.00	\$ 2,472.00
GRAND TOTAL			\$ 21,249.00	\$ 7,682.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-25/02/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT