

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6396 2323 FAX 6341 1183

EMAIL: NORA.NIH@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

Xiao Chen.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 2836 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUR SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	x
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,000.00	Bumper 550 Arch trim x2 = 400 950
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 5,272.00	

* Spray Painting for Front Bumper lower Spoiler : 350

total spray Painting = 950 + 350 = 1300.
#

Adrian L
10/02/22.
Resurveyed
SLS

SLS

Car-in.

8/2/22.

wip: 59421-

Kiam/ Hong-



AIG- Adrian

- 3 days

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6365 2323 FAX: 6341 1183
EMAIL: MORAKHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2836 E

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>behind</i>	1	\$ 1,335.00	✓
2	FRONT BUMPER CONNECTING PIECE <i>RH in</i>	1	\$ 145.00	✓
3	FRONT BUMPER FIXING PARTS	1	\$ 414.00	?
4	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 59.00	?
5	FRONT TRIM <i>crushed</i>	1	\$ 356.00	✓
6	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 217.00	✓
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>not in</i>	2	\$ 50.00	+
8	FRONT BUMPER GRILLE COVER	1	\$ 51.00	?
9	FRONT BUMPER CLOSING ELEMENT <i>RH in</i>	1	\$ 190.00	✓
10	FRONT BUMPER SPOILER <i>distorted</i>	1	\$ 763.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>RH in</i>	1	\$ 153.00	+
12	FRONT BUMPER TRIM - LH MANHATTAN GREY <i>cut</i>	1	\$ 164.00	✓
13	FRONT PARKING AID SENSOR SUPPORT OUTER - LH <i>not in</i>	1	\$ 25.00	+
14	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,928.00	✓
15	FRONT STRIKER PLATE <i>crushed</i>	1	\$ 244.00	✓
16	RADIATOR GRILLE COVER <i>behind</i>	1	\$ 244.00	✓
17	RADIATOR BRACKET	1	\$ 41.00	?
18	RADIATOR BRACKET COVER	1	\$ 56.00	?
19	FRONT BUMPER FOAM FILLER PIECE	1	\$ 102.00	?
20	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 916.00	?
SUB TOTAL SPARE PARTS			\$ 7,453.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408698

TEL: 6366 2323 FAX: 6641 1183

EMAIL: NDRAKIAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2836 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT BUMPER TOP COVER <i>new</i>	1	\$	123.00	X
22	"CAUTION" STICKER <i>new</i>	1	\$	14.00	+
23	AIR COND STICKER <i>new</i>	1	\$	8.00	X
24	HORN - LH	1	\$	137.00	+
25	HORN BRACKET - LH	1	\$	22.00	X
26	FRONT PARKING AID SENSOR <i>new</i>	2		TBC	X
27	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$	9.00	X
28	HEADLIGHT MOUNTING - LH <i>cracked</i>	1	\$	118.00	X
29	HEADLIGHT - LH <i>new</i>	1	\$	5,589.00	X
30	LIFT CYLINDER - LH <i>new</i>	1	\$	210.00	X
31	LIFT CYLINDER HOSE <i>new</i>	1	\$	80.00	X
32	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$	7.00	+
33	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$	240.00	+
34	FRONT WHEEL HOUSING TRIM - LH <i>new</i>	1	\$	16.00	+
35	FRONT WHEEL ARCH COVER - LH/RH <i>new</i>	2	\$	1,072.00	✓
36	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$	38.00	X
37	RADIATOR AIR GUIDE - UPPER / LOWER <i>new</i>	2	\$	84.00	+
38	FRONT NOISE INSULATION	1	\$	397.00	+
39	FRONT NO PLATE <i>new</i>	S/N	\$	60.00	✓
40	SUNDRIES		\$	300.00	?
TOTAL SPARE PARTS		:	\$	15,977.00	
TOTAL LABOUR CHARGES		:	\$	5,272.00	
GRAND TOTAL		:	\$	21,249.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.