



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2023 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1025/2021/JT
DATE : 18-Dec-21
WIP : 59421

Xiao Chen.
\$7682.40.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TEO KEE HUAT
ADDRESS : 18 BEDOK RISE
#10-54
SINGAPORE 465410
TELEPHONE : HP +65 96155981
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210086538
VEHICLE NO : SKF 2836 E
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 5/8/2021
ENGINE NO : CZD C41885
CHASSIS NO : WAUZZZF34M1131576
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Dec-21
PLACE OF ACCIDENT : SPC PETROL (BEDOK NORTH)





55 UBI ROAD 1, SINGAPORE 408899

TEL: 6346 2323 FAX: 6341 1153

EMAIL: INDIRA.KHAI@PREMIUMAUTO.COM.SG / CLAIM@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 2836 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUR SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	x
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,000.00	Bumper 550 Arch trim x2 = 400 950
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ Lower Spoiler 350
TOTAL LABOUR CHARGES		\$ 5,272.00	

total: 950 + 350
= 1300 ✓
H.S.



55, NIBERD RD, SINGAPORE 408699

TEL: 6366 2821 FAX: 6341 1183

EMAIL: INFO@PREMIUMAUTOMOBILES.COM.SG CLAIMS@PREMIUMAUTOMOBILES.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2836 E


			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>crushed</i>	1	\$ 1 335.00	✓ 1068
2	FRONT BUMPER CONNECTING PIECE <i>RH n</i>	1	\$ 145.00	✗
3	FRONT BUMPER FIXING PARTS <i>the ncc</i>	1	\$ 414.00	✗
4	FRONT BUMPER CLOSING ELEMENT - LH <i>the ncc</i>	1	\$ 59.00	✗
5	FRONT TRIM <i>crushed</i>	1	\$ 356.00	✓ 284.40
6	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 217.00	✓ 173.20
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>n</i>	2	\$ 50.00	+
8	FRONT BUMPER GRILLE COVER <i>the ncc</i>	1	\$ 51.00	✗
9	FRONT BUMPER CLOSING ELEMENT <i>the n</i>	1	\$ 190.00	✗
10	FRONT BUMPER SPOILER <i>distorted</i>	1	\$ 763.00	✓ 610
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>the n</i>	1	\$ 153.00	✗
12	FRONT BUMPER TRIM - LH MANHATTAN GREY <i>wt</i>	1	\$ 164.00	✓ 130.80
13	FRONT PARKING AID SENSOR SUPPORT OUTER - LH <i>n</i>	1	\$ 25.00	+
14	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,928.00	✓ 1542.40
15	FRONT STRIKER PLATE <i>cracked</i>	1	\$ 244.00	? 194.80 ✓
16	RADIATOR GRILLE COVER <i>deformed</i>	1	\$ 244.00	? 194.80 ✓
17	RADIATOR BRACKET <i>the ncc</i>	1	\$ 41.00	✗
18	RADIATOR BRACKET COVER <i>the ncc</i>	1	\$ 56.00	✗
19	FRONT BUMPER FOAM FILLER PIECE <i>the ncc</i>	1	\$ 102.00	✗
20	FRONT BUMPER REINFORCEMENT BEAM <i>the ncc</i>	1	\$ 916.00	✗
SUB TOTAL SPARE PARTS		:	\$ 7,453.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2025 FAX 6841 1183

EMAIL: NDRA@PREMIUMAUTO.COM.SG CLAIMS@PREMIUM-AUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2836 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER TOP COVER <i>see u</i>	1	\$	123.00 ✕
22	"CAUTION" STICKER <i>see u</i>	1	\$	14.00 ✕
23	AIR COND STICKER <i>see u</i>	1	\$	8.00 ✕
24	HORN - LH <i>see u</i>	1	\$	137.00 ✕
25	HORN BRACKET - LH <i>see u</i>	1	\$	22.00 ✕
26	FRONT PARKING AID SENSOR <i>see u</i>	2	TBC	✕
27	FRONT PARKING AID SENSOR SEAL RING <i>see u</i>	4	\$	9.00 ✕
28	HEADLIGHT MOUNTING - LH cracked <i>cracked</i>	1	\$	118.00 94.40 ✓
29	HEADLIGHT - LH <i>see u</i>	1	\$	5,589.00 ✕
30	LIFT CYLINDER - LH <i>see u</i>	1	\$	210.00 ✕
31	LIFT CYLINDER HOSE <i>see u</i>	1	\$	80.00 ✕
32	OUTSIDE TEMPERATURE SENSOR BRACKET <i>see u</i>	1	\$	7.00 ✕
33	FRONT WHEEL HOUSING LINER - LH <i>see u</i>	1	\$	240.00 ✕
34	FRONT WHEEL HOUSING TRIM - LH <i>see u</i>	1	\$	16.00 ✕
35	FRONT WHEEL ARCH COVER - LH / RH <i>see u</i>	2	\$	1,072.00 ✓ 857.60
36	RADIATOR AIR GUIDE - LH <i>see u</i>	1	\$	38.00 ✕
37	RADIATOR AIR GUIDE - UPPER / LOWER <i>see u</i>	2	\$	84.00 ✕
38	FRONT NOISE INSULATION	1	\$	397.00 ✕
39	FRONT NO PLATE <i>see u</i>	S/N	\$	60.00 ✓
40	SUNDRIES <i>see u</i>		\$	300.00 ?
TOTAL SPARE PARTS			\$	15,977.00
TOTAL LABOUR CHARGES			\$	5,272.00
GRAND TOTAL			\$	21,249.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6541 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG

NAME : Adrian Lj
SURVEYED DATE : 21/12/21.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT