

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 23 Dec 2021

Preliminary Advice

Vehicle No	: SML3007U	Accident Date	: 18/12/2021
Make	: AUDI A3	Policy No.	: 1900098198-02
Assignment Date	: 22/12/2021	Excess	: S\$600.00
Date of Inspection	: 21/12/2021	Est. Duration of Repair	: 21
Inspection At	: 24 BENOI SECTOR REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 82,477.00
Revised Amount	:S\$ 45,715.00
Check Items (Estimated)	:S\$ 11,559.00
Total	:S\$ 57,274.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 97,000.00
COE / PARF Rebate	:S\$ 43,768.00
Salvage Value	:S\$

Margin for Repair

:S\$ 53,232.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.