

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Dec 2021 13:38	Clm Veh Model Changed		[] Merimen Administrator
2	20 Dec 2021 13:38	Clm Created	Reg No: SML3007U. Policy No: 1900098198-02. Acct Date: 2021/12/18. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R21CK0001	[I] Merimen Administrator
3	22 Dec 2021 16:44	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	22 Dec 2021 16:44	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	22 Dec 2021 16:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	22 Dec 2021 16:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/31	[A] CELINE FONG
7	22 Dec 2021 16:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	22 Dec 2021 16:44	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	22 Dec 2021 16:44	Clm Veh Model Changed	(205252) AUDI A3 999cc TFSI S TRONIC (LED) (A).	[A] CELINE FONG
10	22 Dec 2021 16:45	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	23 Dec 2021 09:49	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	23 Dec 2021 09:49	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	23 Dec 2021 09:49	Clm Dtl Modified	JPJ Reg. Date: -> 2019/05/14.	[A] Elaine Kuan Hwa Meen
14	23 Dec 2021 09:49	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	23 Dec 2021 11:09	Clm Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
16	23 Dec 2021 16:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/12/31	[A] SHIAU CHAN

AUDIT TRAIL

No.	On	Audit	Remarks	By
17	23 Dec 2021 16:55	Adj Mandate Request	Cur.Req:57274.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	23 Dec 2021 17:30	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/31. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after re	[I] Lim, Kok-Chong
19	23 Dec 2021 17:30	Adj Mandate Set	Approved:45715.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong
20	15 Feb 2022 09:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/12/31	[A] SHIAU CHAN
21	15 Feb 2022 09:17	Adj Mandate Request	Cur.Req:61394.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. (Based on Margin for Repair (New for Old Value) KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	15 Feb 2022 11:22	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2021/12/31. Mandate Remarks:	[I] Lim, Kok-Chong
23	15 Feb 2022 11:22	Adj Mandate Set	Approved:55119.00:	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

[23/12/2021 13:50] SHIAU CHAN:
PENDING FOR REPAIR COST FROM REPAIRER.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2751358	23 Dec 2021 09:49:51	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SML3007U		11.00