

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1028/2021/JT
DATE : 20-Dec-21
WIP : 59492

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS YEO MEILING (YANG MEILING)
ADDRESS : BLK 475 UPPER SERANGOON CRESCENT
#03-525
SINGAPORE 532475
TELEPHONE : HP +65 81188800
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900098198-02
VEHICLE NO : **SML 3007 U**
MODEL CODE : AUI A3 SB 1.0 TFSI
MODEL YEAR : 14/5/2019
ENGINE NO : CHZ C29259
CHASSIS NO : WAUZZZ8V3KA065209
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Dec-21
PLACE OF ACCIDENT : GUILLEMARD ROAD TURNING
TO GUILLEMARD CRES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3007 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	✓
2	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$	800.00	✓
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE REPSPRAY OF LHS FRONT DOOR.	S/N \$	280.00	✓
4	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00 280.00	✓
5	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00 300.00	✓
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$	400.00	✓
SUB TOTAL LABOUR CHARGES		:	\$ 2,710.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3007 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00 150 ✓	
8	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW STEERING AIRBAG, SLIP RING. TRANSFER OLD FITTING. RENEW SEAT BELTS AND CONTROL UNIT, ROOF LINING, BOTH CURTAIN AIR BAGS AND LHS SEAT AIRBAG.	S/N \$	3,200.00 ✓	
9	TO RENEW LHS FRONT LEATHER SEAT CUSHION ASSY.	S/N \$	600.00 ✓	
10	TO REMOVE AND RENEW LHS REAR SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00 ✓	
11	TO SETUP THE CAR ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00 ✓	
12	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRYAS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY.	S/N \$	1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		:	\$ 10,200.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3007 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	✓
14	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL WITH LHS B-PILLAR, LHS REAR INNER WHEEL HOUSING AND CONNECTIONG PLATE AND LHS SILL PANEL REINFORCEMENT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 11,000.00	5500 4000 4500
15	✓ TO REPRAY REAR BUMPER, LHS FRONT DOOR, ✓ LHS REAR DOOR, ✓ DOOR HANDLES, ✓ HINGES, LHS REAR FENDER, LHS REAR INNER WHEEL HOUSING AND LHS REAR CONNECTIING PLATE, LHS SILL PANEL, ✓ FOOR ENTRANCE, ✓ ROOF CHANNEL AND REAR END PANELIING.	\$ 8,500.00	4400. 8x550 = 4400 ✓
16	TO RENEW LH REAR RIM. TO CARRY OUT PRE-REPAIR WHEEL ALIGNMENT CHECK AND POST- REPAIR WHEEL ALIGNMENT CHECK.	S/N \$ 520.00	320 ✓
17	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X.
18	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 34,994.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Regr</i>	1	\$ 2,070.00	X
2	REAR BUMPER FIXING PARTS <i>Aben</i>	1	\$ 193.00	X
3	REAR BUMPER LOCKING MECHANISM - LH / RH <i>M m</i>	2	\$ 28.00	X
4	REAR BUMPER ADAPTER - LH <i>Aben</i>	1	\$ 38.00	X
5	REAR BUMPER SPOILER <i>Aben</i>	1	\$ 237.00	X
6	REAR LIGHT REFLECTOR - LH <i>Aben</i>	1	\$ 30.00	X
7	TAIL LIGHT - LH <i>Aben</i>	1	\$ 877.00	X
8	REAR BUMPER GUIDE SECTION - LH <i>new cracked</i>	1	\$ 67.00	X 52.96 ✓
9	REAR FENDER - LH <i>Distorted</i>	1	\$ 3,192.00	✓ 2553.60
10	REAR WINDSCREEN <i>Aben</i>	1	\$ 814.00	X
11	REAR QUART GLASS - LH <i>Aben</i>	1	\$ 292.00	✓ 233.60
12	REAR SIDE WINDOW TRIM STRIP - LH <i>Aben</i>	1	\$ 261.00	✓ 208.80
13	WINDSCREEN PRIMER <i>Aben</i>	2	\$ 40.00	✓ 31.52
14	REAR WHEEL HOUSING LINER - LH ? NN	1	\$ 619.00	? X
15	REAR SIDE MEMBER - LH OUTER ? NN	1	\$ 396.00	? X
16	REAR DOOR - LH <i>Distorted</i>	1	\$ 2,767.00	✓ 2213.60
17	REAR DOOR OUTER SEAL - LH <i>Aben</i>	1	\$ 161.00	✓ 128.40
18	BONDING AGENT ? NN	1	\$ 49.00	? X
19	CLEANING SOLUTION ? NN	1	\$ 68.00	? X
20	APPLICATOR ? NN	1	\$ 8.00	? X
SUB TOTAL SPARE PARTS		:	\$ 12,207.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR ATTACHEMENT PARTS <i>Not m</i>	1	\$ 129.00	X	
22	REAR DOOR CATCH - LH <i>re ? DM</i>	1	\$ 94.00	? <i>74.80 ✓</i>	
23	REAR DOOR HINGE UPPER - LH <i>Best</i>	1	\$ 44.00	✓ <i>34.48</i>	
24	REAR DOOR HINGES HALVE LH - UPPER <i>Best</i>	1	\$ 46.00	✓ <i>36.24</i>	
25	REAR DOOR HINGE LOWER - INNER / OUTER <i>Best</i>	2	\$ 95.00	✓ <i>75.44</i>	
26	REAR DOOR SEAL INNER - LH <i>re n</i>	1	\$ 191.00	X	
27	REAR DOOR HANDLE - LH <i>re n</i>	1	\$ 374.00	X	
28	REAR DOOR HOUSING - LH <i>re m</i>	1	\$ 52.00	X	
29	REAR DOOR HANDLE MOUNTING BAR - LH <i>re n</i>	1	\$ 162.00	X	
30	REAR DOOR BOWDEN CABLE <i>P NN</i>	1	\$ 52.00	? X	
31	REAR WINDOW - LH <i>re m DM</i>	1	\$ 268.00	X <i>214.40 ✓</i>	
32	REAR WINDOW REGULATOR - LH <i>? NN</i>	1	\$ 271.00	? X	
33	REAR DOOR CONTROL UNIT - LH <i>re n</i>	1	\$ 484.00	X	
34	REAR DOOR BOARD - LH <i>? DM</i>	1	\$ 1,651.00	? <i>1320.80 ✓</i>	
35	REAR DOOR WIRING SET <i>re n</i>	1	\$ 334.00	X	
36	REAR WINDOW SLOT SEAL TRIM STRIP - LH <i>re m</i>	1	\$ 270.00	X	
37	ROOF CHROME MOLDING - LH <i>? NN</i>	1	\$ 591.00	? X	
38	REAR TRIM COVER - LH <i>re n</i>	1	\$ 74.00	X <i>58.64 ✓</i>	
39	<i>Per</i> FRONT WINDOW GUIDE - LH <i>re n</i>	1	\$ 420.00	? X	
40	<i>Per</i> FRONT WINDOW APERTURE SEAL INNER - LH <i>re n</i>	1	\$ 113.00	? X	
SUB TOTAL SPARE PARTS		:	\$ 5,715.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	REAR DOOR B-PILLAR TRIM - LH OUTER <i>He n</i>	1	\$ 117.00	X	
42	REAR DOOR WINDOW - LH <i>He n</i>	1	\$ 211.00	X	
43	FRONT B-PILLAR TRIM LH OUTER <i>?</i>	1	\$ 105.00	<i>?</i> X	
44	FRONT WINDOW SLOT SEAL TRIM STRIP - LH <i>He n</i>	1	\$ 270.00	<i>?</i> 215.60 ✓	
45	REAR WHEEL SPOILER - LH <i>He n</i>	1	\$ 35.00	X	
46	REAR WHEEL HOUSING LINER - LH <i>?</i> DM	1	\$ 240.00	<i>?</i> 191.60 ✓	
47	ALUMINIUM RIM - LH REAR <i>LA</i>	1	\$ 1,166.00	✓ 932.80	
48	REAR AXLE BEAM <i>?</i> DM	1	\$ 1,903.00	<i>?</i> 1522.40 ✓	
49	REAR AXLE BEARING BRACKET - LH <i>?</i> NN	1	\$ 201.00	<i>?</i> X	
50	REAR AXLE BRACKET COVER - LH <i>?</i> NN	1	\$ 8.00	<i>?</i> X	
51	REAR AXLE STUB <i>?</i> DM	1	\$ 280.00	<i>?</i> 223.60 ✓	
52	REAR WHEEL BEARING ASSEMBLY - LH <i>?</i> DM	1	\$ 469.00	<i>?</i> 374.80 ✓	
53	REAR GAS ABSORBER - LH <i>?</i> DM	1	\$ 244.00	<i>?</i> 195.20 ✓	
54	DUST SHEILD - PROTECTIVE PIPE <i>?</i> DM	1	\$ 62.00	<i>?</i> 49.28 ✓	
55	GAS ABSORBER BEARING <i>?</i> DM	1	\$ 70.00	<i>?</i> 55.60 ✓	
56	SPPED SENSOR <i>?</i> NN	1	\$ 186.00	<i>?</i> X	
57	REAR WHEEL SENSOR LEVEL - LH <i>?</i> NN	1	\$ 587.00	<i>?</i> X	
58	ARIBAG UNIT - LH / RH <i>Activated</i>	2	\$ 3,726.00	✓ 2980.80	
59	AIRBAG UNIT STEERING WHEEL <i>He n</i>	1	\$ 3,421.00	X	
60	FRONT SIDE AIRBAG UNIT - LH <i>Activated</i>	1	\$ 1,520.00	✓ 1216.	
SUB TOTAL SPARE PARTS		:	\$ 14,821.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIRBAG CRASH SENSOR <i>new</i>	1	TBC	✓ 311.20
62	AIRBAG CONTROL UNIT <i>new</i>	1	\$ 1,647.00	✓ 1317.60
63	THREEE-POINT SEAT BELT - LH / RH <i>Advised</i>	2	\$ 2,206.00	✓ 1764.80
64	SEAT BELT HEIGHT ADJUSTER - LH / RH <i>new</i>	2	\$ 383.00	✓ 306.40 ✓
65	STEERING WHEEL <i>new</i>	1	\$ 2,374.00	✓
66	ROOF LINER <i>crumpled.</i>	1	\$ 1,983.00	✓ 1586.40
67	SEAT LEATHER COVER <i>tear</i>	1	\$ 2,195.00	✓ 1756
68	FRONT, GRAB HANDLE - LH / RH ? DM	2	\$ 283.00	? 226.40 ✓
69	REAR, GRAB HANDLE - LH / RH ? DM	2	\$ 284.00	? 226.40 ✓
70	A-PILLAR TRIM - UPPER LH / RH ? DM	2	\$ 322.00	? 274 ✓
71	B-PILLAR TRIM - UPPER LH / RH ? NN	2	\$ 434.00	? X
72	C-PILLAR TRIM - UPPER LH / RH ? DM	2	\$ 182.00	? 145.28 ✓
73	D-PILLAR TRIM - UPPER LH / RH ? DM	2	\$ 322.00	? 256.80 ✓
74	WHEEL HOUSING TRIM ? DM	1	\$ 106.00	? 84.80 ✓
75	B-PILLAR TRIM - LOWER LH ? DM	1	\$ 116.00	? 92.80 ✓
76	B-PILLAR TRIM - LH ? NN	1	\$ 23.00	? X
77	ARYLIC SEALANT <i>new</i>	S/N	\$ 180.00	✓
78	CAVITY WAX <i>new</i>	S/N	\$ 140.00	✓
79	STONE CHIP <i>new</i>	S/N	\$ 180.00	✓
80	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	✓
81	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$ 200.00	X
82	1/4 GLASS SEALANT <i>new</i>	S/N	\$ 100.00	✓
83	LHS REAR TYRE <i>new</i>	1	TBC	X
84	SUNDRIES NEC	S/N	\$ 800.00	✓ 239.84 ✓
TOTAL SPARE PARTS		:	\$ 47,483.00	
TOTAL LABOUR CHARGES		:	\$ 34,994.00	
GRAND TOTAL		:	\$ 82,477.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

Xiao Chen

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No


PA/OD/1028/2021/JT
17-Jan-22
Tony
1 of 1
SML 3007 U
AUI A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>labour</u>			
1	TO RESPRAY LHS B-PILLAR	\$ 550.00	✓
<u>Parts</u>			
1	LOCKING MECHANISM - FLAT CONTACT HOUSING <i>Damaged</i>	\$ 42.00	✓ 33.36
2	DOOR WIRING HOUSING COVER <i>Crushed</i>	\$ 48.00	✓ 38.16
3	REAR DOOR LOCK - LH <i>Damaged</i>	\$ 630.00	✓ 503.60
4	TAIL LAMP ADJUSTMENT ELEMENT <i>Damaged</i>	\$ 45.00	✓ 35.36
5	CHILD SEAT STICKER <i>Nec</i>	\$ 27.00	✓ 21.28
6	FRONT DOOR WINDOW GUIDE - LH <i>Rebound</i>	\$ 467.00	✓ 373.60
7	IN-CAR-CAMERA SET <i>Snapped.</i> S/N	\$ 900.00	✓ 100 ✓
		<i>Pricing ??</i>	
	GRAND TOTAL	\$ 2,709.00	

For Premium Automobiles Pte Ltd

Adrian L
08/01/22

[Signature]



Authorised Signature

Additional 5 Days of repair
for spray painting to B Pillar
and repair to wheel house and
undercarriage replacement.

[Signature]

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *21/12/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 21 Days inclusive of undercarriage.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT