

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Xiao Chen

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No


PA/OD/1028/2021/JT
17-Jan-22
Tony
1 of 1
SML 3007 U
AUI A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>labour</u>			
1	TO RESPRAY LHS B-PILLAR	\$ 550.00	✓
<u>Parts</u>			
1	LOCKING MECHANISM - FLAT CONTACT HOUSING <i>Damaged</i>	\$ 42.00	✓
2	DOOR WIRING HOUSING COVER <i>crushed</i>	\$ 48.00	✓
3	REAR DOOR LOCK - LH <i>Damaged</i>	\$ 630.00	✓
4	TAIL LAMP ADJUSTMENT ELEMENT <i>Damaged</i>	\$ 45.00	✓
5	CHILD SEAT STICKER <i>Nec</i>	\$ 27.00	✓
6	FRONT DOOR WINDOW GUIDE - LH <i>Rebond</i>	\$ 467.00	✓
7	IN-CAR-CAMERA SET <i>Snapped.</i> S/N	\$ 900.00	??
		<i>Pricing ..</i>	
	GRAND TOTAL	\$ 2,709.00	

For Premium Automobiles Pte Ltd

Adrian L
08/02/22

[Signature]



Authorised Signature

Additional 5 Days of repairs
for spray painting to B pillar
and repairs to wheel house and
undercarriage replacement.

[Signature]

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3007 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	
14	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL WITH LHS B PILLAR, LHS REAR INNER WHEEL HOUSING AND CONNECTION PLATE AND LHS SILL PANEL REINFORCEMENT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 11,000.00 4500 ✓	11 x 500 = \$ 5,500 S.L.S.
15	TO REPAIR REAR BUMPER, LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, HINGES, LHS REAR FENDER, LHS REAR INNER WHEEL HOUSING AND LHS REAR CONNECTION PLATE, LHS SILL PANEL, FOOT ENTRANCE, ROOF CHANNEL AND REAR END PANELING.	\$ 8,500.00 4400 ✓	8 x 550 = 4400
16	TO RENEW LH REAR RIM. TO CARRY OUT PRE-REPAIR WHEEL ALIGNMENT CHECK AND POST-REPAIR WHEEL ALIGNMENT CHECK.	S/N \$ 520.00 320 ✓	
17	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	
18	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		\$ 34,994.00	

Car-in 5/1/22

wip: 59492

PREMIUM AUTOMOBILES

Kiam/Hong



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG-Admin

- 21 days.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	\$ 2,070.00	X
2	REAR BUMPER FIXING PARTS <i>Abc m</i>	1	\$ 193.00	X
3	REAR BUMPER LOCKING MECHANISM - LH / RH <i>mm</i>	2	\$ 28.00	X
4	REAR BUMPER ADAPTER - LH <i>mm</i>	1	\$ 38.00	X
5	REAR BUMPER SPOILER <i>mm</i>	1	\$ 237.00	X
6	REAR LIGHT REFLECTOR - LH <i>mm</i>	1	\$ 30.00	X
7	TAIL LIGHT - LH <i>mm</i>	1	\$ 877.00	X
8	REAR BUMPER GUIDE SECTION - LH <i>cracked.</i>	1	\$ 67.00	X <i>sgs.</i>
9	REAR FENDER - LH <i>Distorted</i>	1	\$ 3,192.00	✓
10	REAR WINDSCREEN <i>mm</i>	1	\$ 814.00	X
11	REAR QUART GLASS - LH <i>mm</i>	1	\$ 292.00	✓
12	REAR SIDE WINDOW TRIM STRIP - LH <i>mm</i>	1	\$ 261.00	✓
13	WINDSCREEN PRIMER <i>mm</i>	2	\$ 40.00	✓
14	REAR WHEEL HOUSING LINER - LH ?	1	\$ 619.00	?
15	REAR SIDE MEMBER - LH OUTER ?	1	\$ 396.00	?
16	REAR DOOR - LH <i>Distorted</i>	1	\$ 2,767.00	✓
17	REAR DOOR OUTER SEAL - LH <i>mm</i>	1	\$ 161.00	✓
18	BONDING AGENT ?	1	\$ 49.00	?
19	CLEANING SOLUTION ?	1	\$ 68.00	?
20	APPLICATOR ?	1	\$ 8.00	?

SUB TOTAL SPARE PARTS

: \$ 12,207.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

8KO 839 723 X 2

8VO 805 673 X 2

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR ATTACHEMENT PARTS <i>Not m</i>	1	\$ 129.00	<i>x</i>
22	REAR DOOR CATCH - LH <i>Not Damaged</i>	1	\$ 94.00	<i>2</i> <i>sls</i>
23	REAR DOOR HINGE UPPER - LH <i>Best</i>	1	\$ 44.00	<i>✓</i>
24	REAR DOOR HINGES HALVE LH - UPPER <i>Best</i>	1	\$ 46.00	<i>✓</i>
25	REAR DOOR HINGE LOWER - INNER / OUTER <i>Best</i>	2	\$ 95.00	<i>✓</i>
26	REAR DOOR SEAL INNER - LH <i>Not m</i>	1	\$ 191.00	<i>x</i>
27	REAR DOOR HANDLE - LH <i>Not m</i>	1	\$ 374.00	<i>x</i>
28	REAR DOOR HOUSING - LH <i>Not m</i>	1	\$ 52.00	<i>x</i>
29	REAR DOOR HANDLE MOUNTING BAR - LH <i>Not m</i>	1	\$ 162.00	<i>x</i>
30	REAR DOOR BOWDEN CABLE <i>P</i>	1	\$ 52.00	<i>?</i>
31	REAR WINDOW - LH <i>Not m</i>	1	\$ 268.00	<i>x</i>
32	REAR WINDOW REGULATOR - LH <i>Damaged</i>	1	\$ 271.00	<i>2</i> <i>sls</i>
33	REAR DOOR CONTROL UNIT - LH <i>Not m</i>	1	\$ 484.00	<i>x</i>
34	REAR DOOR BOARD - LH <i>Deformed</i>	1	\$ 1,651.00	<i>2</i> <i>sls</i>
35	REAR DOOR WIRING SET <i>Not m</i>	1	\$ 334.00	<i>x</i>
36	REAR WINDOW SLOT SEAL TRIM STRIP - LH <i>Not m</i>	1	\$ 270.00	<i>x</i>
37	ROOF CHROME MOLDING - LH <i>?</i>	1	\$ 591.00	<i>?</i>
38	REAR TRIM COVER - LH <i>ut</i>	1	\$ 74.00	<i>x</i> <i>sls</i>
39	FRONT WINDOW GUIDE - LH <i>Not m</i>	1	\$ 420.00	<i>?</i>
40	FRONT WINDOW APERTURE SEAL INNER - LH <i>Not m</i>	1	\$ 113.00	<i>?</i>
SUB TOTAL SPARE PARTS		:	\$ 5,715.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	REAR DOOR B-PILLAR TRIM - LH OUTER <i>new</i>	1	\$ 117.00	X	
42	REAR DOOR WINDOW - LH <i>new</i>	1	\$ 211.00	X	
43	FRONT B-PILLAR TRIM LH OUTER ?	1	\$ 105.00	X ?	
44	FRONT WINDOW SLOT SEAL TRIM STRIP - LH <i>Deformed</i>	1	\$ 270.00	✓	<i>sls</i>
45	REAR WHEEL SPOILER - LH <i>new</i>	1	\$ 35.00	X	
46	REAR WHEEL HOUSING LINER - LH <i>torn</i>	1	\$ 240.00	✓	<i>sls</i>
47	ALUMINIUM RIM - LH REAR <i>lt</i>	1	\$ 1,166.00	✓	
48	REAR AXLE BEAM <i>Bent</i>	1	\$ 1,903.00	✓	<i>sls</i>
49	REAR AXLE BEARING BRACKET - LH ?	1	\$ 201.00	?	
50	REAR AXLE BRACKET COVER - LH ?	1	\$ 8.00	?	
51	REAR AXLE STUB <i>Damd</i>	1	\$ 280.00	?	
52	REAR WHEEL BEARING ASSEMBLY - LH <i>Damd</i>	1	\$ 469.00	?	
53	REAR GAS ABSORBER - LH <i>Bent</i>	1	\$ 244.00	?	
54	DUST SHIELD - PROTECTIVE PIPE <i>Damd</i>	1	\$ 62.00	?	
55	GAS ABSORBER BEARING <i>Damd</i>	1	\$ 70.00	?	
56	SPPED SENSOR ?	1	\$ 186.00	?	
57	REAR WHEEL SENSOR LEVEL - LH ?	1	\$ 587.00	?	
58	AIRBAG UNIT - LH / RH <i>Activated</i>	2	\$ 3,726.00	✓	
59	AIRBAG UNIT STEERING WHEEL <i>new</i>	1	\$ 3,421.00	X	
60	FRONT SIDE AIRBAG UNIT - LH <i>Activated</i>	1	\$ 1,520.00	✓	
SUB TOTAL SPARE PARTS		:	\$ 14,821.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3007 U

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIRBAG CRASH SENSOR <i>neu</i>	1	TBC	✓
62	AIRBAG CONTROL UNIT <i>neu</i>	1	\$ 1,647.00	✓
63	THREE-POINT SEAT BELT - LH / RH <i>A. Admitted</i>	2	\$ 2,206.00	✓
64	SEAT BELT HEIGHT ADJUSTER - LH / RH <i>neu</i>	2	\$ 383.00	✓
65	STEERING WHEEL <i>neu</i>	1	\$ 2,374.00	✓
66	ROOF LINER <i>crumpled.</i>	1	\$ 1,983.00	✓
67	SEAT LEATHER COVER <i>to in</i>	1	\$ 2,195.00	✓
68	FRONT, GRAB HANDLE - LH / RH <i>?</i>	2	\$ 283.00	?
69	REAR, GRAB HANDLE - LH / RH <i>?</i>	2	\$ 284.00	?
70	A-PILLAR TRIM - UPPER LH / RH <i>?</i>	2	\$ 322.00	?
71	B-PILLAR TRIM - UPPER LH / RH <i>?</i>	2	\$ 434.00	?
72	C-PILLAR TRIM - UPPER LH / RH <i>?</i>	2	\$ 182.00	?
73	D-PILLAR TRIM - UPPER LH / RH <i>?</i>	2	\$ 322.00	?
74	WHEEL HOUSING TRIM <i>?</i>	1	\$ 106.00	?
75	B-PILLAR TRIM - LOWER LH <i>?</i>	1	\$ 116.00	?
76	B-PILLAR TRIM - LH <i>?</i>	1	\$ 23.00	?
77	ARYLIC SEALANT <i>?</i>	S/N	\$ 180.00	✓
78	CAVITY WAX <i>neu</i>	S/N	\$ 140.00	✓
79	STONE CHIP <i>neu</i>	S/N	\$ 180.00	✓
80	METAL FILLER POWDER <i>neu</i>	S/N	\$ 280.00	✓
81	REAR WINDSCREEN SEALANT <i>neu</i>	S/N	\$ 200.00	✓
82	1/4 GLASS SEALANT <i>neu</i>	S/N	\$ 100.00	✓
83	LHS REAR TYRE <i>neu</i>	1	TBC	✓
84	SUNDRIES	S/N	\$ 800.00	
TOTAL SPARE PARTS			\$ 47,483.00	
TOTAL LABOUR CHARGES			\$ 34,994.00	
GRAND TOTAL			\$ 82,477.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.