

TP 1st Cap.  
Ashes

SMA 4621Y 2018 June.

Honda Shuttle 1496cc

GK81202011

|                                       |               |                             |
|---------------------------------------|---------------|-----------------------------|
| Front Number Plate                    | } NP<br>over  | 30(SN) X                    |
| Front Number Plate Holder             |               | 30(SN) X                    |
| Front Bumper Deformed                 |               | 1050.50 <del>862.50</del>   |
| Front Bumper Clips. New               |               | 30(SN) ✓                    |
| Front Bumper Side Holder x 02         | NP<br>over    | 35x2=70 X                   |
| Front Bumper Reinforcement. Dented    |               | <del>420.50</del> 397.20    |
| Front Bumper lower Grille. NP<br>over |               | 152.40. X                   |
| Front Grille Crushed                  |               | 363.30 ✓                    |
| Front Grille Clips. New               |               | 20(SN) ✓                    |
| Front Grille Chrome Moulding          | NP<br>over    | 292.60 ✓                    |
| Front Grille Logo. New                |               | 48.20 ✓                     |
| Bonnet Dented.                        |               | 1080.10 ✓                   |
| Bonnet Lock                           | } NP<br>over  | 135.20 X                    |
| Bonnet Weatherstripe                  |               | 75.10. X                    |
| Headlamp x 02                         | LH<br>Crushed | 2128.70<br>2128.7x2=4257.40 |

SMA4621Y.

Panel Beating

~~800~~ 400

Spray Painting

~~800~~ 400

Wiring

~~50~~ 30

Mat: 5360.60

Labour: 830

Lin 20%: 4288.48

Mat: 5168.48

S.N: 50

L/S: 4.8k.

04 Days.

4.1k

04 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: