

Lion City Rentals Pte Ltd
No 4 Jln Besut Singapore (619557)

Ms: China Taiping Insurance (Singapore) Pte Ltd
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLG7507E

CHASSIS NO : NRE1610021906

MAKE / MODEL : Toyota Corolla Axio Hybrid 1.5 G

DATE OF ACCIDENT: 11/12/2021

YOUR INSURED VEHICLE NUMBER : SMP6973P

AGE: 129620 km

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front bumper <i>de✓</i>	1PC	\$ 850.00	\$ 850.00 <i>552.25</i>
2	Front bumper reinforcement <i>X 11</i>	1pc	\$ 289.00	\$ 289.00 <i>X</i>
3	Front bumper sponge <i>X 11</i>	1PC	\$ 60.00	\$ 60.00 <i>X</i>
4	F/R headlamp assy <i>bro✓</i>	1PC	\$ 950.00	\$ 950.00 <i>700</i>
5	Front bonnet <i>bt✓</i>	1PC	\$ 1,200.50	\$ 1,200.50 <i>809.70</i>
6	Front bonnet insulator <i>X 11</i>	1PC	\$ 260.40	\$ 260.40 <i>X</i>
7	Front support panel <i>X 11</i>	1PC	\$ 895.50	\$ 895.50 <i>X</i>
LIST TOTAL S\$:				\$ 4,505.40
25% DISCOUNT S\$:				\$ 1,126.35
<i>2737.95</i>				\$ 3,379.05

*8 F/R fender *bro✓* - 676*

SPECIAL NETT

- 1 Front bumper clips *111✓*

1 SET *30* \$ ~~80.00~~ *30*
\$ 80.00

LABOUR CHARGES

To labour charge for removing front bonnet, support panel, front bumper assy out to facilitate replacement of damaged parts

- 1 To respray front bonnet, support panel and front bumper

400 600
\$ 900.00 } *1200*
400 600
\$ 900.00

LABOUR TOTAL S\$:

\$	1,800.00
TOTAL S\$:	\$ 5,259.05
7% GST	\$ 368.13
GRAND TOTAL S\$:	\$ 5,627.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signed: _____

Date: _____

2053.46

30.00

1200.00

3283.46

20%

2626.77

45-\$2,600

Rasul
Hp 90010068
4 day
L/S
22/12/21 @ 1600
Resy after repair

Lump Sum / I.B.I: (\$

Techn. Invs (\$

Others