


Date: 21/12/2021
Claim Type: TP
VRN: SLU6581Y



✓
✓
x
✓
+
x
+
+
+
+
+
+
285.
-
-
✓
880.
49.
x.
✓
✓
x.
295.
✓
x
x.
✓
P
+.
✓ 185
✓ 315
x

Repair Estimate

31	Rear fender n/s <i>Repair</i>	1	\$ 898.00	\$ 898.00	<i>x</i>
32	End panel <i>Repair</i>	1	\$ 568.00	\$ 568.00	<i>x</i>
			Subtotal	\$ 9,743.00	
			List discount	20.00%	
			Total	\$ 7,794.40	

4897
3917.60

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear fender arch garnish clips n/s <i>new</i>	8	\$ 5.50	\$ 44.00	<i>20</i>
2	Rear bumper lower cowlings clips <i>new</i>	12	\$ 5.50	\$ 66.00	<i>30</i>
3	Reverse sensor <i>3AP</i>	1	\$ 280.00	\$ 280.00	<i>x</i>
4	Reverse sensor holder <i>new</i>	2	\$ 32.00	\$ 64.00	<i>x</i>
5	Tailgate trimboard clips <i>new</i>	10	\$ 5.50	\$ 55.00	<i>30</i>
6	Tailgate windscreen sealant <i>new</i>	1	\$ 100.00	\$ 100.00	<i>60</i>
7	End panel top garnish clips <i>new</i>	6	\$ 5.50	\$ 33.00	<i>20</i>
8	Taillamp panel sealant n/s <i>new</i>	1	\$ 100.00	\$ 100.00	<i>x</i>
9	Rear bumper clips <i>new</i>	10	\$ 5.50	\$ 55.00	<i>30</i>
10	Rear bumper side cover clips <i>new</i>	12	\$ 5.50	\$ 66.00	<i>10</i>
11	Rear fender inner trim board clips n/s <i>new</i>	8	\$ 5.50	\$ 44.00	<i>30</i>
12	Sundries <i>new</i>	1	\$ 50.00	\$ 50.00	<i>x</i>
			Total	\$ 957.00	

230

Labour

No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00	<i>9.00</i>
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	<i>30</i>
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	<i>20</i>
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00	<i>20</i>
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	<i>120</i>
6	To rust proof all affected portions after repair.	0.5	\$ 100.00	<i>80</i>
Total labour			\$ 3,000.00	

Estimate Grand Total \$ **11,751.40**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6157.60

w/s: 4.9K

6 days

2010