

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013008/GNY3Q2**Date:** 14/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00056912100

Claimant Vehicle No : SKL212L **Insured Vehicle No :** SLX7732G

Date of Loss: 19/09/2021 Nature of Claim: TP Claim No: SNM21D205313/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL212L**

Make & Model: PORSCHE CAYMAN, 2.7 (A) Engine No: A02962

Reg. Date: 04/03/2010 (Man. Year: 2010) Chassis No: WP0ZZZ98ZAS700464

Colour: White Odometer: 0 km

Engine Capacity: 2893 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R17 Rear Tyre Size: 235/50 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	172,486.95	125,951.90	46,535.05	26.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,120.00	6,740.00	10,380.00	60.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	189,606.95	132,691.90	56,915.05	30.02
Approved Total (Overridden) (S\$)		106,000.00		
(S\$)	189,606.95	106,000.00	83,606.95	44.09
+ GST 7.00/7.00% (S\$)	13,272.49	7,420.00	5,852.49	44.09
Nett Amount (S\$)	202,879.44	113,420.00	89,459.44	44.09

INSPECTION

Date of Assignment: 22/12/2021

Date Inspected: 23/12/2021 Inspected At: Vin's Auto Pte Ltd (Vin's Auto)
Sin Ming AutoCity,, 160 Sin Ming Drive #03-03
Singapore 575722

Estimated Period of Repair: 22.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2022)
Parts:	M1-COUPE	PORSCHE CAYMAN 2.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL212L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT RH HEADLAMP	Missing	2,350.00 FL	*2,350.00 FL
2	1	*FRONT LH HEADLAMP	Missing	2,350.00 FL	*2,350.00 FL
3	1	*FRONT RH HEADLAMP ECU	Missing	599.00 FL	*599.00 FL
4	1	*FRONT LH HEADLAMP ECU	Missing	599.00 FL	*599.00 FL
5	1	*FRONT RH HEADLAMP HID BULB	Missing	253.00 FL	*253.00 FL
6	1	*FRONT LH HEADLAMP HID BULB	Missing	253.00 FL	*253.00 FL
7	1	*FRONT RH HEADLAMP BRACKET	Missing	390.00 FL	*390.00 FL
8	1	*FRONT LH HEADLAMP BRACKET	Missing	390.00 FL	*390.00 FL
9	1	*FRONT BUMPER	Distorted	1,980.00 FL	*1,980.00 FL
10	1	*FRONT BUMPER RH NOZZLE GUN	Missing	260.00 FL	*260.00 FL
11	1	*FRONT BUMPER LH NOZZLE GUN	Missing	260.00 FL	*260.00 FL
12	1	*FRONT BUMPER RH NOZZLE GUN BRACKET	Missing	65.00 FL	*65.00 FL
13	1	*FRONT BUMPER LH NOZZLE GUN BRACKET	Missing	65.00 FL	*65.00 FL
14	1	*FRONT BUMPER TOWING COVER	Not Necessary	70.00 FL	*- FL
15	1	*FRONT BUMPER CENTRE LOWER GRILLE	Missing	380.00 FL	*380.00 FL
16	1	*FRONT BUMPER RH DAY LIGHT	Missing	690.00 FL	*690.00 FL
17	1	*FRONT BUMPER LH DAY LIGHT	Missing	690.00 FL	*690.00 FL
18	1	*FRONT BUMPER RH SIDE GRILLE COVER	Missing	155.00 FL	*155.00 FL
19	1	*FRONT BUMPER LH SIDE GRILLE COVER	Missing	155.00 FL	*155.00 FL
20	1	*FRONT BUMPER RH SIDE RETAINER -LONG	Missing	85.00 FL	*85.00 FL
21	1	*FRONT BUMPER LH SIDE RETAINER -LONG	Missing	85.00 FL	*85.00 FL
22	1	*FRONT BUMPER RH SIDE RETAINER -SHORT	Missing	65.00 FL	*65.00 FL
23	1	*FRONT BUMPER LH SIDE RETAINER -SHORT	Missing	65.00 FL	*65.00 FL
24	1	*FRONT BUMPER REINFORCEMENT	Bent	860.00 FL	*860.00 FL
25	1	*FRONT BUMPER REINFORCEMENT RH BRACKET	Bent	240.00 FL	*240.00 FL
26	1	*FRONT BUMPER REINFORCEMENT LH BRACKET	Bent	240.00 FL	*240.00 FL
27	10	*FRONT BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
28	1	*LUGGAGE COMPARTMENT ASSY	Repair	720.00 FL	*- FL
29	1	*LUGGAGE COMPARTMENT FRONT SUPPORT	Not Necessary	440.00 FL	*- FL
30	1	*LUGGAGE COMPARTMENT FRONT PANEL	Not Necessary	690.00 FL	*- FL
31	1	*RH HORN	Missing	190.00 FL	*190.00 FL
32	1	*LH HORN	Missing	190.00 FL	*190.00 FL
33	1	*RH HORN BRACKET	Missing	95.00 FL	*95.00 FL
34	1	*LH HORN BRACKET	Missing	95.00 FL	*95.00 FL
35	1	*RH AIRCON CONDENSER	Bent	960.00 FL	*960.00 FL
36	1	*LH AIRCON CONDENSER	Bent	960.00 FL	*960.00 FL
37	1	*RH AIRCON CONDENSER PIPE	Bent	620.00 FL	*620.00 FL
38	1	*LH AIRCON CONDENSER PIPE	Bent	620.00 FL	*620.00 FL
39	1	*RH AIRCON CONDENSER AIR DUCT	Cracked	65.00 FL	*65.00 FL
40	1	*LH AIRCON CONDENSER AIR DUCT	Cracked	65.00 FL	*65.00 FL
41	1	*AIRCON TEMPERATURE SENSOR	Not Working	98.00 FL	*98.00 FL
42	1	*RH RADIATOR	Cracked	880.00 FL	*880.00 FL
43	1	*LH RADIATOR	Cracked	880.00 FL	*880.00 FL
44	1	*RH RADIATOR TOP HOSE	Not Necessary	230.00 FL	*- FL
45	1	*LH RADIATOR TOP HOSE	Not Necessary	230.00 FL	*- FL
46	1	*RH RADIATOR LOWER HOSE	Not Necessary	260.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*LH RADIATOR LOWER HOSE	Not Necessary	260.00 FL	*- FL
48	1		*RH INTER COOLER	Not Necessary	940.00 FL	*- FL
49	1		*LH INTER COOLER	Not Necessary	940.00 FL	*- FL
50	1		*RH RADIATOR AIR DUCT	Distorted	78.00 FL	*78.00 FL
51	1		*LH RADIATOR AIR DUCT	Distorted	78.00 FL	*78.00 FL
52	1		*RH RADIATOR BRACKET	Not Necessary	40.00 FL	*- FL
53	1		*LH RADIATOR BRACKET	Not Necessary	40.00 FL	*- FL
54	1		*RH RADIATOR LOWER BRACKET	Bent	46.00 FL	*46.00 FL
55	1		*LH RADIATOR LOWER BRACKET	Bent	46.00 FL	*46.00 FL
56	1		*RH RADIATOR UNDER COVER	Missing	190.00 FL	*190.00 FL
57	1		*LH RADIATOR UNDER COVER	Missing	190.00 FL	*190.00 FL
58	1		*RH RADIATOR FAN MOTOR ASSY	Not Working	890.00 FL	*890.00 FL
59	1		*LH RADIATOR FAN MOTOR ASSY	Not Working	890.00 FL	*890.00 FL
60	1		*FRONT RH FENDER	Buckled	1,400.00 FL	*1,400.00 FL
61	1		*FRONT LH FENDER	Not Necessary	1,400.00 FL	*- FL
62	1		*FRONT RH FENDER INNER SHIELD -FRONT	Missing	250.00 FL	*250.00 FL
63	1		*FRONT LH FENDER INNER SHIELD -FRONT	Missing	250.00 FL	*250.00 FL
64	1		*FRONT RH FENDER INNER SHIELD -REAR	Missing	255.00 FL	*255.00 FL
65	1		*FRONT LH FENDER INNER SHIELD -REAR	Not Necessary	255.00 FL	*- FL
66	20		*FRONT FENDER INNER SHIELD CLIPS	Necessary	180.00 FL	*180.00 FL
67	1		*FRONT RH DOOR	Buckled	2,800.00 FL	*2,800.00 FL
68	1		*FRONT RH DOOR OUTER MOULDING	Not Necessary	190.00 FL	*- FL
69	1		*FRONT RH DOOR UPPER HINGE	Bent	155.00 FL	*155.00 FL
70	1		*FRONT RH DOOR LOWER HINGE	Bent	155.00 FL	*155.00 FL
71	1		*FRONT RH DOOR RUBBER	Necessary	270.00 FL	*270.00 FL
72	1		*FRONT RH DOOR INNER TRIMBOARD	Cracked	1,250.00 FL	*1,250.00 FL
73	1		*FRONT RH DOOR INNER LOCK	Cut	420.00 FL	*420.00 FL
74	1		*FRONT RH DOOR POWER WINDOW MOTOR	Not Working	520.00 FL	*520.00 FL
75	1		*FRONT RH DOOR POWER WINDOW GEAR	Bent	490.00 FL	*490.00 FL
76	1		*FRONT RH DOOR FRAME BODY RUBBER	Necessary	185.00 FL	*185.00 FL
77	1		*RH SIDE MIRROR ASSY	Distorted	1,080.00 FL	*1,080.00 FL
78	1		*RH SIDE MIRROR GLASS	Distorted	370.00 FL	*370.00 FL
79	1		*RH ROCKER PANEL	Buckled	1,320.00 FL	*1,320.00 FL
80	1		*FRONT LH DOOR	Bent	2,800.00 FL	*2,800.00 FL
81	1		*FRONT LH DOOR OUTER MOULDING	Not Necessary	190.00 FL	*- FL
82	1		*FRONT LH DOOR UPPER HINGE	Not Necessary	155.00 FL	*- FL
83	1		*FRONT LH DOOR LOWER HINGE	Not Necessary	155.00 FL	*- FL
84	1		*FRONT LH DOOR RUBBER	Necessary	270.00 FL	*270.00 FL
85	1		*FRONT LH DOOR INNER TRIMBOARD	Cracked	1,250.00 FL	*1,250.00 FL
86	1		*FRONT LH DOOR INNER LOCK	Cut	420.00 FL	*420.00 FL
87	1		*FRONT LH DOOR POWER WINDOW MOTOR	Not Working	520.00 FL	*520.00 FL
88	1		*FRONT LH DOOR POWER WINDOW GEAR	Bent	490.00 FL	*490.00 FL
89	1		*FRONT LH DOOR FRAME BODY RUBBER	Necessary	185.00 FL	*185.00 FL
90	1		*LH ROCKER PANEL	Buckled	1,320.00 FL	*1,320.00 FL
91	1		*REAR RH FENDER	Buckled	3,700.00 FL	*3,700.00 FL
92	1		*REAR LH FENDER	Buckled	3,700.00 FL	*3,700.00 FL
93	1		*REAR RH FENDER AIR VENT COVER	Deformed	140.00 FL	*140.00 FL
94	1		*REAR LH FENDER AIR VENT COVER	Missing	140.00 FL	*140.00 FL
95	1		*REAR RH FENDER INNER SHIELD -FRONT	Missing	165.00 FL	*165.00 FL
96	1		*REAR LH FENDER INNER SHIELD -FRONT	Missing	170.00 FL	*170.00 FL
97	1		*REAR RH FENDER INNER SHIELD -REAR	Missing	165.00 FL	*165.00 FL
98	1		*REAR LH FENDER INNER SHIELD -REAR	Missing	170.00 FL	*170.00 FL
99	1		*REAR RH FENDER INNER PANEL	Not Necessary	550.00 FL	*- FL
100	1		*REAR LH FENDER INNER PANEL	Not Necessary	550.00 FL	*- FL
101	20		*REAR FENDER INNER SHIELD CLIPS	Necessary	180.00 FL	*180.00 FL
102	1		*REAR RH FENDER STONE GUARD STICKER	Necessary	78.00 FL	*78.00 FL
103	1		*REAR LH FENDER STONE GUARD STICKER	Necessary	78.00 FL	*78.00 FL
104	1		*REAR RH MUDGUARD	Deformed	105.00 FL	*105.00 FL
105	1		*REAR LH MUDGUARD	Deformed	105.00 FL	*105.00 FL
106	1		*REAR BUMPER	Distorted	2,350.00 FL	*2,350.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*REAR BUMPER PARKING SENSOR	Damaged	220.00 FL	*220.00 FL
108	1		*REAR BUMPER RH NO PLATE LIGHT	Missing	65.00 FL	*65.00 FL
109	1		*REAR BUMPER LH NO PLATE LIGHT	Missing	65.00 FL	*65.00 FL
110	1		*REAR BUMPER RH LOWER SPOILER	Broken	530.00 FL	*530.00 FL
111	1		*REAR BUMPER LH LOWER SPOILER	Broken	530.00 FL	*530.00 FL
112	1		*REAR BUMPER RH SIDE RETAINER	Deformed	90.00 FL	*90.00 FL
113	1		*REAR BUMPER LH SIDE RETAINER	Deformed	90.00 FL	*90.00 FL
114	1		*REAR BUMPER TOWING HOOK	Not Necessary	45.00 FL	*- FL
115	10		*REAR BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
116	1		*REAR RH TAILLAMP	Cracked	790.00 FL	*790.00 FL
117	1		*REAR LH TAILLAMP	Cracked	790.00 FL	*790.00 FL
118	1		*REAR RH EXHAUST SILENCER	Bent	1,600.00 FL	*1,600.00 FL
119	1		*REAR LH EXHAUST SILENCER	Bent	1,600.00 FL	*1,600.00 FL
120	1		*REAR EXHAUST SILENCER CHROME	Bent	290.00 FL	*290.00 FL
121	1		*REAR EXHAUST SILENCER HEAT SHIELD	Bent	190.00 FL	*190.00 FL
122	1		*FRONT RH WHEEL SPORT RIM	Cut	1,300.00 FL	*1,300.00 FL
123	1		*FRONT LH WHEEL SPORT RIM	Cut	1,300.00 FL	*1,300.00 FL
124	1		*FRONT RH WHEEL SHOCK ABSORBER	Cut	920.00 FL	*920.00 FL
125	1		*FRONT LH WHEEL SHOCK ABSORBER	Cut	920.00 FL	*920.00 FL
126	1		*FRONT RH WHEEL SHOCK ABSORBER TOP MOUNTING	Not Necessary	360.00 FL	*- FL
127	1		*FRONT LH WHEEL SHOCK ABSORBER TOP MOUNTING	Not Necessary	360.00 FL	*- FL
128	1		*FRONT RH WHEEL SHOCK ABSORBER TOP BEARING	Not Necessary	150.00 FL	*- FL
129	1		*FRONT LH WHEEL SHOCK ABSORBER TOP BEARING	Not Necessary	150.00 FL	*- FL
130	1		*FRONT RH WHEEL SHOCK ABSORBER TOP STOPPER	Bent	120.00 FL	*120.00 FL
131	1		*FRONT LH WHEEL SHOCK ABSORBER TOP STOPPER	Bent	120.00 FL	*120.00 FL
132	1		*FRONT RH WHEEL KNUCKLE ARM	Bent	1,350.00 FL	*1,350.00 FL
133	1		*FRONT LH WHEEL KNUCKLE ARM	Bent	1,350.00 FL	*1,350.00 FL
134	1		*FRONT RH WHEEL KNUCKLE ARM BEARING	Bent	290.00 FL	*290.00 FL
135	1		*FRONT LH WHEEL KNUCKLE ARM BEARING	Bent	290.00 FL	*290.00 FL
136	1		*FRONT RH WHEEL LOWER ARM	Bent	940.00 FL	*940.00 FL
137	1		*FRONT LH WHEEL LOWER ARM	Bent	940.00 FL	*940.00 FL
138	1		*FRONT RH WHEEL CONTROL ARM	Bent	880.00 FL	*880.00 FL
139	1		*FRONT LH WHEEL CONTROL ARM	Bent	880.00 FL	*880.00 FL
140	1		*FRONT LH WHEEL CONTROL ARM COVER	Missing	60.00 FL	*60.00 FL
141	1		*FRONT RH WHEEL CONTROL ARM COVER	Missing	60.00 FL	*60.00 FL
142	1		*FRONT RH WHEEL STABILIZER LINKAGE	Bent	180.00 FL	*180.00 FL
143	1		*FRONT LH WHEEL STABILIZER LINKAGE	Bent	180.00 FL	*180.00 FL
144	1		*FRONT ANTI ROLL BAR	Bent	650.00 FL	*650.00 FL
145	1		*STEERING RACK AND PINION	Bent	3,400.00 FL	*3,400.00 FL
146	1		*FRONT RH WHEEL ABS SENSOR	Not Working	290.00 FL	*290.00 FL
147	1		*FRONT LH WHEEL ABS SENSOR	Not Working	290.00 FL	*290.00 FL
148	1		*FRONT LH WHEEL LEVELLING SENSOR	Not Working	310.00 FL	*310.00 FL
149	1		*STEERING CROSS MEMBER	Bent	3,700.00 FL	*3,700.00 FL
150	1		*REAR RH WHEEL SPORT RIM	Distorted	1,300.00 FL	*1,300.00 FL
151	1		*REAR LH WHEEL SPORT RIM	Distorted	1,300.00 FL	*1,300.00 FL
152	1		*REAR RH WHEEL SHOCK ABSORBER	Bent	650.00 FL	*650.00 FL
153	1		*REAR LH WHEEL SHOCK ABSORBER	Bent	650.00 FL	*650.00 FL
154	1		*REAR RH WHEEL SHOCK ABSORBER TOP MOUNTING	Bent	280.00 FL	*280.00 FL
155	1		*REAR LH WHEEL SHOCK ABSORBER TOP MOUNTING	Bent	280.00 FL	*280.00 FL
156	1		*REAR RH WHEEL KNUCKLE ARM	Bent	1,200.00 FL	*1,200.00 FL
157	1		*REAR LH WHEEL KNUCKLE ARM	Bent	1,200.00 FL	*1,200.00 FL
158	1		*REAR RH WHEEL KNUCKLE ARM BEARING	Bent	290.00 FL	*290.00 FL
159	1		*REAR LH WHEEL KNUCKLE ARM BEARING	Bent	290.00 FL	*290.00 FL
160	1		*REAR RH WHEEL LOWER ARM	Bent	920.00 FL	*920.00 FL
161	1		*REAR LH WHEEL LOWER ARM	Bent	920.00 FL	*920.00 FL
162	1		*REAR RH WHEEL CONTROL ARM	Bent	850.00 FL	*850.00 FL
163	1		*REAR LH WHEEL CONTROL ARM	Broken	850.00 FL	*850.00 FL
164	1		*REAR RH WHEEL TRAILING ARM	Bent	330.00 FL	*330.00 FL
165	1		*REAR LH WHEEL TRAILING ARM	Bent	330.00 FL	*330.00 FL
166	1		*REAR RH WHEEL DRIVE SHAFT	Bent	1,650.00 FL	*1,650.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
167	1		*REAR LH WHEEL DRIVE SHAFT	Broken	1,650.00 FL	*1,650.00 FL
168	1		*REAR RH WHEEL STABILIZER LINKAGE	Bent	210.00 FL	*210.00 FL
169	1		*REAR LH WHEEL STABILIZER LINKAGE	Bent	210.00 FL	*210.00 FL
170	1		*REAR ANTI ROLL BAR	Bent	630.00 FL	*630.00 FL
171	1		*REAR ANTI ROLL BAR RH BUSH	Bent	45.00 FL	*45.00 FL
172	1		*REAR ANTI ROLL BAR LH BUSH	Bent	45.00 FL	*45.00 FL
173	1		*REAR ANTI ROLL BAR RH BRACKET	Bent	55.00 FL	*55.00 FL
174	1		*REAR ANTI ROLL BAR LH BRACKET	Bent	55.00 FL	*55.00 FL
175	1		*REAR RH WHEEL DISC ROTOR	Broken	390.00 FL	*390.00 FL
176	1		*REAR LH WHEEL DISC ROTOR	Broken	390.00 FL	*390.00 FL
177	1		*REAR RH WHEEL DISC ROTOR PLATE	Bent	90.00 FL	*90.00 FL
178	1		*REAR LH WHEEL DISC ROTOR PLATE	Bent	90.00 FL	*90.00 FL
179	1		*REAR RH WHEEL BRAKE CALIPER	Bent	960.00 FL	*960.00 FL
180	1		*REAR LH WHEEL BRAKE CALIPER	Not Necessary	960.00 FL	*- FL
181	1		*REAR RH WHEEL BRAKE PIPE	Bent	85.00 FL	*85.00 FL
182	1		*REAR LH WHEEL BRAKE PIPE	Bent	85.00 FL	*85.00 FL
183	1		*REAR RH ABS SENSOR	Not Working	290.00 FL	*290.00 FL
184	1		*REAR LH ABS SENSOR	Not Working	290.00 FL	*290.00 FL
185	1		*RH CATAL YST	Dented	4,200.00 FL	*4,200.00 FL
186	1		*LH CATAL YST	Dented	4,200.00 FL	*4,200.00 FL
187	1		*CATALYST HEAT SHIELD	Buckled	190.00 FL	*190.00 FL
188	1		*REAR ENGINE RH CROSS MEMBER	Bent	2,700.00 FL	*2,700.00 FL
189	1		*REAR ENGINE LH CROSS MEMBER	Bent	2,700.00 FL	*2,700.00 FL
190	1		*REAR ENGINE RH CROSS MEMBER SUPPORT BAR	Bent	320.00 FL	*320.00 FL
191	1		*REAR ENGINE LH CROSS MEMBER SUPPORT BAR	Bent	320.00 FL	*320.00 FL
192	1		*ENGINE MOUNTING	Bent	920.00 FL	*920.00 FL
193	1		*ENGINE MOUNTING BRACKET	Bent	180.00 FL	*180.00 FL
194	1		*RH ENGINE HEAD	Not Necessary	5,800.00 FL	*- FL
195	1		*GEARBOX HOUSING	Not Necessary	8,000.00 FL	*- FL
196	1		*GEARBOX TOP COVER (BLACK)	Bent	420.00 FL	*420.00 FL
197	1		*GEARBOX LOWER COVER (METAL)	Bent	290.00 FL	*290.00 FL
198	1		*GEARBOX LOWER COVER SUPPORT BRACKET	Bent	150.00 FL	*150.00 FL
199	1		*GEARBOX RH BRACKET	Not Necessary	280.00 FL	*- FL
200	1		*GEARBOX LH BRACKET	Not Necessary	280.00 FL	*- FL
201	1		*GEARBOX RH MOUNTING	Bent	620.00 FL	*620.00 FL
202	1		*GEARBOX LH MOUNTING	Bent	620.00 FL	*620.00 FL
203	1		*GEARBOX MOUNTING RH BRACKET	Bent	170.00 FL	*170.00 FL
204	1		*GEARBOX MOUNTING LH BRACKET	Bent	170.00 FL	*170.00 FL
205	12		*GEARBOX SCREWS AND NUTS	Necessary	120.00 FL	*120.00 FL
206	1		*BODY RH UNDER COVER	Missing	280.00 FL	*280.00 FL
207	1		*BODY LH UNDER COVER	Missing	280.00 FL	*280.00 FL
208	1		*BODY CENTRE UNDER COVER	Missing	230.00 FL	*230.00 FL
209	1		*FRONT RH WHEEL TYRE	Cut	380.00 FS	*150.00 FS
210	1		*FRONT LH WHEEL TYRE	Cut	380.00 FS	*150.00 FS
211	1		*REAR RH WHEEL TYRE	Cut	380.00 FS	*150.00 FS
212	1		*REAR LH WHEEL TYRE	Cut	380.00 FS	*150.00 FS
213	1		*FRONT NO PLATE	Missing	40.00 FS	*40.00 FS
214	1		*REAR NO PLATE	Missing	40.00 FS	*40.00 FS
215	1		*GEARBOX	Cracked	38,000.00 FL	*22,000.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	181,481.00	139,871.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	8,994.05	13,919.10
Total Parts (\$\$)	172,486.95	125,951.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	150.00	60.00
2	TO REFILL AIRCON GAS	New	120.00	120.00
3	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	800.00	400.00
4	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	800.00	400.00
5	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	New	500.00	100.00
6	TO REMOVE AND REFIX PETROL TANK	New	150.00	60.00
7	TO REMOVE AND REFIX ENGINE	New	600.00	300.00
8	TO REMOVE GEARBOX	New	6,000.00	300.00
9	TO REPAIR DAMAGES	New	4,800.00	2,800.00
10	TO SPRAY PAINTING	New	3,200.00	2,200.00
Gross Labour Cost (\$\$)			17,120.00	6,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >