

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
 (Singapore) Pte Ltd
 3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5137
Date : 16-12-2021
Accident Date : 19-09-2021

Vehicle Details

Make & Model : Porsche CAYMAN 2.7 A
Chassis No : WP0ZZZ98ZEK160837
Registration No : SKL212L

Third Party Vehicle Details

Registration No : SLX7732G

S/N	Description	Qty	Amount (\$)
1	FRONT RH HEADLAMP	1.00	\$2,350.00
2	FRONT LH HEADLAMP	1.00	\$2,350.00
3	FRONT RH HEADLAMP ECU	1.00	\$599.00
4	FRONT LH HEADLAMP ECU	1.00	\$599.00
5	FRONT RH HEADLAMP HID BULB	1.00	\$253.00
6	FRONT LH HEADLAMP HID BULB	1.00	\$253.00
7	FRONT RH HEADLAMP BRACKET	1.00	\$390.00
8	FRONT LH HEADLAMP BRACKET	1.00	\$390.00
9	FRONT BUMPER	1.00	\$1,980.00
10	FRONT BUMPER RH NOZZLE GUN	1.00	\$260.00
11	FRONT BUMPER LH NOZZLE GUN	1.00	\$260.00
12	FRONT BUMPER RH NOZZLE GUN BRACKET	1.00	\$65.00
13	FRONT BUMPER LH NOZZLE GUN BRACKET	1.00	\$65.00
14	FRONT BUMPER TOWING COVER	1.00	\$70.00 X
15	FRONT BUMPER CENTRE LOWER GRILLE	1.00	\$380.00
16	FRONT BUMPER RH DAY LIGHT	1.00	\$690.00
17	FRONT BUMPER LH DAY LIGHT	1.00	\$690.00
18	FRONT BUMPER RH SIDE GRILLE COVER	1.00	\$155.00
19	FRONT BUMPER LH SIDE GRILLE COVER	1.00	\$155.00
20	FRONT BUMPER RH SIDE RETAINER - LONG	1.00	\$85.00
21	FRONT BUMPER LH SIDE RETAINER - LONG	1.00	\$85.00
22	FRONT BUMPER RH SIDE RETAINER - SHORT	1.00	\$65.00
23	FRONT BUMPER LH SIDE RETAINER - SHORT	1.00	\$65.00
24	FRONT BUMPER REINFORCEMENT	1.00	\$860.00
25	FRONT BUMPER REINFORCEMENT RH BRACKET	1.00	\$240.00
26	FRONT BUMPER REINFORCEMENT LH BRACKET	1.00	\$240.00
27	FRONT BUMPER CLIPS @ \$9.00	10.00	\$90.00
28	LUGGAGE COMPARTMENT ASSY	1.00	\$720.00 X
29	LUGGAGE COMPARTMENT FRONT SUPPORT	1.00	\$440.00 X
30	LUGGAGE COMPARTMENT FRONT PANEL	1.00	\$690.00 X

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

31	RH HORN	/ 4 mis	1.00	\$190.00
32	LH HORN		1.00	\$190.00
33	RH HORN BRACKET	/ 5 mis	1.00	\$95.00
34	LH HORN BRACKET		1.00	\$95.00
35	RH AIRCON CONDENSER	✓ BT	1.00	\$960.00
36	LH AIRCON CONDENSER	✓ BT	1.00	\$960.00
37	RH AIRCON CONDENSER PIPE	✓ BT	1.00	\$620.00
38	LH AIRCON CONDENSER PIPE	✓ BT	1.00	\$620.00
39	RH AIRCON CONDENSER AIR DUCT	✓	1.00	\$65.00
40	LH AIRCON CONDENSER AIR DUCT	✓ CRA	1.00	\$65.00
41	AIRCON TEMPERATURE SENSOR	✓ NW	1.00	\$98.00
42	RH RADIATOR	✓ CRA	1.00	\$880.00
43	LH RADIATOR	✓ CRA	1.00	\$880.00
44	RH RADIATOR TOP HOSE	✗ NN	1.00	\$230.00 ✗
45	LH RADIATOR TOP HOSE	✗ NN	1.00	\$230.00 ✗
46	RH RADIATOR LOWER HOSE	✗ NN	1.00	\$260.00 ✗
47	LH RADIATOR LOWER HOSE	✗ NN	1.00	\$260.00 ✗
48	RH INTER COOLER	✗ NN	1.00	\$940.00 ✗
49	LH INTER COOLER	✗ NN	1.00	\$940.00 ✗
50	RH RADIATOR AIR DUCT	/ 4 mis	1.00	\$78.00
51	LH RADIATOR AIR DUCT		1.00	\$78.00
52	RH RADIATOR BRACKET	✗ NN	1.00	\$40.00 ✗
53	LH RADIATOR BRACKET	✗ NN	1.00	\$40.00 ✗
54	RH RADIATOR LOWER BRACKET	✓ BT	1.00	\$46.00
55	LH RADIATOR LOWER BRACKET	✓ BT	1.00	\$46.00
56	RH RADIATOR UNDER COVER	/ 5 mis	1.00	\$190.00
57	LH RADIATOR UNDER COVER		1.00	\$190.00
58	RH RADIATOR FAN MOTOR ASSY	✓ NW	1.00	\$890.00
59	LH RADIATOR FAN MOTOR ASSY	✓ NW	1.00	\$890.00
60	FRONT RH FENDER	/ Blue	1.00	\$1,400.00
61	FRONT LH FENDER	✗ NN	1.00	\$1,400.00 ✗
62	FRONT RH FENDER INNER SHIELD - FRONT	/	1.00	\$250.00
63	FRONT LH FENDER INNER SHIELD - FRONT	/ 4 mis	1.00	\$250.00
64	FRONT RH FENDER INNER SHIELD - REAR	/	1.00	\$255.00
65	FRONT LH FENDER INNER SHIELD - REAR	✗ NN	1.00	\$255.00 ✗
66	FRONT FENDER INNER SHIELD CLIPS @ \$9.00	/	20.00	\$180.00
67	FRONT RH DOOR	/ Blue	1.00	\$2,800.00
68	FRONT RH DOOR OUTER MOULDING	✗ NN	1.00	\$190.00 ✗
69	FRONT RH DOOR UPPER HINGE	/ 4 mis	1.00	\$155.00
70	FRONT RH DOOR LOWER HINGE	/	1.00	\$155.00
71	FRONT RH DOOR RUBBER	✓	1.00	\$270.00
72	FRONT RH DOOR INNER TRIMBOARD	✓ CRA	1.00	\$1,250.00
73	FRONT RH DOOR INNER LOCK	✓ CUT	1.00	\$420.00
74	FRONT RH DOOR POWER WINDOW MOTOR	✓ NW	1.00	\$520.00

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

75	FRONT RH DOOR POWER WINDOW GEAR	✓ BT	1.00	\$490.00
76	FRONT RH DOOR FRAME BODY RUBBER	✓ NEC	1.00	\$185.00
77	RH SIDE MIRROR ASSY	✓	1.00	\$1,080.00
78	RH SIDE MIRROR GLASS	✓	1.00	\$370.00
79	RH ROCKER PANEL	✓	1.00	\$1,320.00
80	FRONT LH DOOR	✓	1.00	\$2,800.00
81	FRONT LH DOOR OUTER MOULDING	X	1.00	\$190.00 X
82	FRONT LH DOOR UPPER HINGE	X	1.00	\$155.00 X
83	FRONT LH DOOR LOWER HINGE	X	1.00	\$155.00 X
84	FRONT LH DOOR RUBBER	✓	1.00	\$270.00
85	FRONT LH DOOR INNER TRIMBOARD	✓ CRA	1.00	\$1,250.00
86	FRONT LH DOOR INNER LOCK	✓ CUT	1.00	\$420.00
87	FRONT LH DOOR POWER WINDOW MOTOR	✓ NW	1.00	\$520.00
88	FRONT LH DOOR POWER WINDOW GEAR	✓ BT	1.00	\$490.00
89	FRONT LH DOOR FRAME BODY RUBBER	✓ NEC	1.00	\$185.00
90	LH ROCKER PANEL	✓	1.00	\$1,320.00
91	REAR RH FENDER	✓	1.00	\$3,700.00
92	REAR LH FENDER	✓	1.00	\$3,700.00
93	REAR RH FENDER AIR VENT COVER	✓	1.00	\$140.00
94	REAR LH FENDER AIR VENT COVER	✓	1.00	\$140.00
95	REAR RH FENDER INNER SHIELD - FRONT	✓	1.00	\$165.00
96	REAR LH FENDER INNER SHIELD - FRONT	✓	1.00	\$170.00
97	REAR RH FENDER INNER SHIELD - REAR	✓	1.00	\$165.00
98	REAR LH FENDER INNER SHIELD - REAR	✓	1.00	\$170.00
99	REAR RH FENDER INNER PANEL	X	1.00	\$550.00 X
100	REAR LH FENDER INNER PANEL	X	1.00	\$550.00 X
101	REAR FENDER INNER SHIELD CLIPS @ \$9.00	✓	20.00	\$180.00
102	REAR RH FENDER STONE GUARD STICKER	✓	1.00	\$78.00
103	REAR LH FENDER STONE GUARD STICKER	✓	1.00	\$78.00
104	REAR RH MUDFLAG	✓	1.00	\$105.00
105	REAR LH MUDFLAG	✓	1.00	\$105.00
106	REAR BUMPER	✓	1.00	\$2,350.00
107	REAR BUMPER PARKING SENSOR	✓	1.00	\$220.00
108	REAR BUMPER RH NO. PLATE LIGHT	✓	1.00	\$65.00
109	REAR BUMPER LH NO. PLATE LIGHT	✓	1.00	\$65.00
110	REAR BUMPER RH LOWER SPOILER	✓	1.00	\$530.00
111	REAR BUMPER LH LOWER SPOILER	✓	1.00	\$530.00
112	REAR BUMPER RH SIDE RETAINER	✓	1.00	\$90.00
113	REAR BUMPER LH SIDE RETAINER	✓	1.00	\$90.00
114	REAR BUMPER TOWING HOOK	X	1.00	\$45.00 X
115	REAR BUMPER CLIPS @ \$9.00	✓	10.00	\$90.00
116	REAR RH TAILLAMP	✓	1.00	\$790.00
117	REAR LH TAILLAMP	✓	1.00	\$790.00
118	REAR RH EXHAUST SILENCER	✓	1.00	\$1,600.00

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

119	REAR LH EXHAUST SILENCER	/	1.00	\$1,600.00
120	REAR EXHAUST SILENCER CHROME	/	1.00	\$290.00
121	REAR EXHAUST SILENCER HEAT SHIELD	/	1.00	\$190.00
122	FRONT RH WHEEL SPORT RIM	/	1.00	\$1,300.00
123	FRONT LH WHEEL SPORT RIM	/	1.00	\$1,300.00
124	FRONT RH WHEEL SHOCK ABSORBER	=	1.00	\$920.00
125	FRONT LH WHEEL SHOCK ABSORBER	=	1.00	\$920.00
126	FRONT RH WHEEL SHOCK ABSORBER TOP MOUNTING	X	1.00	\$360.00 X
127	FRONT LH WHEEL SHOCK ABSORBER TOP MOUNTING	X	1.00	\$360.00 X
128	FRONT RH WHEEL SHOCK ABSORBER TOP BEARING	X	1.00	\$150.00 X
129	FRONT LH WHEEL SHOCK ABSORBER TOP BEARING	X	1.00	\$150.00 X
130	FRONT RH WHEEL SHOCK ABSORBER TOP STOPPER	=	1.00	\$120.00
131	FRONT LH WHEEL SHOCK ABSORBER TOP STOPPER	=	1.00	\$120.00
132	FRONT RH WHEEL KNUCKLE ARM	=	1.00	\$1,350.00
133	FRONT LH WHEEL KNUCKLE ARM	=	1.00	\$1,350.00
134	FRONT RH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
135	FRONT LH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
136	FRONT RH WHEEL LOWER ARM	=	1.00	\$940.00
137	FRONT LH WHEEL LOWER ARM	=	1.00	\$940.00
138	FRONT RH WHEEL CONTROL ARM	✓ BT	1.00	\$880.00
139	FRONT LH WHEEL CONTROL ARM	✓ BT	1.00	\$880.00
140	FRONT RH WHEEL CONTROL ARM COVER	✓ MIS	1.00	\$60.00
141	FRONT LH WHEEL CONTROL ARM COVER	✓ MIS	1.00	\$60.00
142	FRONT RH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$180.00
143	FRONT LH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$180.00
144	FRONT ANTI ROLL BAR	✓ BT	1.00	\$650.00
145	STEERING RACK AND PINION	✓ BT	1.00	\$3,400.00
146	FRONT RH WHEEL ABS SENSOR	✓ NW	1.00	\$290.00
147	FRONT LH WHEEL ABS SENSOR	✓ NW	1.00	\$290.00
148	FRONT LH WHEEL LEVELLING SENSOR	✓ NW	1.00	\$310.00
149	STEERING CROSS MEMBER	✓ BT	1.00	\$3,700.00
150	REAR RH WHEEL SPORT RIM	=	1.00	\$1,300.00
151	REAR LH WHEEL SPORT RIM	=	1.00	\$1,300.00
152	REAR RH WHEEL SHOCK ABSORBER	=	1.00	\$650.00
153	REAR LH WHEEL SHOCK ABSORBER	=	1.00	\$650.00
154	REAR RH WHEEL SHOCK ABSORBER TOP MOUNTING	=	1.00	\$280.00
155	REAR LH WHEEL SHOCK ABSORBER TOP MOUNTING	=	1.00	\$280.00
156	REAR RH WHEEL KNUCKLE ARM	=	1.00	\$1,200.00
157	REAR LH WHEEL KNUCKLE ARM	=	1.00	\$1,200.00
158	REAR RH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
159	REAR LH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
160	REAR RH WHEEL LOWER ARM	=	1.00	\$920.00
161	REAR LH WHEEL LOWER ARM	=	1.00	\$920.00
162	REAR RH WHEEL CONTROL ARM	✓ BT	1.00	\$850.00

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

163	REAR LH WHEEL CONTROL ARM	✓ BR	1.00	\$850.00
164	REAR RH WHEEL TRAILING ARM	✓ BT	1.00	\$330.00
165	REAR LH WHEEL TRAILING ARM	✓ BT	1.00	\$330.00
166	REAR RH WHEEL DRIVE SHAFT	✓ BT	1.00	\$1,650.00
167	REAR LH WHEEL DRIVE SHAFT	✓ BR	1.00	\$1,650.00
168	REAR RH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$210.00
169	REAR LH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$210.00
170	REAR ANTI ROLL BAR		1.00	\$630.00
171	REAR ANTI ROLL BAR RH BUSH		1.00	\$45.00
172	REAR ANTI ROLL BAR LH BUSH		1.00	\$45.00
173	REAR ANTI ROLL BAR RH BRACKET		1.00	\$55.00
174	REAR ANTI ROLL BAR LH BRACKET		1.00	\$55.00
175	REAR RH WHEEL DISC ROTOR	✓ BR	1.00	\$390.00
176	REAR LH WHEEL DISC ROTOR	✓ BT	1.00	\$390.00
177	REAR RH WHEEL DISC ROTOR PLATE	✓ BT	1.00	\$90.00
178	REAR LH WHEEL DISC ROTOR PLATE	✓ BT	1.00	\$90.00
179	REAR RH WHEEL BRAKE CALIPER	✓ BT	1.00	\$960.00
180	REAR LH WHEEL BRAKE CALIPER	✗ NN	1.00	\$960.00 ✗
181	REAR RH WHEEL BRAKE PIPE	✓ BT	1.00	\$85.00
182	REAR LH WHEEL BRAKE PIPE	✓ BT	1.00	\$85.00
183	REAR RH ABS SENSOR	✓ NW	1.00	\$290.00
184	REAR LH ABS SENSOR	✓ NW	1.00	\$290.00
185	RH CATALYST	✓ DD	1.00	\$4,200.00
186	LH CATALYST	✓ DD	1.00	\$4,200.00
187	CATALYST HEAT SHIELD	✓ BT	1.00	\$190.00
188	REAR ENGINE RH CROSS MEMBER	✓ BT	1.00	\$2,700.00
189	REAR ENGINE LH CROSS MEMBER	✓ BT	1.00	\$2,700.00
190	REAR ENGINE RH CROSS MEMBER SUPPORT BAR	✓ BT	1.00	\$320.00
191	REAR ENGINE LH CROSS MEMBER SUPPORT BAR	✓ BT	1.00	\$320.00
192	ENGINE MOUNTING	✓ BT	1.00	\$920.00
193	ENGINE MOUNTING BRACKET	✓ BT	1.00	\$180.00
194	RH ENGINE HEAD	✗ NN	1.00	\$5,800.00 ✗
195	GEARBOX HOUSING	✗ NN	1.00	\$8,000.00 ✗
196	GEARBOX TOP COVER (BLACK)	✓ BT	1.00	\$420.00
197	GEARBOX LOWER COVER (METAL)	✓ BT	1.00	\$290.00
198	GEARBOX LOWER COVER SUPPORT BRACKET	✓ BT	1.00	\$150.00
199	GEARBOX RH BRACKET	✗ NN	1.00	\$280.00 ✗
200	GEARBOX LH BRACKET	✗ NN	1.00	\$280.00 ✗
201	GEARBOX RH MOUNTING	✓ BT	1.00	\$620.00
202	GEARBOX LH MOUNTING	✓ BT	1.00	\$620.00
203	GEARBOX MOUNTING RH BRACKET	✓ BT	1.00	\$170.00
204	GEARBOX MOUNTING LH BRACKET	✓ BT	1.00	\$170.00
205	GEARBOX SCREWS AND NUTS @ \$10.00	✓ NEC	12.00	\$120.00
206	BODY RH UNDER COVER	✓	1.00	\$280.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

207 BODY LH UNDER COVER / *mis*
208 BODY CENTRE UNDER COVER /

1.00 \$280.00
1.00 \$230.00

\$141,881.00 117191
(\$7,094.05)

Discount: -5%
-10%: 105471.9

\$134,786.95

209 FRONT RH WHEEL TYRE / *cut*
210 FRONT LH WHEEL TYRE / *cut*
211 REAR RH WHEEL TYRE / *cut*
212 REAR LH WHEEL TYRE / *cut*
213 FRONT NO. PLATE / *mis*
214 REAR NO. PLATE / *mis*
215 TO CHECK WHEEL ALIGNMENT
216 TO REFILL AIRCON GAS
217 TO REMOVE AND REFIX FRONT UNDERCARRIAGE
218 TO REMOVE AND REFIX REAR UNDERCARRIAGE
219 TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION
220 TO REMOVE AND REFIX PETROL TANK
221 TO REMOVE AND REFIX ENGINE
222 TO REMOVE ~~AND OVERHAUL~~ GEARBOX
223 TO REPAIR DAMAGES
224 TO SPRAY PAINTING

1.00 \$380.00 150
1.00 \$380.00 150
1.00 \$380.00 150
1.00 \$380.00 150
1.00 \$40.00 ✓
1.00 \$40.00 ✓
1.00 \$150.00 *bc*
1.00 \$120.00 ✓
1.00 \$800.00 *400*
1.00 \$800.00 *400*
1.00 \$500.00 *100*
1.00 \$150.00 *60*
1.00 \$600.00 *2 300*
1.00 \$6,000.00 *2 300*
1.00 \$4,800.00 *2800*
1.00 \$3,200.00 *2200*

Subtotal w/o GST: \$153,506.95 7420

139891.9

-20%: 111900

22 ~~18~~ Days.

4/5

After repair photos.

Enc Q: op

23/12/21

LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.