

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel: 6453 2121 Fax: 6459 9795
 GST Registration No: 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
 (Singapore) Pte Ltd
 3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5137
Date : 16-12-2021
Accident Date : 19-09-2021

Vehicle Details

Make & Model : Porsche CAYMAN 2.7 A
Chassis No : WP0ZZZ98ZEK160837
Registration No : SKL212L

Third Party Vehicle Details

Registration No : SLX7732G

S/N	Description	Qty	Amount (\$S)
1	FRONT RH HEADLAMP	1.00	\$2,350.00
2	FRONT LH HEADLAMP	1.00	\$2,350.00
3	FRONT RH HEADLAMP ECU	1.00	\$599.00
4	FRONT LH HEADLAMP ECU	1.00	\$599.00
5	FRONT RH HEADLAMP HID BULB	1.00	\$253.00
6	FRONT LH HEADLAMP HID BULB	1.00	\$253.00
7	FRONT RH HEADLAMP BRACKET	1.00	\$390.00
8	FRONT LH HEADLAMP BRACKET	1.00	\$390.00
9	FRONT BUMPER	1.00	\$1,980.00
10	FRONT BUMPER RH NOZZLE GUN	1.00	\$260.00
11	FRONT BUMPER LH NOZZLE GUN	1.00	\$260.00
12	FRONT BUMPER RH NOZZLE GUN BRACKET	1.00	\$65.00
13	FRONT BUMPER LH NOZZLE GUN BRACKET	1.00	\$65.00
14	FRONT BUMPER TOWING COVER	1.00	\$70.00 X
15	FRONT BUMPER CENTRE LOWER GRILLE	1.00	\$380.00
16	FRONT BUMPER RH DAY LIGHT	1.00	\$690.00
17	FRONT BUMPER LH DAY LIGHT	1.00	\$690.00
18	FRONT BUMPER RH SIDE GRILLE COVER	1.00	\$155.00
19	FRONT BUMPER LH SIDE GRILLE COVER	1.00	\$155.00
20	FRONT BUMPER RH SIDE RETAINER - LONG	1.00	\$85.00
21	FRONT BUMPER LH SIDE RETAINER - LONG	1.00	\$85.00
22	FRONT BUMPER RH SIDE RETAINER - SHORT	1.00	\$65.00
23	FRONT BUMPER LH SIDE RETAINER - SHORT	1.00	\$65.00
24	FRONT BUMPER REINFORCEMENT	1.00	\$860.00
25	FRONT BUMPER REINFORCEMENT RH BRACKET	1.00	\$240.00
26	FRONT BUMPER REINFORCEMENT LH BRACKET	1.00	\$240.00
27	FRONT BUMPER CLIPS @ \$9.00	10.00	\$90.00
28	LUGGAGE COMPARTMENT ASSY	1.00	\$720.00 X
29	LUGGAGE COMPARTMENT FRONT SUPPORT	1.00	\$440.00 X
30	LUGGAGE COMPARTMENT FRONT PANEL	1.00	\$690.00 X

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel: 6453 2121 Fax: 6459 9795
GST Registration No. 199906067G

31	RH HORN	/ Mis	1.00	\$190.00
32	LH HORN	/ Mis	1.00	\$190.00
33	RH HORN BRACKET	/ Mis	1.00	\$95.00
34	LH HORN BRACKET	/ Mis	1.00	\$95.00
35	RH AIRCON CONDENSER	✓ BT	1.00	\$960.00
36	LH AIRCON CONDENSER	✓ BT	1.00	\$960.00
37	RH AIRCON CONDENSER PIPE	✓ BT	1.00	\$620.00
38	LH AIRCON CONDENSER PIPE	✓ BT	1.00	\$620.00
39	RH AIRCON CONDENSER AIR DUCT	✓	1.00	\$65.00
40	LH AIRCON CONDENSER AIR DUCT	✓ CRA	1.00	\$65.00
41	AIRCON TEMPERATURE SENSOR	✓ NW	1.00	\$98.00
42	RH RADIATOR	✓ CRA	1.00	\$880.00
43	LH RADIATOR	✓ CRA	1.00	\$880.00
44	RH RADIATOR TOP HOSE	✗ NN	1.00	\$230.00 ✗
45	LH RADIATOR TOP HOSE	✗ NN	1.00	\$230.00 ✗
46	RH RADIATOR LOWER HOSE	✗ NN	1.00	\$260.00 ✗
47	LH RADIATOR LOWER HOSE	✗ NN	1.00	\$260.00 ✗
48	RH INTER COOLER	✗ NN	1.00	\$940.00 ✗
49	LH INTER COOLER	✗ NN	1.00	\$940.00 ✗
50	RH RADIATOR AIR DUCT	/ Mis	1.00	\$78.00
51	LH RADIATOR AIR DUCT	/ Mis	1.00	\$78.00
52	RH RADIATOR BRACKET	✗ NN	1.00	\$40.00 ✗
53	LH RADIATOR BRACKET	✗ NN	1.00	\$40.00 ✗
54	RH RADIATOR LOWER BRACKET	✓ BT	1.00	\$46.00
55	LH RADIATOR LOWER BRACKET	✓ BT	1.00	\$46.00
56	RH RADIATOR UNDER COVER	/ Mis	1.00	\$190.00
57	LH RADIATOR UNDER COVER	/ Mis	1.00	\$190.00
58	RH RADIATOR FAN MOTOR ASSY	✓ NW	1.00	\$890.00
59	LH RADIATOR FAN MOTOR ASSY	✓ NW	1.00	\$890.00
60	FRONT RH FENDER	/ Blue	1.00	\$1,400.00
61	FRONT LH FENDER	✗ NN	1.00	\$1,400.00 ✗
62	FRONT RH FENDER INNER SHIELD - FRONT	/ Mis	1.00	\$250.00
63	FRONT LH FENDER INNER SHIELD - FRONT	/ Mis	1.00	\$250.00
64	FRONT RH FENDER INNER SHIELD - REAR	/ Mis	1.00	\$255.00
65	FRONT LH FENDER INNER SHIELD - REAR	✗ NN	1.00	\$255.00 ✗
66	FRONT FENDER INNER SHIELD CLIPS @ \$9.00	/	20.00	\$180.00
67	FRONT RH DOOR	/ Blue	1.00	\$2,800.00
68	FRONT RH DOOR OUTER MOULDING	✗ NN	1.00	\$190.00 ✗
69	FRONT RH DOOR UPPER HINGE	/ Mis	1.00	\$155.00
70	FRONT RH DOOR LOWER HINGE	/ Mis	1.00	\$155.00
71	FRONT RH DOOR RUBBER	✓	1.00	\$270.00
72	FRONT RH DOOR INNER TRIMBOARD	✓ CRA	1.00	\$1,250.00
73	FRONT RH DOOR INNER LOCK	✓ CUT	1.00	\$420.00
74	FRONT RH DOOR POWER WINDOW MOTOR	✓ NW	1.00	\$520.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

75	FRONT RH DOOR POWER WINDOW GEAR	✓ BT	1.00	\$490.00
76	FRONT RH DOOR FRAME BODY RUBBER	✓ NEC	1.00	\$185.00
77	RH SIDE MIRROR ASSY	✓	1.00	\$1,080.00
78	RH SIDE MIRROR GLASS	✓	1.00	\$370.00
79	RH ROCKER PANEL	✓	1.00	\$1,320.00
80	FRONT LH DOOR	✓	1.00	\$2,800.00
81	FRONT LH DOOR OUTER MOULDING	X	1.00	\$190.00 X
82	FRONT LH DOOR UPPER HINGE	X	1.00	\$155.00 X
83	FRONT LH DOOR LOWER HINGE	X	1.00	\$155.00 X
84	FRONT LH DOOR RUBBER	✓	1.00	\$270.00
85	FRONT LH DOOR INNER TRIMBOARD	✓ CRA	1.00	\$1,250.00
86	FRONT LH DOOR INNER LOCK	✓ CUT	1.00	\$420.00
87	FRONT LH DOOR POWER WINDOW MOTOR	✓ NW	1.00	\$520.00
88	FRONT LH DOOR POWER WINDOW GEAR	✓ BT	1.00	\$490.00
89	FRONT LH DOOR FRAME BODY RUBBER	✓ NEC	1.00	\$185.00
90	LH ROCKER PANEL	✓	1.00	\$1,320.00
91	REAR RH FENDER	✓	1.00	\$3,700.00
92	REAR LH FENDER	✓	1.00	\$3,700.00
93	REAR RH FENDER AIR VENT COVER	✓	1.00	\$140.00
94	REAR LH FENDER AIR VENT COVER	✓	1.00	\$140.00
95	REAR RH FENDER INNER SHIELD - FRONT	✓	1.00	\$165.00
96	REAR LH FENDER INNER SHIELD - FRONT	✓	1.00	\$170.00
97	REAR RH FENDER INNER SHIELD - REAR	✓	1.00	\$165.00
98	REAR LH FENDER INNER SHIELD - REAR	✓	1.00	\$170.00
99	REAR RH FENDER INNER PANEL	X	1.00	\$550.00 X
100	REAR LH FENDER INNER PANEL	X	1.00	\$550.00 X
101	REAR FENDER INNER SHIELD CLIPS @ \$9.00	✓	20.00	\$180.00
102	REAR RH FENDER STONE GUARD STICKER	✓	1.00	\$78.00
103	REAR LH FENDER STONE GUARD STICKER	✓	1.00	\$78.00
104	REAR RH MUDFLAG	✓	1.00	\$105.00
105	REAR LH MUDFLAG	✓	1.00	\$105.00
106	REAR BUMPER	✓	1.00	\$2,350.00
107	REAR BUMPER PARKING SENSOR	✓	1.00	\$220.00
108	REAR BUMPER RH NO. PLATE LIGHT	✓	1.00	\$65.00
109	REAR BUMPER LH NO. PLATE LIGHT	✓	1.00	\$65.00
110	REAR BUMPER RH LOWER SPOILER	✓	1.00	\$530.00
111	REAR BUMPER LH LOWER SPOILER	✓	1.00	\$530.00
112	REAR BUMPER RH SIDE RETAINER	✓	1.00	\$90.00
113	REAR BUMPER LH SIDE RETAINER	✓	1.00	\$90.00
114	REAR BUMPER TOWING HOOK	X	1.00	\$45.00 X
115	REAR BUMPER CLIPS @ \$9.00	✓	10.00	\$90.00
116	REAR RH TAILLAMP	✓	1.00	\$790.00
117	REAR LH TAILLAMP	✓	1.00	\$790.00
118	REAR RH EXHAUST SILENCER	✓	1.00	\$1,600.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

119	REAR LH EXHAUST SILENCER	/	1.00	\$1,600.00
120	REAR EXHAUST SILENCER CHROME	/	1.00	\$290.00
121	REAR EXHAUST SILENCER HEAT SHIELD	/	1.00	\$190.00
122	FRONT RH WHEEL SPORT RIM	/	1.00	\$1,300.00
123	FRONT LH WHEEL SPORT RIM	/	1.00	\$1,300.00
124	FRONT RH WHEEL SHOCK ABSORBER	=	1.00	\$920.00
125	FRONT LH WHEEL SHOCK ABSORBER	=	1.00	\$920.00
126	FRONT RH WHEEL SHOCK ABSORBER TOP MOUNTING	X	1.00	\$360.00 X
127	FRONT LH WHEEL SHOCK ABSORBER TOP MOUNTING	X	1.00	\$360.00 X
128	FRONT RH WHEEL SHOCK ABSORBER TOP BEARING	X	1.00	\$150.00 X
129	FRONT LH WHEEL SHOCK ABSORBER TOP BEARING	X	1.00	\$150.00 X
130	FRONT RH WHEEL SHOCK ABSORBER TOP STOPPER	=	1.00	\$120.00
131	FRONT LH WHEEL SHOCK ABSORBER TOP STOPPER	=	1.00	\$120.00
132	FRONT RH WHEEL KNUCKLE ARM	/	1.00	\$1,350.00
133	FRONT LH WHEEL KNUCKLE ARM	/	1.00	\$1,350.00
134	FRONT RH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
135	FRONT LH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
136	FRONT RH WHEEL LOWER ARM	/	1.00	\$940.00
137	FRONT LH WHEEL LOWER ARM	/	1.00	\$940.00
138	FRONT RH WHEEL CONTROL ARM	✓ BT	1.00	\$880.00
139	FRONT LH WHEEL CONTROL ARM	✓ BT	1.00	\$880.00
140	FRONT RH WHEEL CONTROL ARM COVER	✓ MIS	1.00	\$60.00
141	FRONT LH WHEEL CONTROL ARM COVER	✓ MIS	1.00	\$60.00
142	FRONT RH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$180.00
143	FRONT LH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$180.00
144	FRONT ANTI ROLL BAR	✓ BT	1.00	\$650.00
145	STEERING RACK AND PINION	✓ BT	1.00	\$3,400.00
146	FRONT RH WHEEL ABS SENSOR	✓ NW	1.00	\$290.00
147	FRONT LH WHEEL ABS SENSOR	✓ NW	1.00	\$290.00
148	FRONT LH WHEEL LEVELLING SENSOR	✓ NW	1.00	\$310.00
149	STEERING CROSS MEMBER	✓ BT	1.00	\$3,700.00
150	REAR RH WHEEL SPORT RIM	=	1.00	\$1,300.00
151	REAR LH WHEEL SPORT RIM	=	1.00	\$1,300.00
152	REAR RH WHEEL SHOCK ABSORBER	=	1.00	\$650.00
153	REAR LH WHEEL SHOCK ABSORBER	=	1.00	\$650.00
154	REAR RH WHEEL SHOCK ABSORBER TOP MOUNTING	=	1.00	\$280.00
155	REAR LH WHEEL SHOCK ABSORBER TOP MOUNTING	=	1.00	\$280.00
156	REAR RH WHEEL KNUCKLE ARM	=	1.00	\$1,200.00
157	REAR LH WHEEL KNUCKLE ARM	=	1.00	\$1,200.00
158	REAR RH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
159	REAR LH WHEEL KNUCKLE ARM BEARING	=	1.00	\$290.00
160	REAR RH WHEEL LOWER ARM	=	1.00	\$920.00
161	REAR LH WHEEL LOWER ARM	=	1.00	\$920.00
162	REAR RH WHEEL CONTROL ARM	✓ BT	1.00	\$850.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel: 6453 2121 Fax: 6459 9795
GST Registration No. 199906067G

163	REAR LH WHEEL CONTROL ARM	✓ BR	1.00	\$850.00
164	REAR RH WHEEL TRAILING ARM	✓ BT	1.00	\$330.00
165	REAR LH WHEEL TRAILING ARM	✓ BT	1.00	\$330.00
166	REAR RH WHEEL DRIVE SHAFT	✓ BT	1.00	\$1,650.00
167	REAR LH WHEEL DRIVE SHAFT	✓ BT	1.00	\$1,650.00
168	REAR RH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$210.00
169	REAR LH WHEEL STABILIZER LINKAGE	✓ BT	1.00	\$210.00
170	REAR ANTI ROLL BAR		1.00	\$630.00
171	REAR ANTI ROLL BAR RH BUSH		1.00	\$45.00
172	REAR ANTI ROLL BAR LH BUSH		1.00	\$45.00
173	REAR ANTI ROLL BAR RH BRACKET		1.00	\$55.00
174	REAR ANTI ROLL BAR LH BRACKET		1.00	\$55.00
175	REAR RH WHEEL DISC ROTOR	✓ BR	1.00	\$390.00
176	REAR LH WHEEL DISC ROTOR	✓ BT	1.00	\$390.00
177	REAR RH WHEEL DISC ROTOR PLATE	✓ BT	1.00	\$90.00
178	REAR LH WHEEL DISC ROTOR PLATE	✓ BT	1.00	\$90.00
179	REAR RH WHEEL BRAKE CALIPER	✓ BT	1.00	\$960.00
180	REAR LH WHEEL BRAKE CALIPER	✓ NN	1.00	\$960.00 X
181	REAR RH WHEEL BRAKE PIPE	✓ BT	1.00	\$85.00
182	REAR LH WHEEL BRAKE PIPE	✓ BT	1.00	\$85.00
183	REAR RH ABS SENSOR	✓ NW	1.00	\$290.00
184	REAR LH ABS SENSOR	✓ NW	1.00	\$290.00
185	RH CATALYST	✓ DD	1.00	\$4,200.00
186	LH CATALYST	✓ DD	1.00	\$4,200.00
187	CATALYST HEAT SHIELD	✓ BT	1.00	\$190.00
188	REAR ENGINE RH CROSS MEMBER	✓ BT	1.00	\$2,700.00
189	REAR ENGINE LH CROSS MEMBER	✓ BT	1.00	\$2,700.00
190	REAR ENGINE RH CROSS MEMBER SUPPORT BAR	✓ BT	1.00	\$320.00
191	REAR ENGINE LH CROSS MEMBER SUPPORT BAR	✓ BT	1.00	\$320.00
192	ENGINE MOUNTING	✓ BT	1.00	\$920.00
193	ENGINE MOUNTING BRACKET	✓ BT	1.00	\$180.00
194	RH ENGINE HEAD	✓ NN	1.00	\$5,800.00 X
195	GEARBOX HOUSING	✓ BT	1.00	\$8,000.00 X
196	GEARBOX TOP COVER (BLACK)	✓ BT	1.00	\$420.00
197	GEARBOX LOWER COVER (METAL)	✓ BT	1.00	\$290.00
198	GEARBOX LOWER COVER SUPPORT BRACKET	✓ BT	1.00	\$150.00
199	GEARBOX RH BRACKET	✓ NN	1.00	\$280.00 X
200	GEARBOX LH BRACKET	✓ NN	1.00	\$280.00 X
201	GEARBOX RH MOUNTING	✓ BT	1.00	\$620.00
202	GEARBOX LH MOUNTING	✓ BT	1.00	\$620.00
203	GEARBOX MOUNTING RH BRACKET	✓ BT	1.00	\$170.00
204	GEARBOX MOUNTING LH BRACKET	✓ BT	1.00	\$170.00
205	GEARBOX SCREWS AND NUTS @ \$10.00	✓ NEC	12.00	\$120.00
206	BODY RH UNDER COVER	✓	1.00	\$280.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel: 6453 2121 Fax: 6459 9795
GST Registration No: 199906067G

207	BODY LH UNDER COVER	1.00	\$280.00	
208	BODY CENTRE UNDER COVER	1.00	\$230.00	
			\$141,881.00	117191
			(\$7,094.05)	
			Discount: -5%	
			-10%: 105471.9	
			\$134,786.95	
209	FRONT RH WHEEL TYRE	1.00	\$380.00	150
210	FRONT LH WHEEL TYRE	1.00	\$380.00	150
211	REAR RH WHEEL TYRE	1.00	\$380.00	150
212	REAR LH WHEEL TYRE	1.00	\$380.00	150
213	FRONT NO. PLATE	1.00	\$40.00	✓
214	REAR NO. PLATE	1.00	\$40.00	✓
215	TO CHECK WHEEL ALIGNMENT	1.00	\$150.00	60
216	TO REFILL AIRCON GAS	1.00	\$120.00	✓
217	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	1.00	\$800.00	400
218	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$800.00	400
219	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	1.00	\$500.00	100
220	TO REMOVE AND REFIX PETROL TANK	1.00	\$150.00	60
221	TO REMOVE AND REFIX ENGINE	1.00	\$600.00	2300
222	TO REMOVE AND OVERHAUL GEARBOX	1.00	\$6,000.00	2300
223	TO REPAIR DAMAGES	1.00	\$4,800.00	2800
224	TO SPRAY PAINTING	1.00	\$3,200.00	2200
Subtotal w/o GST:			\$153,506.95	7420

132691.9

-20%: 106k

22 ~~18~~ Days.

4/5

After repair photos.

Good Q: up

23/12/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5137
Date : 28-06-2022
Accident Date : 19-09-2021

Vehicle Details

Make & Model : Porsche Boxster PDK 2.9L SMT
ABS AB 2WD 2DR HID
Chassis No : WP0ZZZ98ZEK160837
Registration No : SKL212L

Third Party Vehicle Details

Registration No : SLX7732G

S/N	Description	Qty	Amount (\$\$)
1	GEARBOX ✓ CRA	1.00	\$38,000.00 22000
			\$38,000.00
Discount: -5%			(\$1,900.00)
			\$36,100.00
-10%: 19800			\$36,100.00
Subtotal w/o GST:			\$36,100.00

Issued by Raymond Teo

This is a computer-generated document. No signature is required.