

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21013009/TNY3E2**Date:** 03/05/2023REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00001892101

**Claimant Vehicle  
No :** FBS8243P**Insured Vehicle  
No :** SMR5945S

Date of Loss: 16/12/2021

Nature of Claim: TP

Claim  
No: SNM21D207364/C02/THAMYLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBS8243P**

Make &amp; Model: HONDA XADV750, 745cc

Engine No: RH10E5011447

Reg. Date: 18/08/2021 (Man. Year: 2021)

Chassis No: JH2RH10A5MK010832

Colour: Black

Odometer: 800 km

Engine Capacity: 745 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17

Rear Tyre Size: 160/60 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,185.20	2,185.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	180.00	100.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,465.20</b>	<b>2,365.20</b>	<b>100.00</b>	<b>4.06</b>
<b>+ GST 8.00/8.00% (S\$)</b>	197.22	189.22	8.00	4.06
<b>Nett Amount (S\$)</b>	<b>2,662.42</b>	<b>2,554.42</b>	<b>108.00</b>	<b>4.06</b>

INSPECTION

Date of Assignment: 22/12/2021

Date Inspected: 22/12/2021 Inspected At:

Pan Euro Bikes Pte Ltd (HQ)  
21 Moonstone Lane #01-01 Poh Leng Building  
Singapore 328462

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 03 May 2023)	
<b>Parts:</b>	N/A	HONDA XADV750 745cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBS8243P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH MIRROR	Cut	220.00 FL	*220.00 FL
2	1		*RH HANDGUARD W MOUNTINGS	Cut	135.00 FL	*135.00 FL
3	1		*RH FRONT SIGNAL ASSY	Cut	198.00 FL	*198.00 FL
4	1		*SET RH VENT SHROUD, MATT	Cut	115.00 FL	*115.00 FL
5	1		*ACCESSORY LEVERS	Cut	120.00 FS	*120.00 FS
6	1		*FOG LAMPS, BAJA DESIGNS	Cut	565.00 FS	*565.00 FS
7	1		*CLAMPS, FOG LAMP	Cut	120.00 FS	*120.00 FS
8	1		*SET CRASHBARS, HEPKO BECKER	Dented	399.00 FS	*399.00 FS
9	1		*SET GIVI SIDE PANNIERS	Cut	380.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,252.00</b>	<b>2,252.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	66.80	66.80
<b>Total Parts (\$\$)</b>	<b>2,185.20</b>	<b>2,185.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	280.00	180.00
Gross Labour Cost (S\$)			280.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >