

PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg

Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INS (S) PTE LTD

DATE: 18.12.2021

ESTIMATED COST OF REPAIRS TO HONDA X-ADV 750

ENGINE NO : CHASSIS NO :
VEHICLE NO : FBS 8243P ACCIDENT ON : 16.12.2021
INSURED : LEE BOON WEE

1 PC	RH MIRROR	\$	220.00	cut ✓
1 PC	RH HANDGUARD w MOUNTINGS	\$	135.00	cut ✓
1 PC	RH FRONT SIGNAL ASSY	\$	198.00	cut ✓
1 SET	RH VENT SHROUD, MATT	\$	115.00	cut ✓
TOTAL		\$	668.00	
LESS 10%		\$	66.80	
SUB TOTAL		\$	601.20	
NETT ITEMS:				
1 PC	ACCESSORY LEVERS	\$	120.00	cut ✓
1 PC	FOG LAMPS, BAJA DESIGNS	\$	565.00	cut ✓
1 PC	CLAMPS, FOG LAMP	\$	120.00	cut ✓
1 SET	CRASHBARS, HEPKO BECKER	\$	399.00	dg ✓
1 SET	GIVI SIDE PANNIERS	\$	380.00	cut ✓
	LABOUR CHARGE	\$	280.00	180
TOTAL		\$	2,465.20	
ADD 7% GST		\$	172.56	
GRAND TOTAL		\$	2,637.76	

REMARKS:

Kindly send a surveyor down for a 3rd Party claim against your insured SMR 5945S.

Thank You.

Kin Wah: 9731-7133

Tanji 97495749 / 62565561

WP 22/12/21 @ 535 pm

p/p Resurvey new parts

2 days

Tanji e (LKK Auto Consultants)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: