

03/CT/21013009/11/13

PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg

Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INS (S) PTE LTD

DATE: 18.12.2021

ESTIMATED COST OF REPAIRS TO HONDA X-ADV 750

ENGINE NO : CHASSIS NO :
VEHICLE NO : FBS 8243P ACCIDENT ON : 16.12.2021
INSURED : LEE BOON WEE

1 PC RH MIRROR *ent*
1 PC RH HANDGUARD w MOUNTINGS *ent*
1 PC RH FRONT SIGNAL ASSY *ent*
1 SET RH VENT SHROUD, MATT *ent*

TOTAL

\$ -

LESS 10%

\$ -

SUB TOTAL

\$ -

NETT ITEMS:

1 PC ACCESSORY LEVERS *ent*
1 PC FOG LAMPS, BAJA DESIGNS *ent*
1 PC CLAMPS, FOG LAMP *ent*
1 SET CRASHBARS, HEPKO BECKER *del*
1 SET GIVI SIDE PANNIERS *ent*
LABOUR CHARGE

TOTAL

\$ -

ADD 7% GST

\$ -

GRAND TOTAL

\$ -

REMARKS:

Kindly send a surveyor down for a 3rd Party claim
against your insured SMR 5945S.

Thank You.

Kin Wah: 9731-7133

Tanfilin 97495749/62563561
inf 22/12/21 535pm
p/p Resurvey new parts
New & Old
2 days
tanfilin@khauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: