

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21013011/KPA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SLU8886E **Insured Vehicle No :** SLW8759D  
 Date of Loss: 18/12/2021 Nature of Claim: TP Claim No: 0459326071SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8886E**  
 Make & Model: HONDA STEPWAGON, 1.5 (A) Engine No: L15B5144594  
 Reg. Date: 06/11/2020 (Man. Year: 2019) Chassis No: RP31231579  
 Colour: Metallic Pearl White Odometer: 15277 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,900.08	3,644.20	1,255.88	25.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,440.00	390.00	21.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,730.08</b>	<b>5,084.20</b>	<b>1,645.88</b>	<b>24.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	471.11	355.89	115.22	24.46
<b>Nett Amount (S\$)</b>	<b>7,201.19</b>	<b>5,440.09</b>	<b>1,761.10</b>	<b>24.46</b>
<b>+ Car Rental (8.0 x S\$100.00/day) (S\$)</b>		800.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,242.09</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,240.00</b>		

INSPECTION

Date of Assignment: 22/12/2021  
 Date Inspected: 22/12/2021 Inspected At: Alan's United Auto Pte Ltd (HQ)  
 Singapore 575642  
 Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,950.00 FL	*1,950.00 FL
2	1		*TAIL GATE RUBBER	Serviceable	205.40 FL	*- FL
3	1		*REAR N/S BUMPER SIDE	Serviceable	685.20 FL	*- FL
4	1		*REAR N/S BUMPER SIDE REFLECTOR	Serviceable	117.40 FL	*- FL
5	1		*REAR OUTER DOOR	Bent	1,450.70 FL	*1,450.70 FL
6	1		*REAR OUTER DOOR CHROME	Serviceable	225.40 FL	*- FL
7	1		*REAR OUTER DOOR OUTER GARNISH	Dented	721.40 FL	*721.40 FL
8	1		*REAR END PANEL TOP GARNISH	Serviceable	155.40 FL	*- FL
9	1		*REAR N/S W/S GLASS MOULDING	Necessary	97.20 FL	*97.20 FL
10	1		*REAR O/S W/S GLASS MOULDING	Necessary	65.40 FL	*65.40 FL
11	1		*REAR N/S DOOR STEPWGN EMBLEM	Necessary	55.60 FL	*55.60 FL
12	1		*REAR N/S DOOR LOGO	Necessary	58.70 FL	*58.70 FL
13	1		*REAR O/S SPADA EMBLEM	Not Necessary	87.30 FL	*- FL
14	1		*REAR W/S GLASS SEALANT	Necessary	120.00 FS	*80.00 FS
15	1		*REAR NO.PLATE WITH BOX	Dented	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,075.10</b>	<b>4,524.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,175.02	879.80
<b>Total Parts (\$\$)</b>	<b>4,900.08</b>	<b>3,644.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	280.00	160.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	150.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	720.00
4	TO REMOVE,CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	600.00	500.00
<b>Gross Labour Cost (\$)</b>			<b>1,830.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >