


Kenneth

AIG / 21013011/KCP  
**ASSIGNMENT**

C

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Alan's  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 05 days Res.: Yes or No  
 Lum Sum: 1.8.1 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLU 888GE Yr Regn: 11.20  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Stepwgen <sup>41</sup> Wagon C.C. 1496  
 Colour: M. P. White A/C: Insured / Std / NI / NA  
 Sp. Reading: 829588 T/Radio: Insured / Std / NI / NA  
 Eng/No: 15277  
 C/No: RP3 1231579  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / SRim / STD A/Rim or  
 Tyre Size: F: 225/45ZR17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 7 mm R/Bal. 6 mm  
 L/Bal. 7 mm L/Bal. 6 mm  
 D.O.A. 18/12/21 D.O.I. 22/12/2021  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>28/12</u>	<u>5084.20 Carbur</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$) )  
 : Interview (\$) )  
 : Tech Invs (\$) )  
 : Weekend (\$) )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 \$ - RS. \$ \_\_\_\_\_  
 Extras \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06505

Vehicle Insured : SLW8759D  
Accident Date : 18-Dec-2021

Date : 20-Dec-2021

Our Ref : 021188 (AIG) / CHAN

PAGE : 1

TAN KIM LIAN  
BLK 603 YISHUN STREET 61  
#07-345  
Singapore 760603

*Not Authorized*  
*Resurvey B6 painting*  
*5 days*

ESTIMATED COST OF REPAIR FOR HONDA STEPWAGON SPADA SLU8886E

1 pc	Tail gate	1950	As	1,950.00	✓
1 pc	Tail gate rubber		sn	205.40	X
1 pc	Rear n/s bumper side		sn	685.20	X
1 pc	Rear n/s bumper side reflector		As	117.40	X
1 pc	Rear outer door	1450.70	As	1,450.70	✓
1 pc	Rear outer door chrome		sn	225.40	X
1 pc	Rear outer door outer garnish		net	721.40	✓
1 pc	Rear end panel top garnish		sn	155.40	X
1 pc	Rear n/s w/s glass moulding		sn	97.20	X
1 pc	Rear o/s w/s glass moulding		sn	65.40	✓
1 pc	Rear n/s door "STEPWGN" emblem		net	55.60	✓
1 pc	Rear n/s door logo		net	58.70	✓
1 pc	Rear o/s "SPADA" emblem		sn	87.30	X

5,875.10

Less 20% : 1,175.02

4,700.08 *Paint*  
sn 120.00  
net sn 80.00 *45sn*

1 pc Rear w/s glass sealant  
1 pc Rear no.plate with box

To remove & refix rear windscreen glass and conduct water leak test.

280.00 *1601*

To remove roof lining, front and rear seats, trim board and carpet

150.00 *601*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

**GST Reg. No.: 201113667N**

Vehicle Insured : SLW8759D

Page : 2

To putty and spray replaced parts

800.00 *72d*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

600.00 *50d*

Total : S\$ 6,730.08

Singapore Dollars Six Thousand Seven Hundred  
and Thirty and Cents Eight Only