

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLW8759D
Accident Date : 18-Dec-2021

No. : 06505
Date : 20-Dec-2021

Our Ref : 021188 (AIG) / CHAN

PAGE : 1

TAN KIM LIAN
BLK 603 YISHUN STREET 61
#07-345
Singapore 760603

Not Notified
Resurvey B4 pain
5 days

ESTIMATED COST OF REPAIR FOR HONDA STEPWAGON SPADA SLU8886E

1 pc Tail gate	Pr 1,950.00	✓
1 pc Tail gate rubber	Pr 205.40	X
1 pc Rear n/s bumper side	Sn 685.20	X
1 pc Rear n/s bumper side reflector	Pr 117.40	X
1 pc Rear outer door	Pr 1,450.70	✓
1 pc Rear outer door chrome	Pr 225.40	X
1 pc Rear outer door outer garnish	Pr 721.40	✓
1 pc Rear end panel top garnish	155.40	✓
1 pc Rear n/s w/s glass moulding	Pr 97.20	✓
1 pc Rear o/s w/s glass moulding	Pr 65.40	✓
1 pc Rear n/s door "STEPWGN" emblem	Pr 55.60	✓
1 pc Rear n/s door logo	Pr 58.70	✓
1 pc Rear o/s "SPADA" emblem	Pr 87.30	X

5,875.10
Less 20% : 1,175.02

1 pc Rear w/s glass sealant
1 pc Rear no.plate with box

4,700.08 *Pr*
Pr 120.00 *sn*
Pr 80.00 *sn 45%*

To remove & refix rear windscreen glass and conduct water leak test.

280.00 *160*

To remove roof lining, front and rear seats, trim board and carpet

150.00 *60*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLW8759D

Page : 2

To putty and spray replaced parts

800.00 *72d*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *50d*

Total :

S\$ 6,730.08
=====

Singapore Dollars Six Thousand Seven Hundred
and Thirty and Cents Eight Only